

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21003869/UBS3Q2
Date: 25/06/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	FBM5087A	Insured Vehicle No :	SLU5300Z
Date of Loss:	23/03/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001254

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM5087A		
Make & Model:	YAMAHA SNIPER T150, 150cc	Engine No:	G3E6E0318556
Reg. Date:	28/11/2017 (Man. Year: 2017)	Chassis No:	MH3UG0740H0066661
Colour:	Yellow	Odometer:	14738 km
Engine Capacity:	150 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	70-90-17	Rear Tyre Size:	120-70-17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,710.00	1,834.70	1,875.30	50.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	485.00	215.00	30.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,410.00	2,319.70	2,090.30	47.40
Approved Total (Overridden) (S\$)		1,850.00		

(S\$)	4,410.00	1,850.00	2,560.00	58.05
+ GST 7.00/7.00% (S\$)	308.70	129.50	179.20	58.05
Nett Amount (S\$)	4,718.70	1,979.50	2,739.20	58.05
+ Loss of Use (8.0 x S\$30.00/day) (S\$)		240.00		
Nett Liability (S\$)		2,219.50		

INSPECTION

Date of Assignment: 25/03/2021

Date Inspected: 29/03/2021

Estimated Period of Repair: 4.0 days

Inspected At: Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Jun 2021)	
Parts:	N/A	YAMAHA SNIPER T150 150cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBM5087A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE MIRROR	Cut	100.00 FL	*90.00 FL
2	1		*CLUTCH LEVER	Cut	65.00 FL	*65.00 FL
3	1		*HANDLE BALANCER	Cut	35.00 FL	*35.00 FL
4	1		*HANDLE BAR	Bent	150.00 FL	*130.00 FL
5	1		*N/S FRONT FOOT REST	Bent	65.00 FL	*48.00 FL
6	1		*FRONT FOOT REST BRACKET	Bent	150.00 FL	*115.00 FL
7	1		*O/S REAR FOOT REST BRACKET	Bent	150.00 FL	*115.00 FL
8	1		*LUGGAGE BOX	Cut	540.00 FS	*250.00 FS
9	1		*LUGGAGE BOX BRACKET	Bent	120.00 FL	*120.00 FL
10	2		*BOTH REAR TAIL SIDE COVER	Cracked	340.00 FL	*340.00 FL
11	1		*REAR MUDGUARD ASSY	Distorted	140.00 FL	*120.00 FL
12	1		*REAR NUMBERPLATE LAMP	Broken	50.00 FL	*50.00 FL
13	1		*REAR TAIL LAMP	Cracked	95.00 FL	*95.00 FL
14	1		*REAR NUMBER PLATE	Bent	18.00 FS	*10.00 FS
15	1		*NUMBER PLATE BRACKET	Bent	50.00 FL	*50.00 FL
16	1		*EXHAUST CAP	Cut	75.00 FL	*75.00 FL
17	1		*REAR WHEEL RIM	Repair	450.00 FL	*- FL
18	1		*REAR DISC ROTOR	Not Necessary	75.00 FL	*- FL
19	1		*SET YAMAHA SNIPER STICKER	Necessary	45.00 FL	*45.00 FL
20	1		*GEAR LEVER ASSY	Bent	120.00 FL	*90.00 FL
21	1		*N/S GEAR COVER	Repair	75.00 FL	*- FL
22	1		*REAR TYRE	Serviceable	140.00 FS	*- FS
23	1		*SET CAMERA ASSY	Shorted	150.00 FS	*150.00 FS
24	1		*REAR TAIL LAMP ASSY	Repeated	180.00 FL	*- FL
25	1		*FRONT FORK ASSY	Not Necessary	200.00 FL	*- FL
26	1		*FOOT REST ROD	Repeated	150.00 FL	*- FL
27	1		*CHASSIS ROD	Repair	300.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					4,028.00	1,993.00
- List Item Discount on L Items 10.00/10.00% (S\$)					318.00	158.30
Total Parts (S\$)					3,710.00	1,834.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING CHARGES	New	70.00	35.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	50.00	0.00
3	LABOUR CHARGES	New	350.00	300.00
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	200.00	150.00
5	TO TRANSFER OF TYRE ,RIM AND ON WHEEL BALANCING	New	30.00	0.00
Gross Labour Cost (S\$)			700.00	485.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >