



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 6756E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	688.00	688.00
1	REAR BUMPER ENFORCEMENT	CRACKED	313.00	313.00
2	REAR BUMPER RETAINER	NECESSARY	56.00	56.00
10	REAR BUMPER CLIPS	NECESSARY	35.00	35.00
1	REAR BUMPER LOWER W/REFLECTOR	DEFORMED	347.00	347.00
1	BOOT COVER	BENT	1,297.00	1,297.00
1	BOOT COVER WEATHER STRIPE	NECESSARY	92.00	92.00
1	BOOT COVER LOCK	SERVICEABLE	109.00	-
1	"KIA" LOGO	NECESSARY	32.00	32.00
1	"CERATO K3" EMBLEM	NECESSARY	32.00	32.00
2	TAILLAMP OUTER	SCRATCHED	708.00	708.00
2	TAILLAMP INNER	CRACKED	430.00	430.00
1	END PANEL	BENT	324.00	324.00
1	END PANEL GARNISH	CRACKED	66.00	66.00
1	BOOT RELEASE CABLE	SERVICEABLE	160.00	-
1	SPARE TYRE COVER (ADDITIONAL)	CRACKED	159.00	159.00
1	ENFORCEMENT BRACKET LH (ADDITIONAL)	BENT	128.40	128.40
2	BUMPER BRACKET (ADDITIONAL)	BENT	126.00	126.00
	LESS 20% DISCOUNT		-1,020.48	-966.68
			4,081.92	3,866.72
<u>SPECIAL NETT ITEMS</u>				
1	SET BUMPER REVERSE SENSOR (SN)	CUT	220.00	220.00
			220.00	220.00
<u>LABOUR</u>				
	TO REMOVE & REPLACE REAR BUMPER, BOOT COVER, TAILLAMPS AND TO PANEL BEAT, CUT & WELD END PANEL.		1,400.00	850.00
	TO PUTTY & SPRAY PAINT REAR BUMPER, BOOT COVER, FENDERS, END PANEL & OTHER AFFECTED AREA.		1,000.00	800.00
	TO CHECK & RECIFY WIRING AND REPLACE SENSOR.		140.00	60.00

Report Ref No. CS/EQI21003870/R1qf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE.		320.00	80.00
	FULL COMPUTERISE WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			2,980.00	1,790.00
GRAND TOTAL			7,281.92	5,876.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,700.00

Report Ref No. CS/EQI21003870/R1qf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.