

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21003873/R1GA3Q2
Date: 07/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100456311	
Claimant Vehicle No :	SJY1232R	Insured Vehicle No :	SGG9628K	
Date of Loss:	20/03/2021	Nature of Claim:	TP	Claim No: 6946424577SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY1232R		
Make & Model:	VOLKSWAGEN GOLF, 2.0 GTI (A)	Engine No:	CHH309392
Reg. Date:	05/08/2020 (Man. Year: 2019)	Chassis No:	WVWZZZAUZKW184966
Colour:	Red	Odometer:	4946 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,172.12	2,709.94	462.18	14.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	3,200.00	2,480.00	43.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,852.12	5,909.94	2,942.18	33.24
+ GST 7.00/7.00% (S\$)	619.65	413.70	205.95	33.24

Nett Amount (S\$)	9,471.77	6,323.64	3,148.13	33.24
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
Nett Liability (S\$)		6,723.64		

INSPECTION

Date of Assignment: 26/03/2021

Date Inspected: 26/03/2021

Estimated Period of Repair: 4.0 days

Inspected At:

Volkswagen Group Singapore Pte Ltd
 247 ALEXANDRA ROAD
 Singapore 159934

Adjuster: MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Deformed	1,404.78 FS	*1,404.78 FS
2	1		*GUIDE PIECE	Serviceable	21.92 FS	*- FS
3	1		*SENSOR BRACKET	Necessary	12.86 FS	*12.86 FS
4	2		*SENSOR BRACKET	Necessary	24.78 FS	*24.78 FS
5	1		*SENSOR BRACKET	Necessary	12.86 FS	*12.86 FS
6	1		*BONDING AGENT FOR PLASTIC	Necessary	62.81 FS	*62.81 FS
7	1		*2K-PLASTIC ADHESIVE	Necessary	78.91 FS	*78.91 FS
8	1		*FRONT SPOILER	Necessary	1,018.99 FS	*1,018.99 FS
9	1		*FRONT SPOILER -SPLITTER	Scratched	440.26 FS	*- FS
10	1		*ADHESIVE KIT FOR AERODYNA	Necessary	67.83 FS	*67.83 FS
11	1		*SENSOR BRACKET	Necessary	13.06 FS	*13.06 FS
12	1		*SENSOR BRACKET	Necessary	13.06 FS	*13.06 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)
3,172.12
2,709.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
2	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
3	LABOUR	New	2,520.00	840.00
4	SPRAY PAINTING	New	2,400.00	1,600.00
Gross Labour Cost (S\$)			5,680.00	3,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >