

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21003875/UPA3Q2
Date: 30/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900006634
Claimant Vehicle No :	SMU7315G	Insured Vehicle No :	SKG91U
Date of Loss:	24/03/2021	Nature of Claim:	TP
		Claim No:	4046332544SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU7315G		
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Engine No:	L13B1461457
Reg. Date:	26/08/2020 (Man. Year: 2019)	Chassis No:	GK31351386
Colour:	Grey	Odometer:	22401 km
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,856.80	5,583.76	6,273.04	52.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,300.00	2,590.00	1,710.00	39.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,156.80	8,173.76	7,983.04	49.41
Approved Total (Overridden) (S\$)		6,500.00		

(S\$)	16,156.80	6,500.00	9,656.80	59.77
+ GST 7.00/7.00% (S\$)	1,130.98	455.00	675.98	59.77
Nett Amount (S\$)	17,287.78	6,955.00	10,332.78	59.77
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		7,317.00		
Global Sum Settlement (S\$)		7,300.00		

INSPECTION

Date of Assignment: 25/03/2021

Date Inspected: 25/03/2021

Inspected At: Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR O/S	Badly Dented	948.20 F	*915.20 FL
2	1		*FRONT DOOR OUTER HANDLE O/S	Cut	266.50 F	*245.30 FL
3	1		*FRONT DOOR OUTER GLASS MOULDING O/S	Necessary	105.30 F	*102.20 FL
4	1		*SET FRONT DOOR FRAME BLACK STICKER O/S	Necessary	80.00 F	*80.00 FL
5	1		*FRONT DOOR INNER LOCK O/S	Shorted	322.20 F	*315.50 FL
6	1		*FRONT DOOR INNER RUBBER O/S	Necessary	168.50 F	*166.20 FL
7	1		*FRONT DOOR INNER TRIM BOARD O/S	Deformed / Cracked	540.20 F	*485.50 FL
8	1		*SET FRONT DOOR INNER TRIM BOARD CLIPS O/S	Necessary	40.00 F	*40.00 FL
9	1		*FRONT DOOR GLASS REGULATOR & MOTOR O/S	Bent / Shorted	395.00 F	*388.20 FL
10	2		*FRONT DOOR HINGES O/S	Not Necessary	201.00 F	*- FL
11	1		*FRONT DOOR CHECKER O/S	Not Necessary	122.00 F	*- FL
12	1		*FRONT DOOR KEY CYCLINDER O/S	Damaged	162.00 F	*162.00 FL
13	1		*CENTRE PILLAR OUTER O/S	Dented / Bent	845.20 F	*645.90 FL
14	1		*REAR DOOR O/S	Badly Dented	921.00 F	*905.20 FL
15	1		*REAR DOOR OUTER HANDLE O/S	Not Necessary	266.50 F	*- FL
16	1		*REAR DOOR OUTER GLASS MOULDING O/S	Necessary	105.30 F	*102.20 FL
17	1		*SET REAR DOOR FRAME BLACK STICKER O/S	Necessary	80.00 F	*80.00 FL
18	1		*REAR DOOR INNER LOCK O/S	Shorted / Damaged	322.20 F	*315.50 FL
19	1		*REAR DOOR INNER RUBBER O/S	Necessary	168.20 F	*165.30 FL
20	1		*REAR DOOR INNER TRIM BOARD O/S	Deformed / Cracked	520.50 F	*466.50 FL
21	1		*SET REAR DOOR INNER TRIM BOARD CLIPS O/S	Necessary	40.00 F	*40.00 FL
22	2		*REAR DOOR HINGES O/S	Twisted	210.00 F	*210.00 FL
23	1		*REAR DOOR CHECKER O/S	Serviceable	122.00 F	*- FL
24	1		*REAR FENDER O/S	Repair	899.20 F	*- FL
25	1		*REAR FENDER UNDER SHIELD O/S	Not Necessary	102.30 F	*- FL
26	1		*REAR BUMPER	Repair	665.20 F	*- FL
27	1		*REAR BUMPER SIDE RETAINER O/S	Not Necessary	45.00 F	*- FL
28	1		*SET REAR BUMPER CLIPS	Necessary	39.00 F	*39.00 FL
29	1		*REAR SHOCK ABSORBER O/S	Not Necessary	219.30 F	*- FL
30	1		*REAR WHEEL HUB BEARING O/S	Damaged	485.00 F	*485.00 FL
31	1		*REAR AXLE BEAM ASSY	Serviceable	1,150.00 F	*- FL
32	1		*REAR SPORT RIM O/S	Cut / Bent	800.00 FS	*400.00 FS
33	1		*REAR TYRE O/S	Serviceable	200.00 FS	*- FS
34	1		*SET FRT & REAR DOOR VISOR O/S	Necessary	150.00 FS	*100.00 FS
35	1		*SET FRT & REAR DOOR OUTER PROTECTOR O/S	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR FENDER GLASS SEALANT O/S	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					11,856.80	6,854.70
- List Item Discount on L Items 0.00/20.00% (\$\$)					0.00	1,270.94
Total Parts (\$\$)					11,856.80	5,583.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REFIX REAR REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR FENDER GLASS O/S	New	120.00	0.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	150.00	80.00
5	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	New	380.00	150.00
6	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
7	TO TRANSFER BOTH O/S DOOR MECHANISM	New	150.00	120.00
8	TO SPRAY RUST PROOFING	New	120.00	80.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	900.00
10	TO PUTTY & SPRAY PAINTING	New	1,600.00	1,100.00
Gross Labour Cost (S\$)			4,300.00	2,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >