

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21003877/UPA3Q2
Date: 09/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800021615
Claimant Vehicle No :	SLT525E	Insured Vehicle No :	SKK9808P
Date of Loss:	24/03/2021	Nature of Claim:	TP
		Claim No:	6151685180SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT525E		
Make & Model:	AUDI A5, 2.0 SB TFSI S TRONIC (DESIGN) (A)	Engine No:	CVK073921
Reg. Date:	29/03/2019 (Man. Year: 2018)	Chassis No:	WAUZZZF52KA013301
Colour:	Red	Odometer:	35682 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	245/40Z R18	Rear Tyre Size:	245/40Z R18
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,517.00	13,322.25	12,194.75	47.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,960.00	2,540.00	1,420.00	35.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	29,477.00	15,862.25	13,614.75	46.19
+ GST 7.00/7.00% (S\$)	2,063.39	1,110.36	953.03	46.19

Nett Amount (S\$)	31,540.39	16,972.61	14,567.78	46.19
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		17,674.61		
Global Sum Settlement (S\$)		17,550.00		

INSPECTION

Date of Assignment: 25/03/2021

Date Inspected: 25/03/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Not Necessary	850.00 F	*- FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	182.00 F	*115.00 FL
3	1		*TAILGATE	Bent / Buckled	5,470.00 F	*3,818.00 FL
4	2		*TAILGATE REFLECTORS	Cracked	1,640.00 F	*820.00 FL
5	1		*TAILGATE REAR LOGO	Serviceable	108.00 F	*- FL
6	1		*TAILGATE A5 EMBLEM	Serviceable	105.00 F	*- FL
7	1		*TAILGATE INNER LOCK	Bent / Shorted	650.00 F	*248.00 FL
8	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	688.00 F	*415.00 FL
9	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
10	1		*TAILGATE WEATHERSTRIP	Twisted	288.00 F	*236.00 FL
11	1		*REAR BUMPER	Distorted	2,800.00 F	*2,504.00 FL
12	1		*REAR BUMPER LOWER CHROME MOULDING	Cracked	880.00 F	*650.00 FL
13	2		*REAR BUMPER REFLECTORS	Not Necessary	210.00 F	*- FL
14	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	230.00 F	*- FL
15	1		*SET REAR BUMPER CLIPS	Necessary	60.00 F	*60.00 FL
16	1		*REAR BUMPER REINFORCEMENT	Distorted	788.00 F	*788.00 FL
17	1		*REAR BUMPER INNER RETAINER	Distorted	285.00 F	*282.00 FL
18	4		*REAR BUMPER PDC SENSORS	Shorted (2 PCS ONLY)	1,064.00 F	*380.00 FL
19	1		*SET REAR BUMPER PDC SENSOR WIRE	Not Necessary	350.00 F	*- FL
20	1		*REAR BUMPER TOP RETAINER	No such part	299.00 F	*- FL
21	1		*REAR SPEAKER	Damaged / Cracked	950.00 F	*367.00 FL
22	1		*REAR END PANEL OUTER	Badly Dented	850.00 F	*360.00 FL
23	1		*REAR END PANEL INNER	Badly Dented	820.00 F	*632.00 FL
24	1		*REAR END PANEL TOP GARNISH	Twisted	278.00 F	*278.00 FL
25	2		*TAILLAMPS	Cracked	1,852.00 F	*1,852.00 FL
26	2		*REAR FENDER INNER TRIMS	Not Necessary	1,772.00 F	*- FL
27	2		*REAR FENDER OUTER PROTECTORS	Not Necessary	798.00 F	*- FL
28	2		*REAR EXHAUST CHROMES	Repair	1,000.00 F	*- FL
29	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
30	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*30.00 FS
31	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
32	1		*REAR LICENCE PLATE	Bent	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,517.00	14,015.00
- List Item Discount on L Items 0.00/5.00% (\$\$)	0.00	692.75

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	25,517.00
						13,322.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REAR PDC SENSOR	New	80.00	50.00
3	TO RESET & REPROGRAMME SYSTEM	New	180.00	80.00
4	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
5	TO TRANSFER TAILGATE MECHANISM	New	100.00	80.00
6	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	150.00	100.00
7	TO DISMANTLE & REFIX REAR EXHAUST	New	150.00	0.00
8	TO SPRAY RUST PROOFING	New	100.00	80.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,500.00	900.00
10	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,100.00
Gross Labour Cost (S\$)			3,960.00	2,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >