

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBE8064M201202

Estimate

Customer

Name: MS First Capital Insurance Limited

Date: 24-03-21

Address Motor Claims Department

Vehicle No: GBE8064M

36 Robinson Road #16-01

Model/Make: Toyota Hiace

City House

Singapore 068877

Van Turbo 5 DR Manual

Item No.	Descriptions Of Parts		Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front	Bumper	\$ 896.80	
2		Bumper Clips 1 set	\$ 50.00	
3	Front Lh	Bumper Bracket	\$ 380.40	
4		Bumper Fog Lamp Garnish Rh	\$ 186.00	
5		Head Lamp	\$ 930.70	
6		Head Lamp Clip 1 set	\$ 65.00	SN X
7		Corner Panel	\$ 426.50	
8		Side Mirror	\$ 1,165.00	
9		Step Panel Lower Rh	\$ 485.20	X
10		Step Panel Lower Clips 1 set Rh	\$ 30.00	SN X
11	Bonnet	"Corporate" Advertisement & Artwork	\$ 250.00	SN 220 s.v
		To check all wiring & electrical component for proper function	\$ 80.00	- 20
		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 600.00	- 400
		To putty & spray painting & including touch up paint on accident affected	\$ 600.00	- 400
		To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 60.00	- 30

Total Parts & Labour of estimate for damaged vehicle

\$ 6,205.60

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg

not Authorised
here
25/3/21
L/S = 2400
Ample After rep.
H days.

Wm. Asher

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P. 2501-10
252
1875.82
3024.82