

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG21003886/AEA3Q2**Date:** 06/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900245821
Claimant Vehicle No :	SKF7700E	Insured Vehicle No :	SMQ3968U
Date of Loss:	23/03/2021	Nature of Claim:	TP
		Claim No:	9096226241SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF7700E	Engine No:	MA103D02107
Make & Model:	PORSCHE 911, 3.8 Carrera 4S (A)	Chassis No:	WP0ZZZ99ZDS110697
Reg. Date:	15/10/2012 (Man. Year: 2012)	Odometer:	0 km
Colour:	Bronze		
Engine Capacity:	3800 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R20	Rear Tyre Size:	245/35 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,676.00	7,590.00	7,086.00	48.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,372.00	1,492.00	1,880.00	55.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,048.00	9,082.00	8,966.00	49.68
+ GST 7.00/7.00% (S\$)	1,263.36	635.74	627.62	49.68
Nett Amount (S\$)	19,311.36	9,717.74	9,593.62	49.68
+ Loss of Use (3.0 x S\$150.00/day) (S\$)		450.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,169.74		

INSPECTION

Date of Assignment:	01/04/2021	
Date Inspected:	01/04/2021	Inspected At: Premium Automobiles Pte Ltd - Alexandra (HQ) 281 Alexandra Pte Ltd, Level B2 Singapore 159938
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	4,500.00 FS	*4,500.00 FS
2	1		*TOW EYE COVER	Not Necessary	54.00 FS	*- FS
3	1		*RH RETAINING FRAME -BLACK	Cut	120.00 FS	*120.00 FS
4	1		*FRONT BUMPER TRIM -RH	Not Necessary	93.00 FS	*- FS
5	1		*RETAINING STRIP -RH	Not Necessary	66.00 FS	*- FS
6	1		*FRONT BUMPER DISC -RH	Damaged	111.00 FS	*111.00 FS
7	1		*FRONT BUMPER FIXING	Not Necessary	114.00 FS	*- FS
8	1		*FRONT LICENCE PLATE BRACKET	Cracked	93.00 FS	*93.00 FS
9	1		*FRONT BUMPER CENTER RETAINING FRAME	Not Necessary	372.00 FS	*- FS
10	1		*FRONT BUMPER SPOILER	Deformed	716.00 FS	*716.00 FS
11	1		*FRONT BUMPER SPOILER LIP	Deformed	364.00 FS	*364.00 FS
12	1		*FRONT PARKING AID SENSOR TRIM -RH	Not Necessary	45.00 FS	*- FS
13	1		*PARKING AID SENSOR	Not Necessary	424.00 FS	*- FS
14	1		*FRONT BUMPER SENSOR BRACKET -RH	Not Necessary	60.00 FS	*- FS
15	1		*HEADLIGHT WASHER RETAINING PLATE -LH	Not Necessary	84.00 FS	*- FS
16	1		*HEADLIGHT WASHER RETAINING PLATE -RH	Not Necessary	84.00 FS	*- FS
17	1		*FRONT REINFORCEMENT BEAM	Not Necessary	2,069.00 FS	*- FS
18	1		*FRONT BUMPER LOWER BRACKET	Not Necessary	633.00 FS	*- FS
19	1		*FRONT WHEELHOUSE PROTECTION -RH	Not Necessary	465.00 FS	*- FS
20	1		*ADDITIONAL HEADLIGHT -RH	Cut	1,299.00 FS	*1,299.00 FS
21	1		*TURN SIGNAL -RH	Not Necessary	213.00 FS	*- FS
22	1		*HEADLIGHT WASHER JET	Damaged	273.00 FS	*273.00 FS
23	1		*WASHER JET CLUTCH	Deformed	54.00 FS	*54.00 FS
24	1		*AIR DUCT -RH	Not Necessary	435.00 FS	*- FS
25	1		*AIR COND CONDENSER	Not Necessary	1,539.00 FS	*- FS
26	4		*O-RING	Not Necessary	36.00 FS	*- FS
27	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
28	1		*FRONT NO PLATE WITH HOLDER	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$) **14,676.00** **7,590.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS HORNS ,OUTSIDE TEMPERA SENSOR HEADLIGHT WASHER ASSY & FRONT PARKING AID	New	480.00	250.00
2	TO DISMANTLE AND RENEW FRONT BUMPER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,350.00	500.00
3	TO RESPRAY FRONT BUMPE	New	1,350.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			3,372.00	1,492.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >