

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21003889/EVF3E2

Date: 21/04/2021

REFERENCE

Insured/Claimant: YEO MIN SI, GRACE (YANG MINSI, GRACE)

Policy No: 1700009447

Date of Loss: 24/03/2021

Nature of Claim: OD

Claim No: 2628612068SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP1829T**

Make & Model: KIA NIRO HYBRID, 1.6 (A)

Engine No: G4LEHS205947

Reg. Date: 29/05/2017 (Man. Year: 2017)

Chassis No: KNACC81CVH5075666

Colour: Red

Odometer: 129052 km

Engine Capacity: 1580 cc

Market Value/New Car Price: S\$73,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Bridgestone 4 mm

Rear Left Side: Bridgestone 4 mm

Front Right Side: Bridgestone 4 mm

Rear Right Side: Bridgestone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,244.00	637.60	2,606.40	80.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,960.00	1,430.00	2,530.00	63.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,204.00	2,067.60	5,136.40	71.30
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	6,704.00	1,567.60	5,136.40	76.62
+ GST 7.00/7.00% (S\$)	469.28	109.73	359.55	76.62
Nett Amount (S\$)	7,173.28	1,677.33	5,495.95	76.62

INSPECTION

Date of Assignment: 25/03/2021

Date Inspected: 25/03/2021 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)

209 Pandan Gardens

Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*MOULDING ASSY-RR BUMPER SIDE, L	Cut	20.00 F	*20.00 FL
3	1		*BRACKET ASSY-RR BUMPER SIDE, LH	Not Necessary	25.00 F	*- FL
4	1		*GARNISH ASSY-QTR SIDE, LH	Cut	144.00 F	*144.00 FL
5	1		*COVER-RR BUMPER LWR	Cut	392.00 F	*392.00 FL
6	1		*WHEEL ASSY-ALUMINIUM	Not Necessary	629.00 F	*- FL
7	1		*HUB & BEARING ASSY-RR	Not Necessary	437.00 F	*- FL
8	1		*ARM ASSY-RR TRAILING ARM, LH	Not Necessary	117.00 F	*- FL
9	1		*ARM COMPLETE-RR LWR, LH	Not Necessary	379.00 F	*- FL
10	1		*ARM ASSY-RR ASSIST	Not Necessary	90.00 F	*- FL
11	1		*ARM & BUSH ASSY-SUSP UPR, LH	Not Necessary	108.00 F	*- FL
12	1		*CROSSMEMBER-RR	Not Necessary	637.00 F	*- FL
13	1		*CAP ASSY-WHEEL HUB (Supplementary)	Cut	216.00 F	*216.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,244.00	792.00
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	154.40
Total Parts (\$)	3,244.00	637.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON LOWER COVER BUMPER, BUMPER MOULDING, REPAIR LH REAR FENDER, REPAIR REAR UPPER BUMPER	New	1,600.00	400.00
2	REMOVE AND INSTALL PARKING ASSIST	New	60.00	60.00
3	PAINT WORK SPRAY LH REAR FENDER, REAR BUMPER AND AFFECTED PORTION	New	1,050.00	700.00
4	PERFORM RUST PREVENTION	New	80.00	0.00
5	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
8	RENEW REAR UNDERCARRIAGE DAMAGES	New	400.00	0.00
9	LABOUR RENEW LH REAR SPORT RIM INCLUDING BALANCING	New	30.00	0.00
10	SUPPLY LH REAR TIRE	New	350.00	0.00
11	TO CARRY OUT AFTER RADAR CALIBRATION AND SETTINGS AFTER REPAIR REAR PORTION	New	120.00	0.00
Gross Labour Cost (\$\$)			3,960.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >