

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21003893/R1GS3Q2
Date: 31/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900249287
Claimant Vehicle No :	SMS7433J	Insured Vehicle No :	SMQ5332R
Date of Loss:	24/03/2021	Nature of Claim:	TP
		Claim No:	4522294787SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS7433J	Engine No:	CZCC05181
Make & Model:	VOLKSWAGEN GOLF, 1.4 TSI (A)	Chassis No:	WVWZZZAUZKW183831
Reg. Date:	12/03/2020 (Man. Year: 2019)	Odometer:	12741 km
Colour:	Red		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,086.91	2,785.32	6,301.59	69.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,320.00	4,040.00	3,280.00	44.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,406.91	6,825.32	9,581.59	58.40
+ GST 7.00/7.00% (S\$)	1,148.48	477.77	670.71	58.40

Nett Amount (\$\$)	17,555.39	7,303.09	10,252.30	58.40
+ Loss of Use (7.0 x S\$50.00/day) (\$\$)		350.00		
Nett Liability (\$\$)		7,653.09		

INSPECTION

Date of Assignment: 26/03/2021

Date Inspected: 26/03/2021

Estimated Period of Repair: 5.0 days

Inspected At:

Volkswagen Group Singapore Pte Ltd
247 ALEXANDRA ROAD
Singapore 159934**Adjuster:** MOHD RASUL**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Deformed	1,247.94 FS	*1,247.94 FS
2	1		*SUPPORT PART LHS BUMPER INNER BRACKET	Serviceable	57.27 FS	*- FS
3	1		*SUPPORT PART RHS BUMPER INNER BRACKET	Serviceable	57.27 FS	*- FS
4	1		*GUIDE PIECE BUMPER SIDE BRACKET LH	Serviceable	21.92 FS	*- FS
5	1		*GUIDE PIECE BUMPER SIDE BRACKET RH	Serviceable	21.92 FS	*- FS
6	1		*FOAM INSERT	Serviceable	43.84 FS	*- FS
7	1		*IMPACT BEAM REINFORCEMENT	Bent	635.13 FS	*635.13 FS
8	1		*SENSOR BRACKET	Necessary	12.86 FS	*12.86 FS
9	2		*SENSOR BRACKET	Necessary	24.78 FS	*24.78 FS
10	1		*SENSOR BRACKET	Necessary	12.86 FS	*12.86 FS
11	2		*SENSOR PRIMED	Serviceable	329.24 FS	*- FS
12	2		*SEAL RING SATIN BLACK	Necessary	2.56 FS	*2.56 FS
13	1		*BONDING AGENT FOR PLASTIC	Necessary	62.81 FS	*62.81 FS
14	1		*2K-PLASTIC ADHESIVE	Necessary	78.91 FS	*78.91 FS
15	1		*RADIATOR GRILLE SATIN BLA	Cracked	448.77 FS	*448.77 FS
16	1		*VW SIGN BLACK/BRIGHT CHRO	Missing	91.91 FS	*91.91 FS
17	1		*COOLING AIR GRILLE SATIN B BUMPER CTR BRACKET	Serviceable	251.31 FS	*- FS
18	1		*LED HEADLIGHT H/LAMP RH	Serviceable	2,759.41 FS	*- FS
19	1		*LED HEADLIGHT H/LAMP LH	Serviceable	2,759.41 FS	*- FS
20	1		*GUIDE BUMPER CTR BRACKET	Cracked	41.56 FS	*41.56 FS
21	1		*SUPPORT FOR LOCK CARRIER	Cracked	45.23 FS	*45.23 FS
22	1		*FRT NUMBER PLATE	Bent	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	9,086.91	2,785.32
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK SHORT CIRCUIT /HARNESS REPAIR	New	280.00	280.00
2	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	3,360.00	1,680.00
4	SPRAY PAINT	New	3,200.00	1,600.00
Gross Labour Cost (S\$)			7,320.00	4,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >