

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003894/APA3Q2
Date: 07/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100486512
Claimant Vehicle No :	SLZ6505S	Insured Vehicle No :	SLH1577L
Date of Loss:	23/03/2021	Nature of Claim:	TP
		Claim No:	7486163445SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ6505S	Engine No:	2AZH579174
Make & Model:	TOYOTA PREVIA, 2.4 8-SEATER (A)	Chassis No:	JTEGD52M60A024194
Reg. Date:	07/10/2010 (Man. Year: 2010)	Odometer:	167146 km
Colour:	Silver		
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,401.62	3,136.15	7,265.47	69.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	840.00	3,340.00	79.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,581.62	3,976.15	10,605.47	72.73
Approved Total (Overridden) (S\$)		3,100.00		

Nett Amount (S\$)	14,581.62	3,100.00	11,481.62	78.74
		+ Car Rental (3.0 x S\$120.00/day) (S\$)	360.00	
		+ Doc/Search Fee (S\$)	36.45	
		Nett Liability (S\$)	3,496.45	
		Global Sum Settlement (S\$)	3,490.00	

INSPECTION

Date of Assignment: 25/03/2021

Date Inspected: 25/03/2021

Inspected At:

Ishare Auto Pte. Ltd. (HQ)
 8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT
 Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*CENTRE GRILLE	Not Necessary	435.00 FL	*- FL
2	1		*CENTRE GRILLE (CHROME)	Not Necessary	175.00 FL	*- FL
3	1		*CENTRE GRILLE LOGO	Not Necessary	75.00 FL	*- FL
4	1		*FRONT GRILLE TOP RUBBER	Not Necessary	57.00 FL	*- FL
5	1		*FRONT BUMPER	Deformed	973.10 FL	*870.00 FL
6	1		*FRONT BUMPER FOGLAMP LH	Cracked	295.00 FL	*295.00 FL
7	1		*FRONT BUMPER FOGLAMP HOUSING LH	Cracked	125.00 FL	*125.00 FL
8	1		*FRONT BRACE PANEL	Not Necessary	106.00 FL	*- FL
9	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	150.00 FL	*- FL
10	2		*FRONT BUMPER SIDE RETAINER	Cracked	180.00 FL	*90.00 FL
11	1		*FRONT BUMPER REINFORCEMENT	Bent	475.00 FL	*475.00 FL
12	1		*FRONT BUMPER SPONGE	Deformed	185.00 FL	*185.00 FL
13	1		*FRONT BUMPER UNDER COVER	Not Necessary	170.00 FL	*- FL
14	1		*HEADLAMP (HID) LH	Cracked	1,930.00 FL	*905.00 FL
15	1		*FRONT SUPPORT PANEL	Not Necessary	1,043.30 FL	*- FL
16	1		*FRONT SUPPORT PANEL COVER GARNISH	Not Necessary	250.00 FL	*- FL
17	1		*RESONATOR TANK	Deformed	294.30 FL	*294.30 FL
18	1		*FRONT FENDER LH	Repair	657.30 FL	*- FL
19	1		*FRONT FENDER EMBLEM VVT-I LH	Necessary	38.90 FL	*38.90 FL
20	1		*FRONT FENDER COWLING LH	Torn	290.00 FL	*290.00 FL
21	1		*FRONT ABS SENSOR	Not Necessary	397.80 FL	*- FL
22	1		*FRONT KNUCKLE ARM LH	Not Necessary	689.30 FL	*- FL
23	1		*FRONT KNUCKLE ARM BEARING LH	Not Necessary	570.00 FL	*- FL
24	1		*FRONT LOWER ARM LH	Not Necessary	687.50 FL	*- FL
25	1		*FRONT STABILIZER BAR LINKAGE LH	Not Necessary	189.30 FL	*- FL
26	1		*FRONT SHOCK ABSORBER LH	Not Necessary	458.30 FL	*- FL
27	1		*FRONT WHEEL HUP LH	Not Necessary	398.40 FL	*- FL
28	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
29	1		*SET ENGINE SIDE COVER GARNISH CLIP	Not Necessary	60.00 FS	*- FS
30	1		*SET ENGINE UNDER COVER GARNISH CLIP	Not Necessary	80.00 FS	*- FS
31	1		*SET FRONT GRILLE CLIP	Not Necessary	50.00 FS	*- FS
32	1		*SET FRONT FENDER COWLING CLIP LH	Necessary	80.00 FS	*30.00 FS
33	1		*FRONT WHEEL TYRE LH	Not Necessary	480.00 FS	*- FS
34	1		*FRONT WHEEL RIM LH	Cut	850.00 FS	*400.00 FS
35	1		*POWER STEERING OIL	Not Necessary	250.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
					Sub Total (\$)	13,225.50
					- List Item Discount on L Items 25.00/25.00% (\$)	2,823.88
					Total Parts (\$)	10,401.62

4,028.20

892.05

3,136.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING REMOAL AND REPLACING PARTS	New	1,000.00	300.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	400.00
3	TUFF COAT	New	250.00	30.00
4	WIRING CHECK	New	250.00	30.00
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	0.00
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	0.00
7	REFOCUS HEADLAMP BEAM	New	60.00	0.00
8	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	0.00
9	FOUR WHEEL ALIGNMENT	New	120.00	80.00
10	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
11	RESET ABS LIGHT	New	350.00	0.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS RESET MEMORIES TO SPECIFICATION	New	180.00	0.00
Gross Labour Cost (S\$)			4,180.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >