

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21003901/T1QF3N2**Date:** 25/08/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00075582003

Claimant Vehicle No : SLF5265X **Insured Vehicle No :** GBF2685E

Date of Loss: 05/03/2021 Nature of Claim: TP **Claim No:** SNM21D201305/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLF5265X**

Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A) Engine No: P520376359

Reg. Date: 30/08/2016 (Man. Year: 2016) Chassis No: JM6BM42A8G0346965

Colour: Grey Odometer: 143571 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,984.00	4,019.40	11,964.60	74.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,550.00	930.00	3,620.00	79.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,534.00	4,949.40	15,584.60	75.90
Approved Total (Overridden) (S\$)		3,950.00		
(S\$)	20,534.00	3,950.00	16,584.00	80.76
+ GST 7.00/7.00% (S\$)	1,437.38	276.50	1,160.88	80.76
Nett Amount (S\$)	21,971.38	4,226.50	17,744.88	80.76

INSPECTION

Date of Assignment: 12/04/2021

Date Inspected: 26/03/2021 Inspected At: RICO 60 AUTO SERVICES PTE LTD (HQ)
8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 25 Aug 2021)**Parts:** 143 MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLF5265X)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,083.00 FL	*866.80 FL
2	1		*FRONT BUMPER TOP PAD	Deformed	458.00 FL	*285.80 FL
3	1		*FRONT BUMPER TOP PAD BASE	Deformed	286.00 FL	*185.00 FL
4	1		*FRONT BUMPER TOWING COVER	Cut	45.60 FL	*45.60 FL
5	1		*FRONT BUMPER LOWER ABSORBER	Not Necessary	308.50 FL	*- FL
6	1		*FRONT BUMPER LOWER SUPPORT BEAN	Cracked	215.00 FL	*215.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	750.10 FL	*545.00 FL
8	1		*FRONT BUMPER REINFORCEMENT GARNISH	Cracked	285.60 FL	*119.00 FL
9	1		*FRONT BUMPER SIDE RETAINER	N/s Deformed/O/s Not Necessary	230.00 FL	*70.00 FL
10	1		*FRONT BUMPER LOWER COVER	Not Necessary	189.20 FL	*- FL
11	1		*FRONT GRILLE	Cracked	970.10 FL	*560.00 FL
12	1		*FRONT GRILLE CHROME MOULDING	N/s Cracked/O/s Not Necessary	552.80 FL	*198.00 FL
13	1		*FRONT FOG LAMP LH	Cracked	321.00 FL	*218.00 FL
14	1		*FRONT FOG LAMP GARNISH LH	Cracked	277.80 FL	*108.00 FL
15	1		*FRONT GRILLE EMBLEM	Necessary	104.90 FL	*104.90 FL
16	1		*FRONT GRILLE TOP GARNISH	Not Necessary	320.50 FL	*- FL
17	2		*FRONT GRILLE SUPPORT BRACKET PIN	Not Necessary	178.00 FL	*- FL
18	1		*BONNET	Repair	1,120.00 FL	*- FL
19	1		*BONNET SEAL	Not Necessary	31.90 FL	*- FL
20	1		*BONNET LOCK	Not Necessary	208.60 FL	*- FL
21	1		*HEADLAMP	N/s Cracked/O/s Not Necessary	6,578.00 FL	*1,075.00 FL
22	1		*FRONT FENDER INNER SHIELD	N/s Torn/O/s Not Necessary	230.60 FL	*115.30 FL
23	1		*FRONT SUPPORT TOP PANEL	Not Necessary	448.00 FL	*- FL
24	1		*FRONT SUPPORT PANEL	Not Necessary	886.90 FL	*- FL
25	1		*RADIATOR AIR GUIDE LH	Deformed	135.30 FL	*135.30 FL
26	1		*A/C CONDENSER	Not Necessary	976.30 FL	*- FL
27	1		*AIR INTAKE DUCT ASSY	Not Necessary	188.90 FL	*- FL
28	1		*HORN	N/s Cracked/O/s Not Necessary	192.60 FL	*96.30 FL
29	1		*WIPER WASHER TANK	Not Necessary	169.30 FL	*- FL
30	1		*RADIATOR	Not Necessary	1,527.50 FL	*- FL
31	2		*NUMBER PLATE	Not Necessary	100.00 FS	*- FS
32	1		*SET FRONT BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS
33	1		*SET BONNET INSULATOR CLIP	Not Necessary	65.00 FS	*- FS
34	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*20.00 FS
35	1		*SET FRONT FENDER INNER COWLING CLIP	Necessary	78.00 FS	*15.00 FS
36	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS
37	1		*RADIATOR COOLANT	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,838.00	5,008.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,854.00	988.60
Total Parts (\$\$)	15,984.00	4,019.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,600.00	500.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	400.00
3	DISMANTLE AND REPLACE A/C CONDENSER ASSY,REFILL,RECHARGE A/C REFRIGERANT GAS AND PERFORM PRESSURE TEST	New	150.00	0.00
4	REMOVE AND INSTALL RADIATOR ASSY,PERFORMED RADIATOR PRESSURE TEST	New	150.00	0.00
5	ADJUST AND FOCUS FRONT LIGHTING SYSTEM,PERFORM HEADLAMP ADJUSTMENT TO POSITION	New	550.00	30.00
6	REMOVE AND INSTALL ENGINE WIRE HARNESS,RESET ENGINE WARNING LIGHT SYSTEM WITH ON-BOARD DIAGNOSTIC COMPUTER	New	500.00	0.00
Gross Labour Cost (\$\$)			4,550.00	930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >