

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21003902/AVF3N2**Date:** 23/08/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00092902002
Claimant Vehicle No :	SLR6150Z	Insured Vehicle No :	XE4368C
Date of Loss:	23/03/2021	Nature of Claim:	TP
		Claim No:	SNM21D201669/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR6150Z	Engine No:	2ZR8141522
Make & Model:	TOYOTA C-HR HYBRID, 1.8 E G CVT (A)	Chassis No:	ZYX102053085
Reg. Date:	22/08/2017 (Man. Year: 2017)	Odometer:	80271 km
Colour:	Blue		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R18	Rear Tyre Size:	225/50R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,349.41	18,948.17	4,401.24	18.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,220.00	3,540.00	1,680.00	32.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,569.41	22,488.17	6,081.24	21.29
Approved Total (Overridden) (S\$)		18,000.00		
(S\$)	28,569.41	18,000.00	10,569.41	37.00
+ GST 7.00/7.00% (S\$)	1,999.86	1,260.00	739.86	37.00
Nett Amount (S\$)	30,569.27	19,260.00	11,309.27	37.00

INSPECTION

Date of Assignment:	25/03/2021	
Date Inspected:	26/03/2021	Inspected At:
Estimated Period of Repair:	10.0 days	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Aug 2021)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 E G CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR6150Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	2	*REAR BLIND SPOT SENSOR UNIT BRACKET L/R	Bent	104.60 FL	*104.60 FL
2	2	*REAR BLIND SPOT SENSOR UNIT L/R	Cracked	3,924.80 FL	*3,160.00 FL
3	1	*REAR BUMPER (LOWER)	Distorted	397.60 FL	*397.60 FL
4	1	*REAR BUMPER (TOP)	Distorted	690.00 FL	*690.00 FL
5	2	*REAR BUMPER CENTER BRACKET L/R	Not Necessary	103.40 FL	*- FL
6	1	*REAR BUMPER CENTER COVER	Deformed	171.45 FL	*171.45 FL
7	2	*REAR BUMPER END SEAL COVER L/R	Torn	164.50 FL	*164.50 FL
8	2	*REAR BUMPER REFLECTOR GARNISH L/R	Cut	374.00 FL	*374.00 FL
9	2	*REAR BUMPER REFLECTOR L/R	Cracked	118.00 FL	*118.00 FL
10	1	*REAR BUMPER REINFORCEMENT	Dented	352.70 FL	*352.70 FL
11	1	*REAR BUMPER REVERSE SENSOR (4 Pcs)	Damaged (2 Pcs only)	1,571.20 FL	*500.00 FL
12	4	*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	101.60 FL	*101.60 FL
13	1	*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Snapped	156.65 FL	*156.65 FL
14	2	*REAR BUMPER SIDE RETAINER L/R	Necessary	224.40 FL	*224.40 FL
15	1	*REAR BUMPER TOW HOOK COVER	Deformed	27.70 FL	*27.70 FL
16	1	*REAR COMPARTMENT SPONGE TRAY	Deformed	371.75 FL	*371.75 FL
17	1	*REAR END PANEL	Distorted	731.35 FL	*731.35 FL
18	1	*REAR END PANEL ANTENNA SENSOR	Cracked	106.00 FL	*106.00 FL
19	2	*REAR END PANEL BRACKET L/R	Dented	128.70 FL	*128.70 FL
20	1	*REAR END PANEL INNER TOP GARNISH	Cracked	347.00 FL	*347.00 FL
21	1	*REAR EXHAUST SILENCER ALUMINIUM HEAT SHIELD	Not Necessary	271.75 FL	*- FL
22	1	*REAR FENDER AIR VENT L/R	O/s Cracked	147.20 FL	*73.60 FL
23	2	*REAR FENDER ARCH GARNISH L/R	Cracked	350.30 FL	*350.30 FL
24	2	*REAR FENDER INNER TOP TRIM GARNISH L/R	Cut	258.20 FL	*258.20 FL
25	1	*REAR FENDER INNER TRIM GARNISH COVER L/R	O/s Cracked	201.60 FL	*100.80 FL
26	2	*REAR FENDER INNER TRIM GARNISH L/R	Cracked	999.00 FL	*999.00 FL
27	2	*REAR FLOOR SPONGE L/R	Deformed	419.00 FL	*419.00 FL
28	1	*REAR LH BUMPER LOWER COVER	Deformed	189.20 FL	*189.20 FL
29	2	*REAR NUMBER PLATE LAMP L/R	Not Necessary	100.80 FL	*- FL
30	1	*REAR RH BUMPER LOWER COVER	Deformed	122.90 FL	*122.90 FL
31	1	*REAR RH FENDER	Buckled	943.60 FL	*943.60 FL
32	1	*REAR RH TAILLAMP PANEL	Dented	103.40 FL	*103.40 FL
33	1	*REAR SPEAKER BOARD	Deformed	599.45 FL	*599.45 FL
34	1	*REAR TAILGATE	Distorted	1,112.45 FL	*1,112.45 FL
35	1	*REAR TAILGATE CHR EMBLEM	Necessary	55.60 FL	*55.60 FL
36	1	*REAR TAILGATE HYBRID SYNERGY DRIVE EMBLEM	Necessary	121.35 FL	*121.35 FL
37	1	*REAR TAILGATE LOGO EMBLEM	Necessary	72.20 FL	*72.20 FL
38	2	*REAR TAILGATE CORNER SEAL RUBBER L/R	Not Necessary	95.60 FL	*- FL
39	2	*REAR TAILGATE DAMPER L/R	Damaged	506.80 FL	*506.80 FL
40	2	*REAR TAILGATE GASKET SEAL L/R	Not Necessary	13.20 FL	*- FL
41	2	*REAR TAILGATE HINGES L/R	Not Necessary	150.60 FL	*- FL
42	2	*REAR TAILGATE INNER SIDE GARNISH L/R	Cut	230.60 FL	*230.60 FL
43	1	*REAR TAILGATE INNER TOP GARNISH	Cut	151.10 FL	*151.10 FL
44	1	*REAR TAILGATE INNER TRIM GARNISH	Cracked	324.15 FL	*324.15 FL
45	2	*REAR TAILGATE LOWER RUBBER STOPPER L/R	Not Necessary	64.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*REAR TAILGATE MECHANISM LOCK	Damaged	467.60 FL	*389.00 FL
47	1		*REAR TAILGATE MECHANISM LOCK COVER	Deformed	43.30 FL	*43.30 FL
48	1		*REAR TAILGATE MECHANISM LOCK STRIKER	Bent	40.40 FL	*40.40 FL
49	1		*REAR TAILGATE OPENER BUTTON SENSOR	Not Necessary	179.10 FL	*- FL
50	1		*REAR TAILGATE OUTER GARNISH	Cracked	925.60 FL	*882.00 FL
51	5		*REAR TAILGATE OUTER GARNISH FASTER CLIPS	Necessary	55.50 FL	*20.00 FL
52	2		*REAR TAILGATE REFLECTOR L/R	Cracked	1,013.40 FL	*1,013.40 FL
53	1		*REAR TAILGATE THIRD BRAKE LAMP	Cut	353.00 FL	*353.00 FL
54	1		*REAR TAILGATE WEATHER STRIP	Cut	371.00 FL	*371.00 FL
55	1		*REAR TAILGATE WINDSCREEN GLASS	Shattered	1,340.00 FL	*1,340.00 FL
56	1		*REAR TAILGATE WINDSCREEN LOWER MOULDING	Necessary	68.20 FL	*68.20 FL
57	2		*REAR TAILGATE WINDSCREEN SIDE MOULDING L/R	Necessary	89.60 FL	*89.60 FL
58	1		*REAR TAILGATE WIPER ARM	Distorted	93.40 FL	*93.40 FL
59	1		*REAR TAILGATE WIPER ARM COVER	Missing	16.70 FL	*16.70 FL
60	1		*REAR TAILGATE WIPER BLADE	Cut	46.50 FL	*46.50 FL
61	1		*REAR TAILGATE WIPER MOTOR	Damaged	827.40 FL	*827.40 FL
62	2		*REAR TAILLAMP L/R	Cracked	1,536.20 FL	*1,536.20 FL
63	2		*REAR TAILLAMP LOWER BRACKET L/R	Damaged	113.70 FL	*113.70 FL
64	2		*REAR TAILLAMP SIDE COVER L/R	Cut	145.40 FL	*145.40 FL
65	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
66	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	40.00 FS	*20.00 FS
67	2		*SET REAR FENDER ARCH GARNISH CLIPS L/R	Necessary	80.00 FS	*40.00 FS
68	2		*SET REAR FENDER INNER TOP TRIM GARNISH CLIPS L/R	Necessary	60.00 FS	*60.00 FS
69	2		*SET REAR FENDER INNER TRIM GARNISH CLIPS L/R	Necessary	100.00 FS	*60.00 FS
70	1		*REAR NUMBER PLATE	Bent	25.00 FS	*25.00 FS
71	1		*REAR NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
72	1		*REAR SPARE TYRE PANEL INSULATOR MAT	Necessary	250.00 FS	*200.00 FS
73	1		*SET REAR TAILGATE INNER TRIM GARNISH CLIPS	Necessary	80.00 FS	*30.00 FS
74	1		*REAR TAILGATE REVERSE CAMERA	Damaged	500.00 FS	*380.00 FS
75	1		*SET REAR TAILGATE SPOILER CLIPS	Necessary	50.00 FS	*30.00 FS
76	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	60.00 FS	*60.00 FS
77	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	60.00 FS	*20.00 FS
78	1		*REAR TAILGATE SPOILER	Cracked	2,741.32 FS	*1,200.00 FS
79	1		*REAR TAILGATE WINDSCREEN SEALANT	Repeated	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	29,723.77	24,535.90
- List Item Discount on L Items 25.00/25.00% (S\$)	6,374.36	5,587.73
Total Parts (S\$)	23,349.41	18,948.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESET SYSTEM AFTER REPAIR WORKS	New	280.00	0.00
2	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
3	TO REMOVE,REINSTALL TAILGATE WINDSCREEN	New	150.00	120.00
4	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,INNER GARNISH,TRIM LINER CARPET (TO FR)	New	150.00	80.00
5	TO SEND VEHICLE FOR CLEANING,SHAMPOO,UPHOLSTERY AND CUSHION SEAT	New	180.00	80.00
6	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT	New	2,000.00	1,500.00
7	TO REMOVE AND REINSTALL EXHAUST PIPE	New	100.00	0.00
8	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,100.00	1,500.00
9	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	100.00	100.00
10	TO REMOVE,REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION	New	80.00	80.00
Gross Labour Cost (S\$)			5,220.00	3,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >