

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21003904/T1VF3E2

Date: 18/01/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00022282000		
Claimant Vehicle No :	SJC1819P	Insured Vehicle No :	GY2822S		
Date of Loss:	24/03/2021	Nature of Claim:	TP	Claim No:	SNM21D201686/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJC1819P	Engine No:	L13A4011769
Make & Model:	HONDA FIT, 1.3 (A)	Chassis No:	GE61010013
Reg. Date:	01/02/2008 (Man. Year: 2007)	Odometer:	224356 km
Colour:	Red		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R14	Rear Tyre Size:	185/65 R14
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,590.24	3,576.56	9,013.68	71.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	1,750.00	2,050.00	53.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	16,390.24	5,326.56	11,063.68	67.50
Approved Total (Overridden) (\$\$)		4,250.00		
Nett Amount (\$\$)	16,390.24	4,250.00	12,140.24	74.07

INSPECTION

Date of Assignment:	29/03/2021		
Date Inspected:	26/03/2021	Inspected At:	15 Kaki Bukit Road 4# 01-53 Repairer: Zoom Autowerks Pte Ltd
Estimated Period of Repair:	6.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jan 2022)
Parts:	144	HONDA FIT 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJC1819P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,408.40 FL	*771.50 FL
2	1		*TAILGATE INNER TRIM BOARD	Cracked	496.10 FL	*192.30 FL
3	1		*TAILGATE WEATHERSTRIP	Cut	299.80 FL	*145.80 FL
4	1		*TAILGATE INNER LOCK	Bent	286.40 FL	*189.20 FL
5	2		*TAILGATE DAMPER	Not Necessary	462.20 FL	*- FL
6	1		*TAILGATE WINDSCREEN GLASS	Broken	1,290.30 FL	*800.00 FL
7	1		*TAILGATE WINDSCREEN MOULDING	Necessary	152.80 FL	*98.20 FL
8	1		*TAILGATE EMBLEM H	Necessary	95.00 FL	*48.00 FL
9	1		*TAILGATE EMBLEM FIT	Necessary	75.00 FL	*35.00 FL
10	1		*TAILGATE OUTER GARNISH	Cracked	256.60 FL	*199.50 FL
11	1		*TAILGATE WIPER ARM	Cut	215.40 FL	*84.60 FL
12	1		*TAILGATE WIPER MOTOR	Not Necessary	386.50 FL	*- FL
13	1		*TAILGATE WIPER BLADE	Cut	42.80 FL	*42.80 FL
14	2		*TAILLAMP ASSY	Cracked	846.80 FL	*576.00 FL
15	2		*TAILLAMP PANEL	Repair	451.60 FL	*- FL
16	1		*REAR BUMPER	Deformed	856.40 FL	*490.00 FL
17	1		*REAR BUMPER SIDE RETAINER	O/S NotNecessary/N/S Deformed	240.40 FL	*33.00 FL
18	2		*REAR BUMPER BRACKET	Not Necessary	136.40 FL	*- FL
19	1		*REAR BUMPER TOW COVER	Deformed	48.00 FL	*48.00 FL
20	1		*REAR SPARE TYRE TOP BOARD	Not Necessary	275.40 FL	*- FL
21	1		*REAR SPARE TYRE TOP FOAM	Not Necessary	295.20 FL	*- FL
22	1		*REAR SPARE TYRE PANEL	Not Necessary	937.10 FL	*- FL
23	2		*REAR FENDER INNER TRIM GARNISH	Not Necessary	926.40 FL	*- FL
24	1		*REAR FENDER N/S	Not Necessary	1,614.00 FL	*- FL
25	1		*REAR END PANEL	Bent	765.50 FL	*288.80 FL
26	1		*REAR END PANEL TOP GARNISH	Deformed	428.30 FL	*65.50 FL
27	1		*REAR EXHAUST BOX	Not Necessary	980.00 FL	*- FL
28	2		*REAR EXHAUST MOUNTING	Not Necessary	204.00 FL	*- FL
29	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
30	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
31	1		*REAR TAILGATE GLASS SEALANT	Necessary	80.00 FS	*50.00 FS
32	1		*REAR EXHAUST CHROME MUFFLER	Not Necessary	280.00 FS	*- FS
33	1		*REAR NUMBER PLATE W/GARNISH	Not Necessary	68.00 FS	*- FS
34	1		*REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS
35	1		*REAR EXHAUST MUFFLER	Not Necessary	180.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	15,520.80	4,398.20
- List Item Discount on L Items 20.00/20.00% (S\$)	2,930.56	821.64
Total Parts (S\$)	12,590.24	3,576.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS	New	1,400.00	700.00
2	TO PUTTY, SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	700.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	30.00
4	TO REMOVE & INSTALL REAR TAILGATE COMPONENTS TRIM & GARNISH	New	150.00	60.00
5	TO REMOVE & INSTALL REAR SPARE TYRE COMPONENTS, TRIM & GARNISH	New	150.00	60.00
6	TO RE-POSITION, DRILL & INSTALL REVERSE SENSOR	New	150.00	30.00
7	TO CONDUCT WATER LEAKAGE TEST	New	150.00	20.00
8	TO RUST PROOF AFFECTED AREAS	New	200.00	30.00
9	TO REMOVE & INSTALL REAR TAILGATE GLASS	New	150.00	120.00
Gross Labour Cost (\$\$)			3,800.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >