



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

✉ zoomautowerks@gmail.com

Car Number: SJC1819P

Model : Honda Fit

Damaged Area: (Rear Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Parts / Material :

1	Tailgate	771.50 \$	1,408.40 <i>bt</i> ✓
2	Tailgate inner trim board	192.30 \$	496.10 <i>cn</i> ✓
3	Tailgate weatherstrip	145.80 \$	299.80 <i>ant</i> ✓
4	Tailgate inner lock	189.20 \$	286.40 <i>bt</i> ✓
5	Tailgate damper @ SGD 231.10	\$	462.20 <i>Xm</i> ✓
6	Tailgate windscreen glass	800 - \$	1,290.30 <i>brd</i> ✓
7	Tailgate windscreen moulding	98.20 \$	152.80 <i>ner</i> ✓
8	Tailgate emblem "H"	48 \$	95.00 <i>ny</i> ✓
9	Tailgate emblem "FIT"	35 \$	75.00 <i>ny</i> ✓
10	Tailgate outer garnish	199.50 \$	256.60 <i>cn</i> ✓
11	Tailgate wiper arm	84.60 \$	215.40 <i>ant</i> ✓
12	Tailgate wiper motor	\$	386.50 <i>Xm</i> ✓
13	Tailgate wiper blade	\$	42.80 <i>ant</i> ✓
14	Taillamp assy @ SGD 423.40 <i>288</i>	576 \$	846.80 <i>cn</i> ✓
15	Taillamp panel @ SGD 225.80	\$	451.60 <i>lp</i> ✓
16	Rear bumper	490 \$	856.40 <i>de</i> ✓
17	Rear bumper side retainer @ SGD 120.20 <i>37</i>	33 <i>RHK</i> \$	240.40 <i>lde</i> ✓
18	Rear bumper bracket @ SGD 68.20	\$	136.40 <i>Xm</i> ✓
19	Rear bumper tow cover	\$	48.00 <i>de</i> ✓
20	Rear spare tyre top board	\$	275.40 <i>Xm</i> ✓
21	Rear spare tyre top foam	\$	295.20 <i>Xm</i> ✓
22	Rear spare tyre panel	\$	937.10 <i>Xm</i> ✓
23	Rear fender inner trim garnish @ SGD 463.20	\$	926.40 <i>Xm</i> ✓
24	Rear fender n/s	\$	1,614.00 <i>Xm</i> ✓
25	Rear end panel	288.80 \$	765.50 <i>ht</i> ✓
26	Rear end panel top garnish	65.50 \$	428.30 <i>de</i> ✓
27	Rear exhaust box	\$	980.00 <i>Xm</i> ✓
28	Rear exhaust muffler	\$	180.00 <i>Xm</i> ✓
29	Rear exhaust mounting @ \$68.00	\$	204.00 <i>Xm</i> ✓

Parts : \$ 14,652.80

Less Parts 20% : \$ 2,930.56

Total Parts : \$ 11,722.24

4108.20

20% - 3286.56

Special Net Items :

Rear End Panel Sealant

Rear Fender Sealant

Rear Tailgate Glass Sealant

Rear Exhaust Chrome Muffler

Rear Number Plate W/Garnish

Reverse Sensor

\$ 80.00 40ml ✓

\$ 80.00 X 17 ✓

\$ 80.00 50ml ✓

\$ 280.00 X 17 ✓

\$ 68.00 X 17 ✓

\$ 280.00 200ml ✓

Total S/N Parts : \$ 868.00 290**Labour :**

To Remove, Repair & Renew Rear Affected Accident Areas

\$ 1,400.00 700

To Putty, Spray Paint on Affected Accident Areas

\$ 1,400.00 700

To Check & Re-Connect all electrical wiring

\$ 50.00 30

To Remove & Install Rear Tailgate Components Trim & Garnish

\$ 150.00 60

To Remove & Install Rear Spare Tyre Components, Trim & Garnish

\$ 150.00 60

To Remove & Install Rear Tailgate Glass

\$ 150.00 120

To Re-Position, Drill & Install Reverse Sensor

\$ 150.00 30

To Conduct Water Leakage Test

\$ 150.00 20

To Rust Proof Affected Areas

\$ 200.00 30

Total Labour : \$ 3,800.00

1750

TOTAL PARTS : \$ 11,722.24**TOTAL SPECIAL NET IT \$ 868.00****TOTAL LABOUR : \$ 3,800.00****TOTAL REPAIR COST : \$ 16,390.24**

3286.56

290

1750

5326.56

1544250

06 days #

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM:

RECOMMENDED NUMBER OF DAYS:

SURVEY BY / SURVEYOR FIRM:

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT:

FINALISED AMOUNT:

Tajiri 97495749

WP' 26/3/21 @ 11:00am

L/S Rosny after repair

Tajiri@khanda.com

06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: