

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21003907/R1TF3E2**Date:** 31/05/2021**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00043022001

Claimant Vehicle No : GBF3553X **Insured Vehicle No :** GBJ5993A

Date of Loss: 24/03/2021 Nature of Claim: TP Claim No: SNM21D201694C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF3553X**

Make & Model: NISSAN NV200, 1.5 (A) Engine No: YD25404965A

Reg. Date: 15/09/2016 (Man. Year: 2016) Chassis No: JN1MC2E26Z0007062

Colour: Grey Odometer: 115766 km

Engine Capacity: 2488 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,972.30	12,554.90	4,417.40	26.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,770.00	4,500.00	1,270.00	22.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,742.30	17,054.90	5,687.40	25.01
Approved Total (Overridden) (S\$)		13,650.00		
(S\$)	22,742.30	13,650.00	9,092.30	39.98
+ GST 7.00/7.00% (S\$)	1,591.96	955.50	636.46	39.98
Nett Amount (S\$)	24,334.26	14,605.50	9,728.76	39.98

INSPECTION

Date of Assignment: 25/03/2021

Date Inspected: 26/03/2021 Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ)
38 Toh Guan Road East, #01-57, Enterprise Hub
Singapore 608581

Estimated Period of Repair: 14.0 days

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 May 2021)	
Parts:	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF3553X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Bent	1,307.00 FL	*1,307.00 FL
2	2		*HEADLAMP LH / RH	Cracked	846.00 FL	*846.00 FL
3	1		*CENTER GRILLE ASSY	Cracked	455.00 FL	*455.00 FL
4	1		*CENTER GRILLE LOGO BADGE	Missing	70.00 FL	*70.00 FL
5	1		*FRONT BUMPER	Torn	542.00 FL	*542.00 FL
6	2		*FRONT BUMPER SIDE RETAINER LH / RH	Necessary	294.00 FL	*294.00 FL
7	2		*FOG LAMP LH / RH	Cracked	644.00 FL	*644.00 FL
8	2		*FOG LAMP COVER LH / RH	Cracked	236.00 FL	*236.00 FL
9	1		*FRONT TOP CORNER PANEL	Repair	478.00 FL	*- FL
10	1		*FRONT BUMPER TOWING COVER	Serviceable	31.00 FL	*- FL
11	1		*HEADLAMP PANEL CENTER	Bent	159.00 FL	*159.00 FL
12	2		*HEADLAMP PANEL LH / RH	Bent	630.00 FL	*630.00 FL
13	1		*FRONT BUMPER BAR	Bent	210.00 FL	*210.00 FL
14	2		*FRONT BUMPER BAR SIDE BRACKET LH / RH	Bent	230.00 FL	*230.00 FL
15	1		*BLOWER ASSY	Serviceable	781.00 FL	*- FL
16	1		*HEATING UNIT ASSY	Serviceable	2,182.00 FL	*- FL
17	1		*POWER STEERING OIL COOLER	Bent	294.00 FL	*294.00 FL
18	1		*RH INTERCOOLER	Bent	2,222.00 FL	*2,222.00 FL
19	1		*LH OIL COOLER	Bent	693.00 FL	*693.00 FL
20	1		*FRONT REINFORCEMENT	Bent	630.00 FL	*630.00 FL
21	2		*FRONT REINFORCEMENT SIDE BRACKET LH / RH	Bent	230.00 FL	*294.00 FL
22	1		*BOOT LID	Buckled	2,102.00 FL	*2,102.00 FL
23	1		*BOOT LID EMBLEM NV350/URBAN	Necessary	102.00 FL	*102.00 FL
24	1		*BOOTLID LOCK	Jammed	281.00 FL	*281.00 FL
25	1		*BOOTLID WEATHERSTRIP	Necessary	148.00 FL	*148.00 FL
26	1		*BOOTLID INNER TRIM BOARD	Cut	224.00 FL	*224.00 FL
27	1		*TAIL LAMP RH / LH	N/S Cracked / O/S Serviceable	440.00 FL	*220.00 FL
28	1		*REAR BUMPER	Deformed	691.00 FL	*691.00 FL
29	2		*REAR BUMPER SIDE BRACKET LH / RH	Necessary	38.00 FL	*38.00 FL
30	1		*REAR REINFORCEMENT	Bent	196.00 FL	*196.00 FL
31	1		*END PANEL	Bent	184.00 FL	*184.00 FL
32	1		*END PANEL TOP GARNISH	Bent	80.00 FL	*80.00 FL
33	1		*REAR FENDER LH	Repair	1,974.00 FL	*- FL
34	1		*FRONT DOOR LH (NPA)	Repair	0.00 FL	*- FL
35	1		*FRONT DOOR RH (NPA)	Repair	0.00 FL	*- FL
36	1		*FRONT BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
37	1		*FRONT CARPLATE	Bent	35.00 FS	*35.00 FS
38	1		*REAR BUMPER CLIPS	Necessary	35.00 FS	*35.00 FS
39	1		*REAR CARPLATE	Bent	35.00 FS	*35.00 FS
40	1		*REAR REVERSE SENSOR	Not Working	200.00 FS	*200.00 FS
41	1		*END PANEL SEALANT	Necessary	60.00 FS	*40.00 FS
42	1		*REAR WINDSCREEN	Broken	891.00 FS	*830.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
44	1		*GEARBOX FLUID	Necessary	80.00 FS	*60.00 FS
45	1		*POWER STEERING FLUID	Necessary	80.00 FS	*60.00 FS
46	1		*REAR WINDSCREEN SOLAR FILM	Necessary	200.00 FS	*150.00 FS
47	1		*70KM/H STICKER	Necessary	15.00 FS	*10.00 FS
48	2		*BOTH DOOR COMPANY DECAL	Necessary	40.00 FS	*40.00 FS
49	1		*AIRCON DRIER PIPE	Bent	193.00 FL	*193.00 FL
50	1		*LH OIL COOLER OUTER GARNISH	Cracked	142.00 FL	*142.00 FL
51	1		*END INNER PANEL	Bent	442.00 FL	*442.00 FL
52	1		*BOOT LID LOCK COVER GARNISH	Deformed	47.00 FL	*47.00 FL
53	1		*REAR BOOTLID PILLAR PANEL LH	Bent	452.00 FL	*452.00 FL
54	1		*REAR BOOTLID PILLAR PANEL RH (NPA)	Repair	0.00 FL	*- FL
55	1		*REAR COMPARTMENT WOODEN PARK	Cracked	500.00 FS	*200.00 FS
56	1		*REAR SPARE TYRE TOP GARNISH PIPE	Cracked	59.00 FL	*59.00 FL
57	1		*BOOT LID INTER TRIM BOARD CLIPS	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,260.00	17,162.00
- List Item Discount on L Items 30.00/30.00% (\$\$)	6,287.70	4,607.10
Total Parts (\$\$)	16,972.30	12,554.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	2,000.00	1,500.00
2	TO SUPPLY MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	2,000.00	1,800.00
3	TO REMOVE / REFIX / REPLACE WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	100.00	50.00
4	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	100.00	60.00
5	TO REMOVE AND REFIT / REPLACE REAR COMPARTMENT FITTING, TRIMMINGS, GARNISH AND ETC	New	100.00	60.00
6	TO REMOVE AND REPLACE REAR WINDSCREEN	New	150.00	120.00
7	TO REMOVE, REPLACE AND FOCUS BOTH HEADLAMP BEAM	New	60.00	30.00
8	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	60.00	60.00
9	AIR-CON DRAIN AND REFILL SYSTEM	New	100.00	60.00
10	TO CARRIED OUT REPAIR ON REAR COMPARTMENT FLOOR PANEL	New	200.00	150.00
11	TO CARRIED OUT REPAIR ON BOOT LID PILLAR PANEL RH	New	200.00	150.00
12	TO SUPPLY PAINT MATERIALS, EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	500.00	400.00
13	TO REMOVE AND REFIX EXHAUST PIPE AND MUFFLER	New	200.00	60.00
Gross Labour Cost (\$\$)			5,770.00	4,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >