

The insurer has given adjuster a maximum mandate of S\$25,000.00 to authorize directly on their behalf, but the adjuster has disabled direct offer mode.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21003908/AGVF3N2
Date: 10/08/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 1001409671
Claimant Vehicle No: GBL580E	Insured Vehicle No: GW3794T
Date of Loss: 19/03/2021	Nature of Claim: TP
	Claim No: 254875

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBL580E	Engine No: 1KDB071325
Make & Model: TOYOTA HIACE, 3.0 TURBO 4DR AT (A)	Chassis No: JTFHT02P100251637
Reg. Date: 09/03/2021 (Man. Year: 2021)	Odometer: 1551 km
Colour: Silver	
Engine Capacity: 2982 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 195R15C	Rear Tyre Size: 195R15C
Front Left Side: Bridgestone 8 mm	Rear Left Side: Bridgestone 8 mm
Front Right Side: Bridgestone 8 mm	Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,581.92	3,229.00	1,352.92	29.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,710.00	1,110.00	600.00	35.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,291.92	4,339.00	1,952.92	31.04
Approved Total (Overridden) (S\$)		3,450.00		
(S\$)	6,291.92	3,450.00	2,841.92	45.17
+ GST 7.00/7.00% (S\$)	440.43	241.50	198.93	45.17
Nett Amount (S\$)	6,732.35	3,691.50	3,040.85	45.17

INSPECTION

Date of Assignment:	25/03/2021		J-mart Motor Pte Ltd (HQ)
Date Inspected:	26/03/2021	Inspected At:	Blk 5 Defu Lane 10, #01-578
Estimated Period of Repair:	5.0 days		Singapore 539186

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 10 Aug 2021)	
Parts:	N/A	TOYOTA HIACE 3.0 TURBO 4DR AT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL580E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRT RH DOOR	Dented	1,867.90 FL	*1,716.00 FL	
2	2		*FRT RH DOOR HINGES	Not Necessary	190.00 FL	*- FL	
3	1		*FRT RH CORNER PANEL	Dented	265.00 FL	*265.00 FL	
4	1		*RH HEADLAMP	Cut	898.00 FL	*782.00 FL	
5	2		*RH HEADLAMP CLIPS	Not Necessary	50.00 FL	*- FL	
6	1		*FRT BUMPER	Deformed	595.00 FL	*595.00 FL	
7	1		*FRT BUMPER RH RETAINER	Cracked	150.00 FL	*150.00 FL	
8	1		*FRT BUMPER RH FOG LAMP COVER	Not Necessary	50.00 FL	*- FL	
9	1		*FRT RH WING MIRROR	Cut	1,150.00 FL	*569.00 FL	
10	1		*FRT RH STEP GARNISH	Cracked	155.00 FL	*155.00 FL	
11	8		*FRT BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL	
12	1		*AIR CLEANER	Not Necessary	665.00 FL	*- FL	
13	1		*BODY STICKER	Necessary	25.00 FS	*25.00 FS	
					Sub Total (S\$)	6,100.90	4,297.00
					- List Item Discount on L Items 25.00/25.00% (S\$)	1,518.98	1,068.00
					Total Parts (S\$)	4,581.92	3,229.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items**There are no new miscellaneous items selected.****Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	500.00
2	SPRAY PAINTING	New	800.00	500.00
3	TRANSFER DOOR PARTS	New	80.00	80.00
4	WIRING	New	30.00	30.00
			Gross Labour Cost (S\$)	1,710.00
				1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >