



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 798G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BUMPER COVER REAR S6 (SN)	DEFORMED	1,746.00	1,571.40
1	TOW COVER REAR S60 1 (SN)	SCRATCHED	85.50	76.95
1	BUMPER BRACKET CTR R (SN)	SERVICEABLE	102.70	-
1	BUMPER SPOILER REAR (SN)	SERVICEABLE	562.20	-
1	PROTECTING PLATE REA (SN)	SERVICEABLE	512.70	-
1	BUMPER BRACKET REAR (SN)	SERVICEABLE	62.90	-
1	BUMPER BRACKET REAR (SN)	SERVICEABLE	62.90	-
1	BUMPER BRACKET REAR (SN)	SERVICEABLE	62.90	-
1	BUMPER BRACKET RHR S (SN)	SERVICEABLE	62.90	-
1	BUMPER RAIL (BEAM) R (SN)	SERVICEABLE	1,544.30	-
1	BOOT REAR S60 11- (SN)	BENT	2,659.10	2,393.19
1	EMBLEM 'VOLVO' REAR (SN)	NECESSARY	106.40	95.76
1	EMBLEM 'T5' XC60 S80 (SN)	NECESSARY	101.80	91.62
1	EMBLEM 'S60' CH 1700 (SN)	NECESSARY	97.20	87.48
1	TAILLAMP RH S60 11- (SN)	CRACKED	447.80	403.02
1	BOOT LAMP RH S60 11- (SN)	SCRATCHED	236.90	213.21
10	BLIND RIVET 4.0*21 P @\$4.10 (SN)	NECESSARY	41.00	36.90
10	BUMPER CLIP 8X8, 5 @\$6.80 (SN)	NECESSARY	68.00	61.20
1	BUMPER INSTALLING MT (SN)	NECESSARY	96.50	86.85
4	RUST INHIBITING FLUI @\$37.70 (SN)	NOT NECESSARY	150.80	-
1	ADHESIVE TUBE CHEMIC (SN)	NECESSARY	797.60	717.84
			9,608.10	5,835.42
<b>LABOUR</b>				
TO REPLACE REAR BOOT LID, REAR EMBLEM, REAR LH TAIL LAMP, REAR BUMPER, REAR LOWER SPOILER, ETC.			2,550.00	1,700.00
TO PUTTY SPRAY PAINT ON REAR BOOT LID, REAR BUMPER, REAR LOWER SPOILER, ETC.			3,000.00	1,500.00
TO TRANSFER REAR BOOT LID PART.			250.00	250.00
TO INSTALL REAR NUMBER PLATE INCLUDE HOLDER.			60.00	-



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		510.00	510.00
			6,370.00	3,960.00
	<b>GRAND TOTAL</b>		<b>15,978.10</b>	<b>9,795.42</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>9,795.42</b>

Report Ref No. CS/AWA21003910/R1vf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.