



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD
(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Ref: CS/AWA21003910/R1vf3e2

Date: 04/05/2021

Code: AWA

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|-----------------|-----------------------|------------|
| Insured Veh. | XD 4671G | Veh. Inspected | SMD 798G |
| Policy No. | BVFCB0006702015 | Coverage (\$) | 0.00 |
| Claim No. | NSV2100039/SG | Excess (\$) | 0.00 |
| Assign From | HEW LEE FONG | Assign Date | 25/03/2021 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|-------------------|---------------------|------------|
| Make & Model | VOLVO S60 T5 A/T | c.c | 1969 |
| Engine No. | HIDDEN | Year of Reg. | 2018 |
| Chassis No. | YV1FS40LDJ2469346 | Colour | BLACK |
| Odometer | 47903 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | FAIR | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|-----------------------|-------------|----------|---------|
| R/H Front Tyre | 215/50Z R17 | MICHELIN | 6 mm |
| L/H Front Tyre | 215/50Z R17 | MICHELIN | 6 mm |
| R/H Rear Tyre | 215/50Z R17 | MICHELIN | 6 mm |
| L/H Rear Tyre | 215/50Z R17 | MICHELIN | 6 mm |

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

| | | | |
|-----------------------|----------------------------------------------------------------------|------------------------|------------|
| Accident Date | 20/03/2021 | Inspection Date | 19/04/2021 |
| Survey held at | WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935 | | |

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**