

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG21003913/KRS3Q2
Date: 31/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900252997	
Claimant Vehicle No :	SMM4227P	Insured Vehicle No :	SMM6701Z	
Date of Loss:	19/03/2021	Nature of Claim:	TP	Claim No: 4314865973SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM4227P		
Make & Model:	PORSCHE BOXSTER, S 3.4	Engine No:	MA123C02737
Reg. Date:	12/12/2012 (Man. Year: 2012)	Chassis No:	WP0ZZZ98ZDS121588
Colour:	Metallic Grey	Odometer:	76589 km
Engine Capacity:	3436 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/35Z R20	Rear Tyre Size:	265/35Z R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,319.31	3,939.45	1,379.86	25.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,290.00	710.00	580.00	44.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,609.31	4,649.45	1,959.86	29.65
Approved Total (Overridden) (S\$)		3,700.00		

(S\$)	6,609.31	3,700.00	2,909.31	44.02
+ GST 7.00/7.00% (S\$)	462.65	259.00	203.65	44.02
Nett Amount (S\$)	7,071.96	3,959.00	3,112.96	44.02
+ Loss of Use (4.0 x S\$200.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,761.00		

INSPECTION

Date of Assignment: 24/03/2021

Date Inspected: 24/03/2021

Estimated Period of Repair: 3.0 days

Inspected At: Optima Werkz Pte Ltd (HQ)
6 Kung Chong Road
Singapore 159143

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	2,580.80 FL	*2,499.00 FL
2	1		*REAR BUMPER LOWER DIFFUSER CENTER	Cracked	282.50 FL	*282.50 FL
3	1		*REAR BUMPER LOWER RETAINER FRAME	Serviceable	480.25 FL	*- FL
4	2		*REAR BUMPER PARKING SENSOR	Shorted	647.50 FL	*590.00 FL
5	1		*REAR BUMPER INNER BRACKET LH	Repair	283.40 FL	*- FL
6	1		*REAR BUMPER INNER BRACKET RH	Repair	283.40 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Bent	852.50 FL	*789.00 FL
8	1		*REAR BUMPER CLIPS	Necessary	150.00 FS	*150.00 FS
9	1		*REAR BUMPER GROMMET	Serviceable	200.00 FS	*- FS
10	1		*REAR NUMBER PLATE }	Dented	50.00 FS	*45.00 FS
11	1		*REAR NUMBER PLATE HOLDER }	Dented	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,860.35	4,355.50
- List Item Discount on L Items 10.00/10.00% (\$)	541.04	416.05
Total Parts (\$)	5,319.31	3,939.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE ,REPLACE ,REFIX & READJUST REAR ACCIDENT AREAS & ETC	New	500.00	300.00
2	LABOUR CHARGES FOR PAINTING & SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER & ETC	New	400.00	320.00
3	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	120.00	60.00
4	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	150.00	0.00
5	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	120.00	30.00
Gross Labour Cost (S\$)			1,290.00	710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >