

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG21003922/EQF3E2

**Date:** 07/05/2021

### REFERENCE

|                   |              |                  |            |           |              |
|-------------------|--------------|------------------|------------|-----------|--------------|
| Insured/Claimant: | YEO CHOK LIH | Policy No:       | 1900151806 |           |              |
| Date of Loss:     | 23/03/2021   | Nature of Claim: | OD         | Claim No: | 4674164854SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMP1825S</b>                   | Engine No:  | G4FGKH749566      |
| Make & Model:               | KIA CERATO, 1.6 (A)               | Chassis No: | KNAF5416MK5052969 |
| Reg. Date:                  | 02/09/2019 (Man. Year: 2018)      | Odometer:   | 0 km              |
| Colour:                     | Blue                              |             |                   |
| Engine Capacity:            | 1591 cc                           |             |                   |
| Market Value/New Car Price: | S\$83,000.00                      |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |            |                  |            |
|-------------------|------------|------------------|------------|
| Front Tyre Size:  | 225/45 R17 | Rear Tyre Size:  | 225/45 R17 |
| Front Left Side:  | NFERA 5 mm | Rear Left Side:  | NFERA 5 mm |
| Front Right Side: | NFERA 5 mm | Rear Right Side: | NFERA 5 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                | Repairer's       | Adjuster's       | Difference       | Diff %       |
|-------------------------------|------------------|------------------|------------------|--------------|
| Parts                         | 13,690.00        | 8,949.20         | 4,740.80         | 34.63        |
| Miscellaneous Items           | 0.00             | 0.00             | 0.00             |              |
| Labour                        | 13,830.00        | 8,330.00         | 5,500.00         | 39.77        |
| Paintwork Labour              | 0.00             | 0.00             | 0.00             |              |
| Towing                        | 0.00             | 0.00             | 0.00             |              |
| <b>Gross Total (S\$)</b>      | <b>27,520.00</b> | <b>17,279.20</b> | <b>10,240.80</b> | <b>37.21</b> |
| <b>+ GST 7.00/7.00% (S\$)</b> | 1,926.40         | 1,209.54         | 716.86           | 37.21        |
| <b>Nett Amount (S\$)</b>      | <b>29,446.40</b> | <b>18,488.74</b> | <b>10,957.66</b> | <b>37.21</b> |

### INSPECTION

|                             |            |               |                                                                                         |
|-----------------------------|------------|---------------|-----------------------------------------------------------------------------------------|
| Date of Assignment:         | 26/03/2021 |               |                                                                                         |
| Date Inspected:             | 25/03/2021 | Inspected At: | Cycle & Carriage KIA Pte Ltd (Pandan Gardens)<br>209 Pandan Gardens<br>Singapore 609339 |
| Estimated Period of Repair: | 9.0 days   |               |                                                                                         |

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                      | Condition     | Repairer's | Amount       |
|-----|-----|----------|----------------------------------|---------------|------------|--------------|
| 1   | 1   |          | *FRT NUMBER PLATE WITH FRAME     | Bent          | 50.00 FS   | *50.00 FS    |
| 2   | 1   |          | *REAR NUMBER PLATE WITH FRAME    | Not Necessary | 50.00 FS   | *- FS        |
| 3   | 1   |          | *C&C LOGO                        | Necessary     | 40.00 FS   | *40.00 FS    |
| 4   | 1   |          | *SUNDRY                          | Necessary     | 20.00 FS   | *20.00 FS    |
| 5   | 1   |          | *COVER-FR BUMPER                 | Crushed       | 633.00 F   | *633.00 FL   |
| 6   | 1   |          | *GRILLE-FRONT BUMPER             | Broken        | 485.00 F   | *485.00 FL   |
| 7   | 1   |          | *COVER-FR BUMPER FOG LAMP, LH    | Cut           | 15.00 F    | *15.00 FL    |
| 8   | 1   |          | *LAMP ASSY-FRONT FOG, LH         | Not Necessary | 303.00 F   | *- FL        |
| 9   | 1   |          | *MOULDING-FRONT BUMPER, LH       | Cut           | 216.00 F   | *216.00 FL   |
| 10  | 1   |          | *LAMP ASSY-SIDE REPEATER, LH     | Cut           | 143.00 F   | *143.00 FL   |
| 11  | 1   |          | *ABSORBER-FRONT BUMPER ENERGY    | Broken        | 84.00 F    | *84.00 FL    |
| 12  | 1   |          | *BRACKET-FR BUMPER UPR SIDE MTG  | Not Necessary | 22.00 F    | *- FL        |
| 13  | 1   |          | *ULTRASONIC SENSOR ASSY-P.A.S    | Broken        | 163.00 F   | *163.00 FL   |
| 14  | 1   |          | *ORNAMENT-KIA NO.115             | Necessary     | 32.00 F    | *32.00 FL    |
| 15  | 1   |          | *COVER-RR BUMPER                 | Broken        | 651.00 F   | *651.00 FL   |
| 16  | 1   |          | *COVER-RR BUMPER LWR             | Broken        | 241.00 F   | *241.00 FL   |
| 17  | 1   |          | *COVER-RR BUMPER FOG LAMP, RH    | Cut           | 19.00 F    | *19.00 FL    |
| 18  | 1   |          | *COVER-RR BUMPER FOG LAMP, LH    | Cut           | 19.00 F    | *19.00 FL    |
| 19  | 1   |          | *LAMP ASSY-SIDE T/SIGNAL, RH     | Cut           | 181.00 F   | *181.00 FL   |
| 20  | 1   |          | *LAMP ASSY-SIDE T/SIGNAL, LH     | Cut           | 181.00 F   | *181.00 FL   |
| 21  | 1   |          | *EXTN WIRING ASSY-BWS            | Broken        | 207.00 F   | *207.00 FL   |
| 22  | 1   |          | *BRACKET-RR BEAM UPR MTG, RH     | Broken        | 9.00 F     | *9.00 FL     |
| 23  | 1   |          | *BRACKET-RR BEAM UPR MTG, LH     | Not Necessary | 9.00 F     | *- FL        |
| 24  | 1   |          | *BRACKET-RR BEAM LWR, CTR        | Broken        | 6.00 F     | *6.00 FL     |
| 25  | 2   |          | *BRACKET-RR BEAM LWR MTG         | Broken        | 12.00 F    | *12.00 FL    |
| 26  | 1   |          | *ANTENNA ASSY-SMARTKEY           | Not Necessary | 46.00 F    | *- FL        |
| 27  | 1   |          | *BEAM-RR BUMPER                  | Broken        | 318.00 F   | *318.00 FL   |
| 28  | 1   |          | *STAY-RR BUMPER RH               | Bent          | 65.00 F    | *65.00 FL    |
| 29  | 1   |          | *STAY-RR BUMPER LH               | Bent          | 65.00 F    | *65.00 FL    |
| 30  | 1   |          | *COVER-RR BUMPER UNDER, RH       | Not Necessary | 33.00 F    | *- FL        |
| 31  | 1   |          | *BRACKET ASSY-RR BPR SIDE UPR, L | Not Necessary | 25.00 F    | *- FL        |
| 32  | 1   |          | *BRACKET-ASSY RR BPR SIDE UPR R  | Broken        | 31.00 F    | *31.00 FL    |
| 33  | 1   |          | *PANEL ASSY-TRUNK LID            | Dented        | 1,297.00 F | *1,297.00 FL |
| 34  | 1   |          | *HINGE ASSY-TRUNK LID, LH        | Not Necessary | 97.00 F    | *- FL        |
| 35  | 1   |          | *HINGE ASSY-TRUNK LID, RH        | Not Necessary | 97.00 F    | *- FL        |
| 36  | 1   |          | *PANEL ASSY-BACK                 | Dented        | 324.00 F   | *324.00 FL   |
| 37  | 1   |          | *LOGO ASSY-KIA SUB               | Necessary     | 32.00 F    | *32.00 FL    |
| 38  | 1   |          | *EMBLEM-CERATO                   | Necessary     | 28.00 F    | *28.00 FL    |
| 39  | 1   |          | *EMBLEM-GT LINE                  | Necessary     | 45.00 F    | *45.00 FL    |
| 40  | 1   |          | *TRIM ASSY-TRUNK LID             | Not Necessary | 202.00 F   | *- FL        |
| 41  | 1   |          | *W/STRIP-TRUNK LID OPNG          | Crushed       | 100.00 F   | *100.00 FL   |
| 42  | 1   |          | *LATCH ASSY-TRUNK LID            | Bent          | 112.00 F   | *112.00 FL   |
| 43  | 1   |          | *TRIM ASSY-RR TRANSVERSE         | Crushed       | 41.00 F    | *41.00 FL    |
| 44  | 1   |          | *TRIM ASSY-LUGGAGE SIDE RH       | Not Necessary | 200.00 F   | *- FL        |
| 45  | 1   |          | *MAT ASSY-LUGGAGE COVERING       | Broken        | 211.00 F   | *211.00 FL   |
| 46  | 1   |          | *PANEL ASSY-REAR FLOOR, RR       | Dented        | 219.00 F   | *219.00 FL   |
| 47  | 1   |          | *LAMP ASSY-REAR COMB INSIDE, RH  | Cut           | 608.00 F   | *608.00 FL   |
| 48  | 1   |          | *LAMP ASSY-REAR COMB INSIDE, LH  | Cut           | 608.00 F   | *608.00 FL   |
| 49  | 1   |          | *LAMP ASSY-REAR COMB OUTSIDE, RH | Cut           | 675.00 F   | *675.00 FL   |
| 50  | 1   |          | *LAMP ASSY-REAR COMB OUTSIDE, LH | Cracked       | 675.00 F   | *675.00 FL   |
| 51  | 1   |          | *MUFFLER ASSY-REAR               | Not Necessary | 757.00 F   | *- FL        |
| 52  | 1   |          | *PROTECTOR-HEAT REAR             | Bent          | 136.00 F   | *136.00 FL   |
| 53  | 1   |          | *LAMP ASSY-CENTER GARNISH        | Not Necessary | 690.00 F   | *- FL        |
| 54  | 1   |          | *WIRING ASSY-BUMPER EXTENSION    | Broken        | 207.00 F   | *207.00 FL   |

(Supplementary)

| No. | Qty | Part No. | Particulars                                                | Condition | Repairer's | Amount       |
|-----|-----|----------|------------------------------------------------------------|-----------|------------|--------------|
| 55  | 1   |          | <b>*REINF-RR SPARE TIRE WELL CROSS</b><br>(Supplementary)  | Necessary | 41.00 F    | *41.00 FL    |
| 56  | 1   |          | <b>*HOOK-TOWING</b><br>(Supplementary)                     | Necessary | 16.00 F    | *16.00 FL    |
| 57  | 1   |          | <b>*REINF-TOWING HOOK</b><br>(Supplementary)               | Necessary | 14.00 F    | *14.00 FL    |
| 58  | 1   |          | <b>*PANEL ASSY-QUARER OUTER, LH</b><br>(Supplementary)     | Dented    | 1,349.00 F | *1,349.00 FL |
| 59  | 1   |          | <b>*PANEL ASSY-RR COMB LAMP HSG, LH</b><br>(Supplementary) | Dented    | 139.00 F   | *139.00 FL   |
| 60  | 1   |          | <b>*PANEL ASSY-RR COMB HSG, RH</b><br>(Supplementary)      | Dented    | 135.00 F   | *135.00 FL   |
| 61  | 15  |          | <b>*CLIPS</b><br>(Supplementary)                           | Necessary | 15.00 F    | *15.00 FL    |
| 62  | 5   |          | <b>*FASTENER</b><br>(Supplementary)                        | Necessary | 5.00 F     | *5.00 FL     |
| 63  | 2   |          | <b>*GROMMETS</b><br>(Supplementary)                        | Necessary | 4.00 F     | *4.00 FL     |
| 64  | 2   |          | <b>*SILENCER, FLOOR</b><br>(Supplementary)                 | Necessary | 26.00 F    | *26.00 FL    |
| 65  | 1   |          | <b>*COVER-RR BUMPER UNDER, LH</b><br>(Supplementary)       | Broken    | 33.00 F    | *33.00 FL    |
| 66  | 1   |          | <b>*ULTRASONIC SENSOR ASSY-BWS</b><br>(Supplementary)      | Broken    | 163.00 F   | *163.00 FL   |
| 67  | 1   |          | <b>*BRACKET ASSY-SPARE TIRE MTG</b><br>(Supplementary)     | Necessary | 15.00 F    | *15.00 FL    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                           |                  |                  |
|-----------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                   | <b>13,690.00</b> | <b>11,159.00</b> |
| <b>- List Item Discount on L Items 0.00/20.00% (\$\$)</b> | 0.00             | 2,209.80         |
| <b>Total Parts (\$\$)</b>                                 | <b>13,690.00</b> | <b>8,949.20</b>  |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                                                            | Lab.Type | Repairer's       | Amount          |
|---------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|----------|------------------|-----------------|
| <b>Labour Items</b>             |                                                                                                                                        |          |                  |                 |
| 1                               | RENEW FRT BUMPER                                                                                                                       | New      | 400.00           | 400.00          |
| 2                               | SPRAY PAINT FOR FRT BUMPER                                                                                                             | New      | 350.00           | 350.00          |
| 3                               | REMOVE & INSTALL FRT PARKING SENSOR                                                                                                    | New      | 60.00            | 60.00           |
| 4                               | CHECK WIRING & ELECTRICAL SYSTEM                                                                                                       | New      | 30.00            | 30.00           |
| 5                               | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST                                                            | New      | 120.00           | 120.00          |
| 6                               | REMOVE & INSTALL REAR COMPARTMENT TRIMS                                                                                                | New      | 300.00           | 300.00          |
| 7                               | REMOVE & INSTALL PARKING SENSOR                                                                                                        | New      | 60.00            | 60.00           |
| 8                               | REMOVE & INSTALL CARPAT AND REAR SEATS                                                                                                 | New      | 300.00           | 300.00          |
| 9                               | SPRAY PAINT FOR REAR BUMPER, BOOTLID, REAR END PANEL, REAR COMPARTMENT REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH, REAR CHASSIS RH | New      | 3,500.00         | 1,400.00        |
| 10                              | REMOVE & INSTALL REA SPOILER                                                                                                           | New      | 100.00           | 80.00           |
| 11                              | APPLY SEALANT FOR ACCIDENT PORTION                                                                                                     | New      | 120.00           | 40.00           |
| 12                              | TO STRAIGHTEN REAR BOTH CHASSIS                                                                                                        | New      | 500.00           | 0.00            |
| 13                              | RENEW REAR EXHAUST SYSTEM                                                                                                              | New      | 300.00           | 300.00          |
| 14                              | REMOVE & INSTALL LH REAR QUARTER GLASS AND CONDUCT WATER LEAK REST<br>(Supplementary)                                                  | New      | 120.00           | 120.00          |
| 15                              | REMOVE & INSTALL REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST<br>(Supplementary)                                                  | New      | 240.00           | 240.00          |
| 16                              | SUPPLY REAR WINDSCREEN GLASS SEALANT<br>(Supplementary)                                                                                | New      | 80.00            | 80.00           |
| 17                              | REPLACE DAMAGED PARTS, REPLACE LH REAR FENDER, REAR FLOOR PANEL, LH & RH REAR COMB LAMP HOUSING, RH REAR CHASSIS<br>(Supplementary)    | New      | 2,000.00         | 2,000.00        |
| 18                              | RESPRAY ON RH REAR FENDER, REAR FLOOR PANEL, REPAIR LH & RH REAR COMB LAMP HOUSING, RH REAR CHASSIS<br>(Supplementary)                 | New      | 1,050.00         | 1,050.00        |
| 19                              | REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR<br>(Supplementary)                                                                     | New      | 200.00           | 200.00          |
| 20                              | REPLACE REAR BUMPER, BOOTLID, REAR END PANEL, REAR COMPARTMENT. REPAIR REAR LAMP HOUSING RH & LH, REAR FENDER RH & LH, REAR CHASSIS RH | New      | 4,000.00         | 1,200.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                                                        |          | <b>13,830.00</b> | <b>8,330.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >