

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/TMI21003926/KTF3Q2

**Date:** 06/04/2021

### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No: ML000509
<b>Claimant</b>	
<b>Vehicle No :</b> SHC5402E	<b>Insured Vehicle No :</b> SMH8515H
Date of Loss: 19/03/2021	Nature of Claim: TP Claim No: M2101373

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SHC5402E</b>	Engine No: M9R8839C001807
Make & Model: HONDA AIRWAVE, 1.5 M (A)	Chassis No: VF1ABL15AUC279583
Reg. Date: 04/11/2014 (Man. Year: 2014)	Odometer: 714247 km
Colour: Metallic White/Red	
Engine Capacity: 1995 cc	
Market Value/New Car Price: N/A	
Sum Insured (\$\$): <b>Market Value/New Car Price</b>	

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16	Rear Tyre Size: 215/60 R16
Front Left Side: Sailun 8 mm	Rear Left Side: Sailun 9 mm
Front Right Side: Sailun 8 mm	Rear Right Side: Sailun 9 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,837.86	0.00	2,837.86	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	220.00	7,360.00	97.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>10,417.86</b>	<b>220.00</b>	<b>10,197.86</b>	<b>97.89</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	729.25	15.40	713.85	97.89
<b>Nett Amount (\$\$)</b>	<b>11,147.11</b>	<b>235.40</b>	<b>10,911.71</b>	<b>97.89</b>

### INSPECTION

Date of Assignment: 26/03/2021		
Date Inspected: 23/03/2021	Inspected At:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
		2, Ang Mo Kio Street 63
		Singapore 569111
Estimated Period of Repair: 1.0 days		

**Adjuster:** KENNETH KONG

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 06 Apr 2021)
<b>Parts:</b>	M1-MPV	HONDA AIRWAVE 1.5 M (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SHC5402E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BUMPER COVER REAR	Repair	561.70 FL	-	*-FL
2	1		*BUMPER LOWER REAR	Serviceable	411.90 FL	-	*-FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	-	*-FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	-	*-FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	-	*-FL
6	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	-	*-FL
7	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	-	*-FL
8	1		*BUMPER BEAM REAR	Repair	547.80 FL	-	*-FL
9	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	-	*-FL
10	1		*BUMPER BEAM BRACKET RH REAR	Repair	114.50 FL	-	*-FL
11	1		*SET PARKING AID	Serviceable	700.00 FS	-	*-FS
12	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	-	*-FS
13	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	-	*-FS
14	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	-	*-FS
15	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	-	*-FS
16	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	-	*-FS
17	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	-	*-FS
18	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	-	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,050.40</b>	<b>0.00</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	212.54	0.00
<b>Total Parts (\$\$)</b>	<b>2,837.86</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PUTTYAND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	3,000.00	0.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>7,580.00</b>	<b>220.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >