

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG21003931/GVF3Q2

**Date:** 13/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070035867

**Claimant**  
**Vehicle No :** SMP2829A **Insured Vehicle No :** SFJ9807G

Date of Loss: 23/03/2021 Nature of Claim: TP Claim No: 7791270056SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMP2829A</b>		
Make & Model:	VOLKSWAGEN PASSAT, 1.8 T (B5) (A)	Engine No:	LEB5643780
Reg. Date:	19/09/2019 (Man. Year: 2019)	Chassis No:	GB71102388
Colour:	Blue	Odometer:	102903 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 26/03/2021

Date Inspected: 26/03/2021 Inspected At: 25 Kaki Bukit Road 4, #01-56 Synergy  
Repairer: Apex Motoring

Estimated Period of Repair: 4.0 days

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT RH DOOR	Repair	0.00 F	*- F
2	1		*FRT RH DOOR WING MIRROR	Cut	0.00 F	*- F
3	1		*FRT RH FENDER	Repair	0.00 F	*- F
4	1		*FRONT RH WHEEL RIM COVER	Scratched	0.00 F	*- F
5	1		*FRT RH SHOCK ABSORBER	*Check	0.00 F	*- F
6	1		*FRT RH KNUCKLE ARM	*Check	0.00 F	*- F
7	1		*FRT RH KNUCKLE ARM BEARING	*Check	0.00 F	*- F
8	1		*FRT RH LOWER ARM	*Check	0.00 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**