

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21003936/BVF3E2

Date: 07/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800054149		
Claimant Vehicle No :	SGS9978L	Insured Vehicle No :	GBG1233C		
Date of Loss:	24/03/2021	Nature of Claim:	TP	Claim No:	1329447862SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGS9978L	Engine No:	4G18HY6049
Make & Model:	MITSUBISHI LANCER, 1.3 (A)	Chassis No:	JMYSTCS3A7U009907
Reg. Date:	29/03/2007 (Man. Year: 2007)	Odometer:	221962 km
Colour:	Grey		
Engine Capacity:	1584 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	KAPSEN 5 mm	Rear Left Side:	KAPSEN 5 mm
Front Right Side:	KAPSEN 5 mm	Rear Right Side:	KAPSEN 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	25/03/2021	
Date Inspected:	26/03/2021	Inspected At: Hong Motor Services (HQ) BLK 5035 ANG MO KIO IND PARK 2 #01-365 Singapore 569538
Estimated Period of Repair:	7.0 days	

Adjuster: Lim Teow Guan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Dented	0.00 F	*- F
2	2		*FRT BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
3	1		*FRT LH HEADLAMP ASSY	Broken	0.00 F	*- F
4	1		*FRT LH FENDER	Dented	0.00 F	*- F
5	1		*FRT LH FENDER LAMP	Dislodged	0.00 F	*- F
6	1		*FRT LH FENDER INNER SHIELD	Torn	0.00 F	*- F
7	1		*BONNET MISALIGNED	Repair	0.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >