



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08778/ABDUL WAHID THOWZEEFAHAMED Reg No/Reg Date SMJ5285E*KC17/ 11/03/201 Date In/Mileage 26/03/2021/ 0 Chassis No KNAF3416MK5031024 Engine No G4FGJH722457 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	26/03/2021/ 12:43	QUK	282 / Kevin Leong	31131			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, BUMPER LWR & AFFECTED AREA REPAIR ON END PANEL					400X1			1200.00
E PNT98000 PAINT WORK ON REAR BUMPER PANEL & END PANEL					350X1			700.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST								120.00
M SUNDRY PERFORM RUST PREVENTION								40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY SUNDRIES								50.00
M COVER-RR BUMPER					1.00	651.00	20.00	520.80
M COVER-RR BUMPER LWR					1.00	241.00	20.00	192.80
M COVER-RR BUMPER UNDER, LH					1.00	33.00	20.00	26.40
M COVER-RR BUMPER FOG LAMP, LH					1.00	19.00	20.00	15.20
M LAMP ASSY-SIDE T/SIGNAL, LH					1.00	181.00	20.00	144.80
M EXTN WIRING ASSY-BWS					1.00	207.00	20.00	165.60
M BRACKET-RR BEAM UPR MTG, LH					1.00	9.00	20.00	7.20
M BRACKET-RR BEAM UPR MTG, RH					1.00	9.00	20.00	7.20
M BRACKET-RR BEAM LWR, CTR					1.00	6.00	20.00	4.80
M BRACKET-RR BEAM LWR MTG					1.00	6.00	20.00	4.80
M BEAM-RR BUMPER					1.00	318.00	20.00	254.40
M ANTENNA ASSY-SMARTKEY					1.00	46.00	20.00	36.80
M STAY-RR BUMPER LH					1.00	65.00	20.00	52.00
M BRACKET ASSY-RR BPR SIDE UPR, L					1.00	25.00	20.00	20.00
M COVER-RR BUMPER FOG LAMP, LH					1.00	19.00	20.00	15.20

Estimate

Steve CLKK)

DD-NH AL

Express -?

P/P

Confirm & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized signatory and company stamp

My Bal Sky
5 days
26/3/21, 2.00pm

Nett

3,728.00

7% GST on

3728.00

260.96

Total Payable

3,988.96

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.