

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV08778/ABDUL WAHID THOWZEEFAHAMED
	Reg No/Reg Date	SMJ5285E*KC17/ 11/03/201
	Date In/Mileage	26/03/2021/ 0
	Chassis No	KNAF3416MK5031024
	Engine No	G4FGJH722457
	Make/Model	KIA/CERATO 1.6 A SR SX G335
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	26/03/2021/ 12:43	QUK	282 / Kevin Leong	31131		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR BUMPER, BUMPER LWR & AFFECTED AREA REPAIR ON END PANEL							1200.00
E PNT98000 PAINT WORK ON REAR BUMPER PANEL & END PANEL							700.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST							120.00
M SUNDRY PERFORM RUST PREVENTION							40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
M SUNDRY SUNDRIES							50.00
M	COVER-RR BUMPER			1.00	651.00	20.00	520.80
M	COVER-RR BUMPER LWR			1.00	241.00	20.00	192.80
M	COVER-RR BUMPER UNDER,LH			1.00	33.00	20.00	26.40
M	COVER-RR BUMPER FOG LAMP,LH			1.00	19.00	20.00	15.20
M	LAMP ASSY-SIDE T/SIGNAL,LH			1.00	181.00	20.00	144.80
M	EXTN WIRING ASSY-BWS			1.00	207.00	20.00	165.60
M	BRACKET-RR BEAM UPR MTG,LH			1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM UPR MTG,RH			1.00	9.00	20.00	7.20
M	BRACKET-RR BEAM LWR,CTR			1.00	6.00	20.00	4.80
M	BRACKET-RR BEAM LWR MTG			1.00	6.00	20.00	4.80
M	BEAM-RR BUMPER			1.00	318.00	20.00	254.40
M	ANTENNA ASSY-SMARTKEY			1.00	46.00	20.00	36.80
M	STAY-RR BUMPER LH			1.00	65.00	20.00	52.00
M	BRACKET ASSY-RR BPR SIDE UPR,L			1.00	25.00	20.00	20.00
M	COVER-RR BUMPER FOG LAMP,LH			1.00	19.00	20.00	15.20

Confirm & accepted by

7% GST on	Nett 3728.00	3,728.00 260.96
Total Payable		3,988.96

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.