

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21003946/BVF3E2

Date: 29/10/2021

REFERENCE

Insured/Claimant:	CHUA LAY CHOO	Policy No:	1700076562		
Date of Loss:	24/03/2021	Nature of Claim:	OD	Claim No:	9780225002SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKH4618U	Engine No:	1NZX673790
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR053HY9305043378
Reg. Date:	26/12/2007 (Man. Year: 2007)	Odometer:	175629 km
Colour:	Yellow		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	S\$38,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55R15	Rear Tyre Size:	195/55R15
Front Left Side:	Dayton 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	Dayton 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,329.19	5,858.72	21,470.47	78.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,730.00	3,480.00	7,250.00	67.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,059.19	9,338.72	28,720.47	75.46
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	37,459.19	8,738.72	28,720.47	76.67
+ GST 7.00/7.00% (S\$)	2,622.14	611.71	2,010.43	76.67
Nett Amount (S\$)	40,081.33	9,350.43	30,730.90	76.67

INSPECTION

Date of Assignment:	26/03/2021		
Date Inspected:	26/03/2021	Inspected At:	Team Autopro Pte Ltd (Sin Ming) 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722
Estimated Period of Repair:	12.0 days		

Adjuster: Lim Teow Guan

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	547.60 FL	*436.50 FL
2	1		*REAR BUMPER REFLECTOR	O/s Broken	518.60 FL	*35.70 FL
3	2		*REAR BUMPER SIDE RETAINER FRONT	Repeated	307.60 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER REAR	Necessary	378.40 FL	*37.80 FL
5	1		*REAR FENDER RH	Repair	785.40 FL	*- FL
6	1		*REAR FENDER INNER TRIM BOARD RH	Not Damaged	489.60 FL	*- FL
7	1		*REAR FENDER INNER COWLING RH	Not Damaged	147.80 FL	*- FL
8	1		*REAR AIR VENTS	Not Damaged	86.30 FL	*- FL
9	1		*REAR WINDSCREEN MOULDING	Not Necessary	185.30 FL	*- FL
10	1		*REAR END PANEL	Not Damaged	588.30 FL	*- FL
11	1		*REAR END PANEL TOP GARNISH	Not Damaged	198.50 FL	*- FL
12	1		*TAILLAMP RH	Not Damaged	652.80 FL	*- FL
13	1		*REAR EXHAUST	Not Damaged	549.30 FL	*- FL
14	1		*REAR EXHAUST HEAT SHIELD	Not Damaged	144.00 FL	*- FL
15	2		*REAR EXHAUST MOUNTING	Not Damaged	131.60 FL	*- FL
16	1		*BONNET	Bent	682.30 FL	*486.30 FL
17	2		*BONNET HINGE	Bent	108.40 FL	*108.40 FL
18	1		*BONNET INNER LOCK	Bent	84.30 FL	*84.30 FL
19	1		*BONNET INNER LOCK CABLE	Not Damaged	110.00 FL	*- FL
20	1		*FRONT GRILLE	Broken	320.50 FL	*305.80 FL
21	1		*FRONT BUMPER LOGO	Necessary	85.60 FL	*27.40 FL
22	1		*FRONT GRILLE OUTER CHROME	Necessary	85.90 FL	*85.90 FL
23	1		*FRONT BUMPER	Broken	658.20 FL	*450.00 FL
24	2		*FRONT BUMPER BRACKET	No such part	374.60 FL	*- FL
25	1		*FRONT BUMPER CENTRE INNER GARNISH	No such part	336.50 FL	*- FL
26	1		*FRONT BUMPER INNER PAD	Bent	314.50 FL	*65.59 FL
27	2		*FRONT BUMPER SIDE RETAINER	Necessary	168.00 FL	*54.40 FL
28	1		*FRONT BUMPER CENTRE GRILLE	Broken	210.00 FL	*79.60 FL
29	2		*FRONT BUMPER FOG LAMP	Not Damaged	463.40 FL	*- FL
30	2		*FRONT BUMPER FOG LAMP GARNISH	Not Necessary	291.60 FL	*- FL
31	1		*FRONT BUMPER REINFORCEMENT	Bent	488.60 FL	*299.00 FL
32	1		*FRONT BUMPER TOW COVER	Missing	58.30 FL	*12.60 FL
33	1		*FRONT SUPPORT PANEL	Bent	652.00 FL	*518.90 FL
34	1		*FRONT CHASSIS FRAME RH	Repair	687.00 FL	*- FL
35	2		*HEADLAMP	Broken	1,516.40 FL	*856.30 FL
36	2		*HEADLAMP LOWER BRACKET	No such part	297.40 FL	*- FL
37	2		*HEADLAMP TOP BEAM	Repair	621.60 FL	*- FL
38	1		*FRONT AIR GUIDE	Not Necessary	98.00 FL	*- FL
39	2		*FRONT FENDER	O/s Dented/N/s Cut	1,174.00 FL	*748.80 FL
40	2		*FRONT FENDER EMBLEM VVT-I	Not Necessary	125.00 FL	*- FL
41	1		*FRONT FENDER INNER COWLING (2PCS)	Missing (1Pc Only)	290.00 FL	*92.60 FL
42	2		*FRONT DOOR	Not Damaged	1,562.00 FL	*- FL
43	2		*FRONT DOOR BLACK TAPE	Not Necessary	168.00 FL	*- FL
44	1		*AIR CON CONDENSER	Bent	987.20 FL	*670.00 FL
45	1		*AIRCON COMPRESSOR	Not Damaged	1,123.00 FL	*- FL
46	1		*AIRCON CONDENSER	Repeated	985.00 FL	*- FL
47	1		*AIRCON SUCTION HOSE	Not Necessary	398.00 FL	*- FL
48	1		*AIRCON DISCHARGE HOSE	Bent	352.00 FL	*83.00 FL
49	1		*RADIATOR	Bent	985.00 FL	*452.10 FL
50	1		*RADIATOR FAN ASSY	Broken	776.00 FL	*495.10 FL
51	1		*RADIATOR TOP HOSE	Not Damaged	148.60 FL	*- FL
52	1		*RADIATOR LOWER HOSE	Not Damaged	159.30 FL	*- FL
53	1		*FAN BELT	Not Damaged	194.50 FL	*- FL
54	1		*AIR DUCT	Not Damaged	146.00 FL	*- FL
55	1		*AIR CLEANER BOX	Not Damaged	482.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*FRONT ENGINE UNDER COVER	Not Damaged	384.70 FL	*- FL
57	1		*ALTORNATER ASSY	Not Damaged	785.00 FL	*- FL
58	1		*STARTER MOTOR ASSY	Not Damaged	954.60 FL	*- FL
59	1		*WIPER WASHER TANK	Broken	98.00 FL	*63.90 FL
60	1		*WIPER WASHER TANK MOTOR	Not Damaged	110.00 FL	*- FL
61	1		*FRONT KNUCKLE ARM RH	Not Damaged	398.00 FL	*- FL
62	1		*FRONT KNUCKLE ARM BEARING RH	Not Necessary	245.50 FL	*- FL
63	1		*FRONT SHOCK ABSORBER RH	Bent	270.00 FL	*270.00 FL
64	1		*FRONT LOWER ARM RH	Bent	535.25 FL	*285.10 FL
65	1		*STEERING RACK	Not Damaged	1,108.00 FL	*- FL
66	1		*REAR SHOCK ABSORBER RH	Not Damaged	412.50 FL	*- FL
67	1		*REAR AXLE	Not Damaged	1,688.00 FL	*- FL
68	1		*REAR WHEEL HUB WITH BEARING RH	Jammed	369.80 FL	*229.10 FL
69	1		*WATER PUMP	Jammed	247.00 FL	*144.10 FL
70	1		*WATER PUMP PULLEY	Not Damaged	88.00 FL	*- FL
71	1		*ENGINE MOUNTING FRONT	Not Damaged	245.00 FL	*- FL
72	1		*ENGINE MOUNTING SIDE	Not Damaged	265.00 FL	*- FL
73	1		*GEARBOX MOUNTING	Not Damaged	248.00 FL	*- FL
74	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
75	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
76	2		*REAR BUMPER REVERSE SENSOR	Not Necessary	500.00 FS	*- FS
77	1		*REAR FENDER SEALANT	Not Necessary	100.00 FS	*- FS
78	1		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	50.00 FS	*- FS
79	1		*REAR FENDER INER COWLING CLIPS	Not Necessary	50.00 FS	*- FS
80	1		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
81	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	80.00 FS	*- FS
82	1		*REAR WINDSCREEN PRIMER & CLANER	Not Necessary	60.00 FS	*- FS
83	1		*REAR END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
84	1		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
85	1		*TAILLAMP CLIPS	Not Necessary	50.00 FS	*- FS
86	1		*TAILLAMP SEAL	Not Necessary	60.00 FS	*- FS
87	1		*BONNET SEALANT	Not Necessary	100.00 FS	*- FS
88	1		*FRONT GRILLE CLIPS	Necessary	50.00 FS	*30.00 FS
89	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
90	2		*FRONT BUMPER FOG LAMP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
91	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
92	1		*FRONT CHASSIS FRAME SEALANT	Not Necessary	100.00 FS	*- FS
93	2		*FRONT FENDER SEALANT	Not Necessary	200.00 FS	*- FS
94	1		*FRONT FENDER INNER COWLING CLIPS	O/S Necessary	100.00 FS	*30.00 FS
95	2		*FRONT DOOR SEALANT	Not Necessary	200.00 FS	*- FS
96	1		*FRONT NUMBER PLATE W/CASING	Broken	80.00 FS	*50.00 FS
97	1		*RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS
98	1		*AIRCON FLUID	Necessary	80.00 FS	*40.00 FS
99	1		*HORN	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	35,562.25	7,728.29
- List Item Discount on L Items 25.00/25.00% (\$)	8,233.06	1,869.57
Total Parts (\$)	27,329.19	5,858.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R REVERSE SENSOR	New	100.00	60.00
2	R&R REAR WINDSCREEN	New	250.00	0.00
3	R&R REAR EXHAUST	New	150.00	0.00
4	R&R REAR UNDER CARRIAGE	New	250.00	120.00
5	R&R REAR TYRE AND BALANCING	New	100.00	0.00
6	REAR CHECK WIRING	New	100.00	30.00
7	REAR UPHOLSTERY	New	300.00	0.00
8	REAR PANEL BEATING	New	1,000.00	200.00
9	REAR RUST PROOFING	New	200.00	0.00
10	REAR SPRAY PAINTING	New	1,000.00	300.00
11	R&R BONNET COMPONENT	New	150.00	80.00
12	R&R AIR CON CONDENSER	New	150.00	120.00
13	R&R RADIATOR	New	150.00	70.00
14	R&R RADIATOR FAN ASSY	New	150.00	50.00
15	R&R AIRCON COMPRESSER	New	150.00	80.00
16	R&R ALTORNATER ASSY	New	150.00	50.00
17	R&R STARTER MOTOR ASSY	New	150.00	0.00
18	R&R ENGINE MOUNTING & GEAR BOX MOUNTING	New	450.00	0.00
19	R&R FRONT UNDER CARRIAGE	New	250.00	150.00
20	R&R FRONT TYRE AND BALANCING	New	100.00	0.00
21	WHEEL ALIGNMENT	New	180.00	60.00
22	MOUNT WORK BENCH	New	350.00	0.00
23	CHASSIS ALIGNMENT	New	300.00	0.00
24	FRONT UPHOLSTERY	New	300.00	0.00
25	FRONT CHECKING WIRING	New	100.00	30.00
26	FRONT PANEL BEATING	New	2,000.00	1,000.00
27	FRONT RUST PROOFING	New	200.00	80.00
28	FRONT SPRAY PAINTING	New	2,000.00	1,000.00
Gross Labour Cost (\$\$)			10,730.00	3,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >