

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG21003949/QRA3Q2
Date: 16/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100470739
Claimant Vehicle No :	SHC4601D	Insured Vehicle No :	SMN64M
Date of Loss:	23/03/2021	Nature of Claim:	TP
		Claim No:	8489098031SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC4601D	Engine No:	2ZR6129575
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Chassis No:	JTDKN36U605748728
Reg. Date:	08/09/2014 (Man. Year: 2014)	Odometer:	624912 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	64,628.96	11,326.60	53,302.36	82.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,156.00	3,530.00	6,626.00	65.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	74,784.96	14,856.60	59,928.36	80.13
Approved Total (Overridden) (S\$)		14,850.00		

Nett Amount (S\$)	74,784.96	14,850.00	59,934.96	80.14
+ Loss of Use (15.0 x S\$50.00/day) (S\$)		750.00		
+ Car Rental (15.0 x S\$106.47/day) (S\$)		1,597.05		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		17,204.05		

INSPECTION

Date of Assignment: 25/03/2021

Date Inspected: 25/03/2021

Estimated Period of Repair: 11.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705

Adjuster: OI SUN PIN**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE ASY (DISC 25%)	Dented	1,007.90 F	*755.93 F
2	1		*TAILGATE DOOR GLASS MOULDING RH (DISC 25%)	Necessary	29.40 F	*22.05 F
3	1		*TAILGATE DOOR GLASS MOULDING LH (DISC 25%)	Necessary	29.40 F	*22.05 F
4	1		*MOULDING BACK WINDOW ,LOWER NO.1 (DISC 25%)	Necessary	29.40 F	*22.05 F
5	1		*MOULDING BACK WINDOW ,LOWER NO.2 (DISC 25%)	Necessary	29.40 F	*22.05 F
6	1		*DAM ,BACK DOOR GLASS ADHESIVE NO.1 (DISC 25%)	Necessary	27.30 F	*20.48 F
7	1		*DAM ,BACK DOOR GLASS ADHESIVE NO.2 (DISC 25%)	Necessary	17.40 F	*13.05 F
8	1		*TAILGATE DOOR LOCK (DISC 25%)	Jammed	444.10 F	*333.08 F
9	1		*TAILGATE LOCK COVER (DISC 25%)	Broken	15.70 F	*11.78 F
10	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
11	1		*HOOD PANEL (DISC 25%)	Dented	748.10 F	*561.08 F
12	1		*HOOD LOCK (DISC 25%)	Jammed	128.90 F	*96.68 F
13	1		*TAILGATE DOOR WEATHERSTRIP (DISC 25%)	Broken	353.40 F	*265.05 F
14	1		*BUMPER REAR (DISC 25%)	Crumpled	458.60 F	*343.95 F
15	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	21.00 F	*15.75 F
16	1		*BUMPER SIDE RETAINER RR/LH (DISC 25%)	Broken	94.80 F	*71.10 F
17	1		*BUMPER SIDE RETAINER RR/RH (DISC 25%)	Broken	94.80 F	*71.10 F
18	1		*BUMPER LIP COVER RR/RH (DISC 25%)	Crumpled	118.10 F	*88.58 F
19	1		*BUMPER LIP REAR (DISC 25%)	Crumpled	228.90 F	*171.68 F
20	1		*BUMPER FRT (DISC 25%)	Crumpled	482.00 F	*361.50 F
21	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
22	1		*BUMPER SUPPORT F/RH (DISC 25%)	Broken	76.40 F	*57.30 F
23	1		*BUMPER SUPPORT F/LH (DISC 25%)	Broken	76.40 F	*57.30 F
24	1		*BUMPER ENERGY ABSORBER FRT (DISC 25%)	Crumpled	78.80 F	*59.10 F
25	1		*BUMPER REINFORCEMENT FRT (DISC 25%)	Dented	498.40 F	*373.80 F
26	1		*ARM SUB-ASSY ,FR BUMPER LH (DISC 25%)	Bent	250.40 F	*187.80 F
27	1		*ARM SUB-ASSY ,FR BUMPER RH (DISC 25%)	Bent	250.40 F	*187.80 F
28	1		*BRACKET ,FR BUMPER (DISC 25%)	Crumpled	110.40 F	*82.80 F
29	1		*COVER ,FR BUMPER HOLE LH (DISC 25%)	Crumpled	18.50 F	*13.88 F
30	1		*COVER ,FR BUMPER HOLE RH (DISC 25%)	Crumpled	18.50 F	*13.88 F
31	1		*BUMPER GRILLE SUB-ASSY LOWER (DISC 25%)	Crumpled	311.10 F	*233.33 F
32	1		*EMBLEM FRONT (DISC 25%)	Necessary	86.50 F	*64.88 F
33	1		*HOOD END PANEL SEAL (DISC 25%)	Necessary	35.50 F	*26.63 F
34	1		*BUMPER LIP FRT (DISC 25%)	Deformed	139.60 F	*104.70 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
35	1		*TAILGATE ,BOARD ASSY (DISC 25%)	Cracked	246.90 F	*185.18 F
36	1		*WIPER WASHER JAR (DISC 25%)	Crumpled	180.10 F	*135.08 F
37	1		*A/C CONDENSER (DISC 25%)	Crumpled	1,181.90 F	*886.43 F
38	1		*RADIATOR ASSY UPPER (DISC 25%)	Crumpled	679.60 F	*509.70 F
39	1		*RADIATOR ASSY (DISC 25%)	Crumpled	1,496.90 F	*1,122.68 F
40	1		*FAN SHROUD (DISC 25%)	Crumpled	244.50 F	*183.38 F
41	1		*FAN SHROUD TOP (DISC 25%)	Cracked	99.60 F	*74.70 F
42	1		*FAN BLADE (DISC 25%)	Cracked	158.60 F	*118.95 F
43	1		*FAN BLADE NO.2 (DISC 25%)	Cracked	204.20 F	*153.15 F
44	1		*FAN MOTOR NO.1 (DISC 25%)	Jammed	538.30 F	*403.73 F
45	1		*FAN MOTOR NO.2 (DISC 25%)	Jammed	538.30 F	*403.73 F
46	1		*BUMPER REINFORCEMENT REAR (DISC 25%)	Bent	205.70 F	*154.28 F
47	1		*ARM SUB-ASSY ,RR BUMPER RH (DISC 25%)	Bent	139.60 F	*104.70 F
48	1		*ARM SUB-ASSY ,RR BUMPER LH (DISC 25%)	Bent	139.60 F	*104.70 F
49	1		*UNDER COVER SUB-ASSY ,RR FLOOR (DISC 25%)	Crumpled	514.50 F	*385.88 F
50	1		*END PANEL (DISC 25%)	Dented	602.10 F	*451.58 F
51	1		*DEGLECTOR ,RADIATOR RH (DISC 25%)	Crumpled	83.50 F	*62.63 F
52	1		*DEGLECTOR ,RADIATOR LH (DISC 25%)	Crumpled	77.00 F	*57.75 F
53	1		*GRILLE ,RADIATOR (DISC 25%)	Cracked	310.60 F	*232.95 F
54	1		*BUMPER FRT ABSORBER LOWER (DISC 25%)	Cracked	127.70 F	*95.78 F
55	1		*HEAD LAMP LH (DISC 10%)	Cracked	945.20 F	*850.68 F
56	1		*HEAD LAMP RH (DISC 10%)	Cracked	945.20 F	*850.68 F
57	1		*TAIL LAMP RH (DISC 10%)	Crumpled	557.80 F	*502.02 F
58	1		*LENS & BODY ,FR TURN RH (DISC 10%)	Crumpled	511.80 F	*460.62 F
59	1		*FOG LAMP RH (DISC 10%)	Cracked	295.20 F	*265.68 F
60	1		*FOG LAMP LH (DISC 10%)	Cracked	280.10 F	*252.09 F
61	1		*NUMBER PLATE (SN)	Dented	15.00 F	*15.00 F
62	1		*NUMBER PLATE FRANE (SN)	Cracked	12.00 F	*12.00 F
63	1		*COOLANT (SN)	Necessary	12.32 F	*12.32 F
64	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
65	1		*SENSOR REVERSE (SN)	Shorted	180.00 F	*180.00 F
66	1		*NUMBER PLATE FRAME (SN)	Crumpled	12.00 F	*12.00 F
67	1		*NUMBER PLATE (SN)	Dented	15.00 F	*15.00 F
68	1		*TAILGATE DOOR GLASS	Serviceable	1,090.90 F	*- F
69	1		*TAILGATE LOWER WINDOW GLASS	Serviceable	721.30 F	*- F
70	1		*WIRE BACK DOR ,NO.1	Serviceable	582.40 F	*- F
71	2		*TAILGATE DOOR HINGE LH/RH	Serviceable	58.30 F	*- F
72	1		*TAILGATE TRIM ,LH	Serviceable	85.90 F	*- F
73	1		*TAILGATE TRIM ,RH	Serviceable	88.30 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
74	1		*TAILGATE TRIM LOWER	Serviceable	180.70 F	*- F
75	1		*TAILGATE TRIM UPPER	Serviceable	49.60 F	*- F
76	1		*TAILGATE BOARD ASSY	Serviceable	246.90 F	*- F
77	1		*TAILGATE OUTSIDE GARNISH	Serviceable	504.90 F	*- F
78	1		*EMBLEM REAR	Serviceable	60.30 F	*- F
79	1		*NAME PLATE (PRUIS)	Serviceable	60.80 F	*- F
80	1		*NAME PLATE (TOYOTA)	Serviceable	51.90 F	*- F
81	1		*SMRT LOGO	Serviceable	7.80 F	*- F
82	1		*STICKER DECAL 65558888	Serviceable	21.60 F	*- F
83	1		*SPOILER REAR	Serviceable	953.70 F	*- F
84	1		*3RD BRAKE LAMP	Serviceable	231.30 F	*- F
85	1		*MOULDING BODY LH	Serviceable	673.60 F	*- F
86	1		*HOOD HINGE LH	Serviceable	55.90 F	*- F
87	1		*HOOD HINGE RH	Serviceable	55.90 F	*- F
88	1		*HORN ASSY ,HIGH	Serviceable	110.40 F	*- F
89	1		*HORN ASSY ,LOW	Serviceable	110.40 F	*- F
90	1		*SUPPORT SUB-ASSY	Serviceable	1,460.40 F	*- F
91	1		*WIPER WASHER INLET	Serviceable	36.90 F	*- F
92	1		*WIPER WASHER JAR	Serviceable	180.10 F	*- F
93	1		*MOTOR NO.1 ,WIPER WASHER JAR	Serviceable	239.00 F	*- F
94	1		*MOTOR NO.2 WIPER WASHER JAR	Serviceable	240.00 F	*- F
95	1		*TUBE & ACCESSORY	Serviceable	631.90 F	*- F
96	1		*HOSE SUB-ASSY DISCHARGE	Serviceable	386.90 F	*- F
97	1		*A/C CONDENSER	Serviceable	1,181.90 F	*- F
98	1		*HOSE SUB-ASSY SUCTION	Serviceable	405.40 F	*- F
99	1		*RADIATOR ASSY UPPER	Serviceable	679.60 F	*- F
100	1		*HOSE INVERTER NO.1	Serviceable	80.00 F	*- F
101	1		*HOSE INVERTER COOLING NO.5	Serviceable	125.30 F	*- F
102	1		*INVERTER BRACKET TRAY	Serviceable	251.60 F	*- F
103	1		*INVERTER RADIATOR CUSHION	Serviceable	5.40 F	*- F
104	1		*INVERTER W CONVERTER	Serviceable	5,390.20 F	*- F
105	1		*RADIATOR ASSY	Serviceable	1,496.90 F	*- F
106	1		*CUSHION ,RADIATOR	Serviceable	11.30 F	*- F
107	1		*SUPPORT RADIATOR LH	Serviceable	17.70 F	*- F
108	1		*SUPPORT RADIATOR RH	Serviceable	54.50 F	*- F
109	1		*SUPPORT ,RADIATOR	Serviceable	18.50 F	*- F
110	1		*RADIATOR LOWER SUPPORT	Serviceable	876.30 F	*- F
111	1		*RADIATOR HOSE LOWER	Serviceable	42.40 F	*- F
112	1		*RADIATOR TOP HOSE NO 1	Serviceable	42.40 F	*- F
113	1		*RADIATOR HOSE BYPASS NO.1	Serviceable	37.20 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
114	1		*RADIATOR HOSE BYPASS NO.2	Serviceable	29.00 F	*- F
115	1		*RADIATOR HOSE BYPASS NO.3	Serviceable	37.20 F	*- F
116	1		*RADIATOR HOSE BYPASS NO.4	Serviceable	37.20 F	*- F
117	1		*COOLANT RESERVE TANK	Serviceable	395.30 F	*- F
118	1		*FAN SHROUD	Serviceable	244.50 F	*- F
119	1		*FAN SHROUD TOP	Serviceable	99.60 F	*- F
120	1		*FAN BLADE	Serviceable	158.60 F	*- F
121	1		*FAN BLADE NO.2	Serviceable	204.20 F	*- F
122	1		*FAN BLADE NO.1	Serviceable	538.30 F	*- F
123	1		*FAN MOTOR NO.2	Serviceable	538.30 F	*- F
124	1		*INLET ASSY ,AIR	Serviceable	232.50 F	*- F
125	1		*AIR CLEANER ASSY	Serviceable	929.90 F	*- F
126	1		*WIRE ,ENGINE ROOM	Serviceable	5,567.10 F	*- F
127	1		*FENDER FRT/RH	Serviceable	723.40 F	*- F
128	1		*NAME PLATE (HYBRID)	Serviceable	51.90 F	*- F
129	1		*FENDER LINER FRT/RH	Serviceable	171.70 F	*- F
130	1		*FENDER LINER PAD ,FR WHEEL RH	Serviceable	49.30 F	*- F
131	1		*FENDER FRT/LH	Serviceable	723.40 F	*- F
132	1		*NAME PLATE (HYBRID)	Serviceable	51.90 F	*- F
133	1		*FENDER LINER FRT/LH	Serviceable	171.70 F	*- F
134	1		*FENDER LINER PAD ,FR WHEE, LH	Serviceable	49.30 F	*- F
135	1		*BUMPER REINFORCEMENT REAR	Serviceable	205.70 F	*- F
136	1		*ARM SUB-ASSY ,R BUMPER RH	Serviceable	139.60 F	*- F
137	1		*ARM SUB-ASSY ,R BUMPER LH	Serviceable	139.60 F	*- F
138	1		*ANTENNA ,ELECTRICAL LOWER REAR	Serviceable	157.40 F	*- F
139	1		*BUMPER SEAL ,RR LH	Serviceable	88.90 F	*- F
140	1		*BUMPER SEAL ,RR RH	Serviceable	65.70 F	*- F
141	1		*BUMPER LIP COVER RR/LH	Serviceable	72.20 F	*- F
142	1		*UNDER COVER SUB-ASSY RR FLOOR	Serviceable	514.50 F	*- F
143	1		*UNDER COVER RR SHIELD	Serviceable	63.90 F	*- F
144	1		*END PANEL	Serviceable	602.10 F	*- F
145	1		*END PANEL COVER ,DECK TRIM HOLE	Serviceable	46.10 F	*- F
146	1		*END PANEL COVER ,DECK TRIM RR	Serviceable	121.10 F	*- F
147	1		*SEALANT SIKAFLEX	Serviceable	37.00 F	*- F
148	1		*BOX ,DECK FLOOR RR	Serviceable	649.70 F	*- F
149	1		*BOX ,RR FLOOR ,BOARD	Serviceable	679.60 F	*- F
150	1		*BOARD ,RR FLOOR	Serviceable	392.30 F	*- F
151	1		*WIRE ENGINE NO.3	Serviceable	74.00 F	*- F
152	1		*WIRE FLOOR NO.2	Serviceable	1,305.40 F	*- F
153	1		*BATTERY	Serviceable	278.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
154	1		*EXHAUST HEAT SHIELD REAR	Serviceable	107.40 F	*- F
155	1		*EXHAUST TAIL PIPE	Serviceable	656.20 F	*- F
156	1		*SUPPORT EXHAUST REAR	Serviceable	33.60 F	*- F
157	1		*DOOR RR/LH	Serviceable	954.50 F	*- F
158	1		*FENDER RR/RH	Serviceable	766.80 F	*- F
159	1		*SMRT LOGO	Serviceable	7.80 F	*- F
160	1		*STICKER DECAL 65558888	Serviceable	21.60 F	*- F
161	1		*TROUGH ,BACK DOOR	Serviceable	110.90 F	*- F
162	1		*TAIL LAMP BRACKET RH	Serviceable	30.70 F	*- F
163	1		*FENDER RR/LH	Serviceable	766.80 F	*- F
164	1		*SMRT LOGO	Serviceable	7.80 F	*- F
165	1		*STICKER DECAL 6555 8888	Serviceable	21.60 F	*- F
166	1		*FENDER LINER R/LH	Serviceable	141.30 F	*- F
167	1		*TROUGH BACK DOOR LH	Serviceable	110.90 F	*- F
168	1		*TAIL LAMP BRACKET ,LH	Serviceable	30.70 F	*- F
169	1		*TAIL LAMP LH	Serviceable	548.40 F	*- F
170	1		*TYRE	Serviceable	126.74 F	*- F
171	1		*WHEEL DISC	Serviceable	1,484.20 F	*- F
172	1		*WHEEL HUB REAR	Serviceable	489.40 F	*- F
173	1		*DEFLECTOR RADIATOR RH	Serviceable	83.50 F	*- F
174	1		*DEFLECTOR RADIATOR LH	Serviceable	77.00 F	*- F
175	1		*WIRE ENGINE ROOM ,NO.3	Serviceable	242.00 F	*- F
176	1		*THERMISTOR ASSY	Serviceable	107.00 F	*- F
177	1		*FOG LAMP RH	Serviceable	295.20 F	*- F
178	1		*FOG LAMP LH	Serviceable	280.10 F	*- F
179	1		*BRACKET ,FR TURN UPPER RH	Serviceable	24.40 F	*- F
180	1		*BRACKET ,FR TURN LOWER RH	Serviceable	26.00 F	*- F
181	1		*BRAKET ,FR TURN	Serviceable	58.20 F	*- F
182	1		*LENS & BODY ,FR TURN LH	Serviceable	511.80 F	*- F
183	1		*BRAKET ,FR TURN UPPER LH	Serviceable	24.40 F	*- F
184	1		*BRAKET ,FR TURN CENTER LH	Serviceable	58.20 F	*- F
185	1		*BRAKET ,FR TURN LOWER LH	Serviceable	26.00 F	*- F
186	1		*COVER ,RADIATOR	Serviceable	122.80 F	*- F
187	1		*GRILLE RADIATOR	Serviceable	310.60 F	*- F
188	1		*GRILLE RADIATOR LOWER NO.2	Serviceable	94.60 F	*- F
189	1		*BUMPER FRT ABSORBER LOWER	Serviceable	127.70 F	*- F
190	1		*UNDER COVER CENTER	Serviceable	448.30 F	*- F
191	1		*UNDER COVER SIDE RH	Serviceable	46.10 F	*- F
192	1		*SPARE TYRE PANEL	Repair	667.70 F	*- F

F=Franchise part.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (S\$)	64,628.96	14,158.25
					- Add. Disc. on L,N Items 0.00/20.00% (S\$)	0.00	2,831.65
					Total Parts (S\$)	64,628.96	11,326.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	2,590.00	1,650.00
2	SPRAY PAINT	New	5,720.00	1,400.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
4	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	200.00	60.00
6	TO TRANSFER REAR TAILGATE MECHANISM	New	120.00	60.00
7	TO REMOVE AND REFIX REAR WINDSCREEN	New	120.00	100.00
8	TO REMOVE AND REFIX TAILGATE GLASS	New	120.00	60.00
9	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	40.00
10	TO REMOVE & REFIT EXHAUST	New	120.00	30.00
11	TO REMOVE AND REFIT ENGINE WIRE ROOM	New	200.00	0.00
12	TO REMOVE AND REFIX ENGINE WIRE HARDNESS	New	120.00	0.00
13	TO INSPECT RR LIGHTING MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	New	120.00	0.00
14	TO REPLACE SUNDRY PARTS	New	100.00	0.00
15	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
16	TO WASH AND VACUUM	New	60.00	0.00
17	TOWING CHARGE	New	126.00	90.00
Gross Labour Cost (S\$)			10,156.00	3,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >