

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21003954/ABA3Q2**Date:** 30/09/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0000105_02
Claimant Vehicle No :	SKM8841M	Insured Vehicle No :	GBH5768U
Date of Loss:	24/03/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0001279

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKM8841M	Engine No:	HIDDEN
Make & Model:	HONDA CIVIC, 1.6 (A)	Chassis No:	MRHFC1660HT000304
Reg. Date:	02/05/2018 (Man. Year: 2018)	Odometer:	74608 km
Colour:	Black		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/45 R17	Rear Tyre Size:	235/45 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,966.68	3,373.32	6,593.36	66.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,120.00	2,190.00	1,930.00	46.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,086.68	5,563.32	8,523.36	60.51
Approved Total (Overridden) (S\$)		4,400.00		

	(S\$)	14,086.68	4,400.00	9,686.68	68.76
+ GST 7.00/7.00% (S\$)		986.07	308.00	678.07	68.76
Nett Amount (S\$)		15,072.75	4,708.00	10,364.75	68.76
	Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 26/03/2021

Date Inspected: 30/03/2021

Estimated Period of Repair: 6.0 days

Inspected At:

Cas Garage Pte Ltd (HQ)
No.1, Kaki Bukit Ave 6, #02-22 Autobay
Singapore 417883**Adjuster:** ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 29 Sep 2021)
Parts: 143	HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKM8841M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	785.60 FL	*572.80 FL
2	2		*BOOTLID STOPPERS	Not Necessary	40.00 FL	*- FL
3	1		*BOOTLID OUTER GARNISH	Cracked	298.60 FL	*298.60 FL
4	1		*BOOTLID SMARTKEY ANTENNA	Not Necessary	152.30 FL	*- FL
5	1		*BOOTLID BUZZER	Not Necessary	105.60 FL	*- FL
6	1		*BOOTLID INNER TRIM	Not Necessary	215.60 FL	*- FL
7	1		*BOOTLID EMBLEM H	Necessary	89.70 FL	*38.00 FL
8	1		*BOOTLID EMBLEM CIVIC	Necessary	78.50 FL	*58.00 FL
9	1		*BOOTLID EMBLEM V-TEC	Necessary	73.60 FL	*45.00 FL
10	2		*BOOTLID LAMP	Not Necessary	411.20 FL	*- FL
11	2		*BOOTLID LAMP INNER SEAL	Not Necessary	76.00 FL	*- FL
12	1		*BOOTLID LOCK	Not Necessary	169.50 FL	*- FL
13	1		*BOOTLID LATCH	Not Necessary	46.20 FL	*- FL
14	2		*BOOTLID HINGES	Not Necessary	150.40 FL	*- FL
15	1		*BOOTLID WEATHERSTRIP	Cut	179.20 FL	*179.20 FL
16	1		*REAR BUMPER	Deformed	778.90 FL	*617.20 FL
17	2		*REAR BUMPER RETAINERS	Necessary	104.60 FL	*48.00 FL
18	2		*REAR BUMPER BRACKETS	Not Necessary	91.20 FL	*- FL
19	2		*REAR BUMPER LOWER SIDE GARNISH	Not Necessary	139.40 FL	*- FL
20	2		*REAR BUMPER SIDE REFLECTORS	Not Necessary	119.60 FL	*- FL
21	1		*REAR BUMPER SIDE REFLECTORS COVERS	O/S Cut	197.40 FL	*98.70 FL
22	4		*REAR BUMPER REVERSE SENSOR	Damaged (1 PCS ONLY)	580.00 FL	*145.00 FL
23	4		*REAR BUMPER REVERSE SENSOR HOLDER	Not Necessary	144.00 FL	*- FL
24	1		*REAR BUMPER SENSOR WIRE HARNESS	Not Necessary	252.30 FL	*- FL
25	1		*REAR BUMPER REINFORCEMENT	Dented	305.80 FL	*305.80 FL
26	1		*TAILLAMPS	O/S Cut	885.20 FL	*368.00 FL
27	2		*TAILLAMP INNER SEAL	Necessary	76.40 FL	*20.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	2		*TAILLAMP PANEL	Repair	691.60 FL	*- FL
29	2		*REAR FENDER INNER COWLING	Not Necessary	312.40 FL	*- FL
30	1		*END PANEL	Dented	578.40 FL	*398.00 FL
31	1		*END PANEL TOP GARNISH	Cracked	145.60 FL	*145.60 FL
32	2		*END PANEL STOPPERS	Not Necessary	70.00 FL	*- FL
33	1		*SPARE TYRE PANEL TOP BOARD	Not Necessary	185.90 FL	*- FL
34	1		*SPARE TYRE TOOL SPONGE	Not Necessary	98.50 FL	*- FL
35	1		*REAR SILENCER BOX RH	Repair	750.20 FL	*- FL
36	2		*REAR SILENCER BOX MOUNTING RH	Not Necessary	76.00 FL	*- FL
37	1		*REAR SILENCER HEAT SHIELD RH	Not Necessary	119.80 FL	*- FL
38	1		*REAR BUMPER CENTRE LOWER GARNISH -ACCESSORIES	Cracked	680.00 FS	*500.00 FS
39	1		*REAR NUMBER PLATE W CASING	Not Necessary	50.00 FS	*- FS
40	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
41	1		*SET BOOTLID CLIPS	Not Necessary	30.00 FS	*- FS
42	1		*SET END PANEL GARNISH CLIPS	Necessary	30.00 FS	*20.00 FS
43	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	30.00 FS	*- FS
44	1		*SET REAR FENDER OUTER COWLING CLIPS	Not Necessary	30.00 FS	*- FS
45	2		*TAILLAMP CLIPS	Necessary	60.00 FS	*10.00 FS
46	2		*BOOTLID LAMP CLIPS	Not Necessary	60.00 FS	*- FS
47	2		*END PANEL INSULATOR SEALS	Necessary	16.00 FS	*60.00 FS
48	1		*REAR REVERSE CAMERA	Not Necessary	250.00 FS	*- FS
49	1		*EXHAUST PIPE MUFFLER RH	Cut	83.00 FS	*83.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,924.20	4,040.90
- List Item Discount on L Items 10.00/20.00% (\$)	957.52	667.58
Total Parts (\$)	9,966.68	3,373.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN /REALIGN ACCIDENT AFFECTED PORTION	New	1,500.00	800.00
2	TO RESPRAY ACCIDENT AFFECTED PORTION	New	1,500.00	1,000.00
3	TO TUFF COAT AFFECTED AREAS	New	150.00	60.00
4	TO REMOVE/REFIX REAR INTERIOR UPHOLSTERY	New	120.00	60.00
5	TO CHECK WIRING /WIRE CONNECTOR AND REWIRE /REPAIR	New	100.00	30.00
6	TO REMOVE/REFIX REVERSE SENSORS AND DISTANCE SETTING	New	150.00	50.00
7	TO REMOVE/REFIT/REPLACE REAR REVERSE CAMERA	New	150.00	50.00
8	TO REMOVE/REALIGN/REPLACE EXHAUST PIPE /SILENCER	New	200.00	80.00
9	TO DISMANTLE /TRANSFER /REPAIR BOOTLID COMPONENTS	New	150.00	60.00
10	TO CONDUCT WATER LEAKAGE TESTING	New	100.00	0.00
			Gross Labour Cost (S\$)	4,120.00
				2,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >