

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21003960/GGA3Q2**Date:** 30/03/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900153041
Claimant Vehicle No :	SJK8828A	Insured Vehicle No :	SMN9983B
Date of Loss:	20/03/2021	Nature of Claim:	TP
		Claim No:	6774116634SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJK8828A	Engine No:	27492031716053
Make & Model:	MERCEDES-BENZ E200, 2.0 AVG (A)	Chassis No:	WDD2130422A586309
Reg. Date:	17/04/2019 (Man. Year: 2018)	Odometer:	28684 km
Colour:	Grey		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,949.36	4,743.89	11,205.47	70.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,600.00	990.00	3,610.00	78.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,549.36	5,733.89	14,815.47	72.10
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	20,549.36	4,600.00	15,949.36	77.61
+ GST 7.00/7.00% (S\$)	1,438.46	322.00	1,116.46	77.61
Nett Amount (S\$)	21,987.82	4,922.00	17,065.82	77.61
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	26/03/2021	
Date Inspected:	29/03/2021 Inspected At:	RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	5.0 days	

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,450.00 FL	*1,350.00 FL
2	2		*FRONT BUMPER SIDE BRACKET	Not Necessary	308.00 FL	*- FL
3	1		*FRONT BUMPER TOP RUBBER	Not Necessary	120.00 FL	*- FL
4	1		*FRONT BUMPER SIDE RAIL RH	Not Necessary	85.00 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	639.00 FL	*- FL
6	1		*FRONT BUMPER SPONGE	Not Necessary	345.00 FL	*- FL
7	1		*FRONT BUMPER FOGLAMP COVER RH	Broken	317.00 FL	*108.00 FL
8	2		*FRONT BUMPER SENSOR RH	Damaged	594.00 FL	*215.00 FL
9	1		*HEADLAMP RH	Cracked	3,689.00 FL	*3,250.00 FL
10	1		*HEADLAMP BRACKET RH	Not Necessary	255.40 FL	*- FL
11	1		*FRONT FENDER RH	Not Necessary	1,224.00 FL	*- FL
12	1		*FRONT FENDER INNER SHIELD RH	Torn	354.00 FL	*292.43 FL
13	1		*FRONT ABSORBER RH	Not Necessary	890.00 FL	*- FL
14	1		*FRONT UPPER ARM RH	Not Necessary	900.00 FL	*- FL
15	1		*FRONT LOWER ARM RH	Not Necessary	760.00 FL	*- FL
16	1		*FRONT CONTROL ARM RH	Not Necessary	695.00 FL	*- FL
17	1		*FRONT AJUST ARM RH	Not Necessary	645.00 FL	*- FL
18	1		*FRONT KNUCKLE ARM RH	Not Necessary	1,375.00 FL	*- FL
19	1		*FRONT WHEEL BEARING RH	Not Necessary	600.00 FL	*- FL
20	1		*FRONT ORIGINAL RIM RH	Not Necessary	1,665.00 FL	*- FL
21	1		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
22	1		*FRONT BUMPER LOWER COVER CLIPS	Not Necessary	60.00 FS	*- FS
23	1		*FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*20.00 FS
24	1		*FROTN TYRE RH	Not Necessary	550.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,640.40	5,265.43
- List Item Discount on L Items 10.00/10.00% (\$)	1,691.04	521.54
Total Parts (\$)	15,949.36	4,743.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,200.00	400.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	500.00
3	ADJUST AND FOCUS FRONT AND ADAPTIVE LIGHTING SYSTEM PERFORM HEADLAMP ADJUSTMENT TO POSITION	New	250.00	30.00
4	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA	New	100.00	0.00
5	RESET AND PROGRAMMING EPS VEHICLE STABILITY SYSTEM WITH ON BOARD DIAGNOSTIC COMPUTER	New	600.00	0.00
6	DISAMANTLE AND REPLACE FRONT UNDER CARRIAGE COMPONENTS	New	600.00	0.00
7	WHEEL ALIGNMENT	New	200.00	60.00
8	REPROGRAM AND CODING HEADLAMP	New	650.00	0.00
			Gross Labour Cost (\$)	4,600.00
				990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >