

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18020437/GQF3E2-1

Date: 29/04/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VPCP/18-000756

Claimant Vehicle No : SLV3715T **Insured Vehicle No :** SLC1905A

Date of Loss: 07/11/2018 Nature of Claim: TP Claim No: MSC/V/18-001474

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV3715T**
Make & Model: TOYOTA C-HR HYBRID, 1.8 S (A) Engine No: 2ZR8200461
Reg. Date: 28/12/2017 (Man. Year: 2017) Chassis No: ZYX102077264
Colour: Red Odometer: 42450 km
Engine Capacity: 1797 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R17 Rear Tyre Size: 215/60R17
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 8,399.70 | 3,470.40 | 4,929.30 | 58.68 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,640.00 | 430.00 | 2,210.00 | 83.71 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 11,039.70 | 3,900.40 | 7,139.30 | 64.67 |
| Approved Total (Overridden) (S\$) | | 3,100.00 | | |
| (S\$) | 11,039.70 | 3,100.00 | 7,939.70 | 71.92 |
| + GST 7.00/7.00% (S\$) | 772.78 | 217.00 | 555.78 | 71.92 |
| Nett Amount (S\$) | 11,812.48 | 3,317.00 | 8,495.48 | 71.92 |

INSPECTION

Date of Assignment: 12/11/2018

Date Inspected: 19/11/2018 Inspected At: Sat Motors (HQ)
24 Defu Lane 12
Singapore 539131

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Apr 2021)

Parts: M1-SUV TOYOTA C-HR HYBRID 1.8 S (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLV3715T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------|-------------|------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Damaged | 898.00 F | *898.00 FL |
| 2 | 2 | | *BUMPER BRACKET | Serviceable | 666.40 F | *- FL |
| 3 | 1 | | *FRONT PRE COLLISION MODULE | Faulty | 2,005.00 F | *2,005.00 FL |
| 4 | 1 | | *FRONT LEFT HEADLAMP | Broken | 3,808.30 F | *1,256.80 FL |
| 5 | 1 | | *FRONT REINFORCEMENT | Impacted | 902.00 F | *467.40 FL |
| 6 | 1 | | *CAR PLATE WITH HOLDER | Serviceable | 120.00 F | *- FL |

F=Franchise part. L=ListItemDisc.

| | | |
|---|-----------------|-----------------|
| Sub Total (\$) | 8,399.70 | 4,627.20 |
| - List Item Discount on L Items 0.00/25.00% (\$) | 0.00 | 1,156.80 |
| Total Parts (\$) | 8,399.70 | 3,470.40 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|---------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO APPLY ANTI RUST COAT AND AFFECTED AREAS | New | 60.00 | 0.00 |
| 2 | TO CHECK WIRING | New | 80.00 | 30.00 |
| 3 | WELDING AND CUTTING OF AFFECTED PANELS, INCLUDING CHASSIS ALIGNMENT | New | 800.00 | 0.00 |
| 4 | SPRAY PAINTING FOR FRONT LEFT AFFECTED PARTS | New | 800.00 | 200.00 |
| 5 | TO APPLY WATERPROOFING SEALER ON END PANELS | New | 100.00 | 0.00 |
| 6 | TO FIX & DISMANTLE AND REMOVE DAMAGED PARTS AND AFFECTED FRONT LEFT AFFECTED DAMAGED PORTION | New | 800.00 | 200.00 |
| | | | Gross Labour Cost (\$\$) | 430.00 |
| | | | 2,640.00 | 2,640.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >