



ALLIN AUTOMOTIVE APPRAISERS
Block 805D, Keat Hong Close. #13-88 Singapore 684805

DZULKIFLEE BIN ABDUL HALIK
c/o Auto Mega Mall Pte Ltd
24, Defu Lane 12
Singapore 539131

Report No : ALLIN-11-0270

Date : 17.11.2018

Reference

Requested by : Workshop, owner's behalf
Date of Request : 1711/2018
Date of Accident : 7/11/2018
Date of Inspection : 17/11/2018
Inspected at : Auto Mega Mall Pte Ltd
24, Defu Lane 12
Singapore 539131

Vehicle Details

Vehicle No.	: SLV3715T	Make & Model	: TOYOTA CHR
Year Make	: 2017	Colour	: RED
Engine No.	: 2ZR8200461	Chassis No.	: ZYX102077264
Engine Capacity	: 1,797cc	Mileage	:
Air-Con	: YES	Radio/CD/Cassette	: YES
Seat Belt	: YES	Rims	: SPORT

General Condition of Vehicle

General Condition	: GOOD	Modification	: NIL
Brakes	: SERVICEABLE	Handbrake	: SERVICEABLE
Steering	: SERVICEABLE		

<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Rim</u>	<u>Tread Balance</u>
Front Right	DUNLOP	215/60/R17	SPORT	70%
Front Left	DUNLOP	215/60/R17	SPORT	70%
Rear Right	DUNLOP	215/60/R17	SPORT	70%
Rear Left	DUNLOP	215/60/R17	SPORT	70%

Assessment

	<u>Repairer's Estimate</u>	<u>Recommendation</u>
Spare Parts	: \$ 8,399.70	\$ 6,719.76
Labour Charges	: \$ 1,840.00	\$ 1472.00
Paint Work	: \$ 800.00	\$ 640.00
Towing Charges	: \$	
Total	: \$ 11,039.70	\$ 8,831.76

Recommend Lum Sum Repairs : \$ 8,800.00
Reduction : \$ 2,239.70

Estimated Period Required for Repair : 12 Days



ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No: SLV3715T
Chassis No: ZYX102077264
Engine No: 2ZR8200461

Report No : ALLIN-11-0270
Date : 17.11.2018

Replacement of Damaged Parts

S/No.	Quantity	Description	Condition / Remarks	Repairer's Estimates	My Recommendation
1	1	Front Bumper	Damaged	\$ 898.00	\$ 718.40
2	2	Bumper Bracket	Necessary	\$ 666.40	\$ 533.12
3	1	Front Pre collision Module	Faulty	\$ 2,005.00	\$ 1,604.00
4	1	Front left Headlamp	Broken	\$ 3,808.30	\$ 3,046.64
5	1	Front Reinforcement	Impacted	\$ 902.00	\$ 721.60
6	1	Car Plate with Holder	Necessary	\$ 120.00	\$ 96.00
				\$ 8,399.70	\$ 6,719.76

Total (Parts): \$ 8,399.70 Less 20% \$ 6,719.76

Labour Charges

7	To fix & dismantle and remove damaged parts and affected Front Left affected damaged portion.	\$ 800.00	\$ 640.00
8	To apply anti rust coat and affected areas	\$ 60.00	\$ 48.00
9	To check wiring	\$ 80.00	\$ 64.00
10	Welding and cutting of affected panels, including chassis alignment.	\$ 800.00	\$ 640.00
11	Spray painting for Front Left affected parts.	\$ 800.00	\$ 640.00
12	To apply waterproofing sealer on end panels	\$ 100.00	\$ 80.00
		Total Labour: \$ 2,640.00	Less 20% \$ 2,112.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$11,039.70 \$ 8,831.76

3900.4
- 20%: 780.08
4 Days.



ALLIN AUTOMOTIVE APPRAISERS
Block 805D, Keat Hong Close. #13-88 Singapore 684805

Vehicle No: SLV3715T

Report No.: ALLIN-11-0270

Point of Impact

Recommendation

The vehicle was inspected thoroughly based on the repairer's estimate against the actual damages found on the vehicle. My findings and recommendation are listed as per attached.

My adjusted amount for the cost of repair is \$8,800.00

Conclusion

The repairer has agreed to undertake repairs at a lump sum of \$8,800.00 corresponding to labour charges, spray painting and replacement of parts.

SURVEYED WITHOUT PREJUDICE



Appraiser Name:
Lim Chang Liang