



ALLIN AUTOMOTIVE APPRAISERS

Block 805D, Keat Hong Close. #13-88 Singapore 684805

Vehicle No: SLV3715T

Report No.: ALLIN-11-0270

Point of Impact

Recommendation

The vehicle was inspected thoroughly based on the repairer's estimate against the actual damages found on the vehicle. My findings and recommendation are listed as per attached.

My adjusted amount for the cost of repair is \$8,800.00

Conclusion

The repairer has agreed to undertake repairs at a lump sum of \$8,800.00 corresponding to labour charges, spray painting and replacement of parts.

SURVEYED WITHOUT PREJUDICE




Appraiser Name:
Lim Chang Liang



ALLIN AUTOMOTIVE APPRAISERS


Block 805D, Keat Hong Close. #13-88 Singapore 684805





ALLIN AUTOMOTIVE APPRAISERS


Block 805D, Keat Hong Close. #13-88 Singapore 684805





ALLIN AUTOMOTIVE APPRAISERS

Block 805D, Keat Hong Close. #13-88 Singapore 684805





ALLIN AUTOMOTIVE APPRAISERS

Block 805D, Keat Hong Close. #13-88 Singapore 684805





ALLIN AUTOMOTIVE APPRAISERS
Block 805D, Keat Hong Close. #13-88 Singapore 684805

