8/27/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG21003962/KGS3Q2

Date:

27/08/2021

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

1800137967-03

Claimant Vehicle No:

SKC3503A 25/03/2021 Insured Vehicle No:

Nature of Claim:

GZ9949J ΤP

Claim No:

9265350088SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKC3503A

Make & Model: MAZDA 3, 1.5 HATCHBACK L SP.6EAT (A)

Engine No: P520272789 Chassis No: JM6BM44A8G0307275

12/06/2015 (Man. Year: 2015) Reg. Date:

Odometer:

61006 km

Colour: Metallic Dark Blue

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification: Yes

Yes No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

205/60 R16

Rear Tyre Size: Rear Left Side:

205/60 R16

Front Left Side: Front Right Side: Yokohama 9 mm Yokohama 9 mm

Rear Right Side:

Yokohama 9 mm Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		2,572.40	960.80	1,611.60	62.65
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,780.00	530.00	1,250.00	70.22
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	4,352.40	1,490.80	2,861.60	65.75
	Approved Total (Overridden) (S\$)		1,200.00		

(S\$)	4,352.40	1,200.00	3,152.40	72.43
+ GST 7.00/7.00% (S\$)	304.67	84.00	220.67	72.43
Nett Amount (S\$)	4,657.07	1,284.00	3,373.07	72.43
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Do	oc/Search Fee (S\$)	2.00		
	Nett Liability (S\$)	1,436.00		

INSPECTION

Date of Assignment: 26/03/2021

Kgc Workshop Pte Ltd (AMK) Date Inspected: Inspected At: 14 Ang Mo Kio Street 63, Blk B 02/06/2021

Singapore 569116

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other circumstances is hereby expressly

REPAIR DETAILS

Recommended Parts

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*FRONT DOOR RHS	Bent	1,201.00 FL	*1,201.00 FL
2	1	*FRONT DOOR WEATHER STRIP RHS	Serviceable	125.80 FL	*-FL
3	1	*FRONT DOOR WINDOW REGULATOR RHS	Serviceable	225.30 FL	*-FL
4	1	*FRONT DOOR -APPLIQUE RHS	Serviceable	72.50 FL	*- FL
5	1	*FRONT DOOR MOULDING RHS	Serviceable	80.40 FL	*- FL
6	1	*FRONT DOOR INNER TRIM BOARD RHS	Serviceable	889.80 FL	*- FL
7	1	*FRONT FENDER RHS	Repair	558.20 FL	*- FL
8	1	*SET LHS FRONT INNER TRIM BOARD CLIP	Not Necessary	50.00 FS	*-FS
F=Fr	anchise part. S=SpcNett.	L=ListItemDisc.			
			Sub Total (S\$)	3,203.00	1,201.00
			- List Item Discount on L Items 20.00/20.00% (S\$)	630.60	240.20
			Total Parts (S\$)	2,572.40	960.80

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISMANTLE ,REPLACE ,CUT WELD KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PART, INCLUSIVE OF REPLACEMENT PARTS	ΓS New	800.00	200.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS	New	600.00	220.00
3	TO CHECK WIRING SYSTEM TO FACILITATE REPAIR AND REFIT THE SAME	New	100.00	20.00
4	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	80.00	30.00
5	TRANSFER DOOR MECHANISM	New	150.00	60.00
6	TO CONDUCT WATER PROOF TEST	New	50.00	0.00
	Gross Labour Cost (S\$)		1,780.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >