

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJB 6002B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET (CONSISTENT)	BUCKLED	1,150.30	685.00
1	BONNET LOCK (CONSISTENT)	NOT NECESSARY	320.00	-
1	FRONT BUMPER (CONSISTENT)	DEFORMED	1,055.60	688.00
2	FRONT BUMPER SIDE RETAINER @\$84.60 (CONSISTENT)	NECESSARY	169.20	70.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	BENT	430.00	272.00
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	CRACKED	288.90	123.00
2	HEADLAMP @\$758.30 (CONSISTENT)	CRACKED	1,516.60	1,516.60
2	HEAD LAMP LOWER BRACKET @\$95.00 (CONSISTENT)	NOT NECESSARY	190.00	-
2	FRONT FENDER @\$933.50 (CONSISTENT)	TO REPAIR SEE LABOUR	1,867.00	-
1	SUPPORT PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	830.50	-
1	SUPPORT PANEL TOP COVER (CONSISTENT)	DEFORMED	211.30	211.30
1	AIR-CON CONDENSOR (CONSISTENT)	NOT NECESSARY	895.30	-
1	RADIATOR (CONSISTENT)	NOT NECESSARY	1,355.60	-
1	TAILGATE (CONSISTENT)	DISTORTED	1,455.30	903.00
1	TAILGATE INNER LOCK (CONSISTENT)	DAMAGED	360.20	189.00
1	TAILGATE WEATHER STRIP (CONSISTENT)	CUT	211.30	211.30
1	TAILGATE INNER BOARD (CONSISTENT)	CRACKED	488.90	285.00
1	TAILGATE OUTER GARNISH (CONSISTENT)	CRACKED	376.60	249.00
1	TAILGATE WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	190.60	190.60
1	REAR BUMPER TOWING COVER (CONSISTENT)	DEFORMED	60.00	60.00
2	REAR BUMPER SIDE RETAINER @\$42.30 (CONSISTENT)	NECESSARY	84.60	84.60
2	TAILLAMP @\$488.70 (CONSISTENT)	CRACKED	977.40	736.00
2	REAR FENDER INNER TRIM @\$633.50 (CONSISTENT)	CRACKED	1,267.00	594.00
1	REAR END PANEL (CONSISTENT)	DENTED	663.50	545.00
1	REAR END PANEL BOTTOM (CENTRE)	DENTED	340.40	186.00
1	REAR END PANEL TOP GARNISH (CONSISTENT)	DEFORMED	244.30	175.00
1	REAR SPARE TYRE BRACKET (CONSISTENT)	NOT NECESSARY	398.30	-
	LESS 20% DISCOUNT		-3,479.74	-1,594.88
			13,918.96	6,379.52

Report Ref No. CC4/ASM21003968/Aga3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	CUT	50.00	50.00
1	SET FRONT BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	SET FRONT BUMPER LOWER GRILLE CLIPS (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	CENTRE GRILLE (SN) (CONSISTENT)	CRACKED	850.00	400.00
1	SET CENTRE GRILLE CLIP (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	SET HEADLAMP CLIP (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
2	FRONT FENDER INNER PROTECTOR @\$220.00 (SN) (CONSISTENT)	TORN	440.00	380.00
1	AIR-CON FAN ASSY (SN) (CONSISTENT)	CRACKED	850.00	350.00
1	RADIATOR COOLANT (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
1	REAR NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	SET TAILGATE INNER BOARD CLIP (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	TAILGATE WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	100.00	60.00
1	REAR BUMPER (SN) (CONSISTENT)	DEFORMED	1,200.00	800.00
1	REAR BUMPER DIFFUSER (SN) (CONSISTENT)	DISTORTED	1,000.00	700.00
1	SET REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	SET REAR FENDER INNER TRIM CLIP (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	SET TAILLAMP CLIP (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	SET REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	REAR END PANEL INSULATION SEAL (SN) (CONSISTENT)	NECESSARY	80.00	60.00
1	REVERSE SENSOR (SN) (CONSISTENT)	DAMAGED	220.00	200.00
			5,090.00	3,130.00
	<u>LABOUR</u>			
	TO PANEL BEAT ,REMOVE AND REPLACE PARTS .INCLUSIVE OF THE REPAIR OF FRONT FENDER AND SUPPORT PANEL.		1,200.00	600.00
	TO SPRAY PAINT AFFECTED AREA.		1,200.00	800.00
	TUFF COAT.		250.00	40.00
	WIRING AND BULB CHECKING .		80.00	30.00
	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.	NOT NECESSARY	100.00	-

Report Ref No. CC4/ASM21003968/Aga3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

10,000.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL GAS.	NOT NECESSARY	120.00	-
	TO PANEL BEAT ,REMOVE AND REPLACE PARTS.		2,000.00	1,000.00
	TO SPRAY PAINT AFFECTED AREA.		2,000.00	1,000.00
	TUFF COAT.		250.00	80.00
	WIRING AND BULB CHECK.		180.00	30.00
	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR.		150.00	80.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		150.00	50.00
	REMOVE AND REFIX REVERSE CAMERA.		220.00	50.00
	REMOVE AND REFIX TAILGATE WINDSCREEN .		140.00	120.00
	TRANSFER TAILGATE MECHANISM .		120.00	80.00
			8,160.00	3,960.00
	GRAND TOTAL		27,168.96	13,469.52

Report Ref No. CC4/ASM21003968/Aga3q2

**RECOMMENDED COST OF LUMP SUM REPAIRS** 

(TO ITS PRE-ACCIDENT CONDITION)



**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.