

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21003980/R1QF3E2

Date: 12/04/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900161216		
Claimant Vehicle No :	SLT3867Z	Insured Vehicle No :	SMP1343R		
Date of Loss:	25/03/2021	Nature of Claim:	TP	Claim No:	2528461147SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT3867Z	Engine No:	1ZR1994447
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 ECO (A)	Chassis No:	MR053REH604572048
Reg. Date:	27/10/2017 (Man. Year: 2017)	Odometer:	50511 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	29/03/2021	Eco Automobile Claims & Repair Pte Ltd - Bartley Biz Center (HQ)
Date Inspected:	29/03/2021 Inspected At:	15 KAKI BUKIT ROAD 4, #01-53 BARTLEY BIZ CENTER
Estimated Period of Repair:	12.0 days	Singapore 417808

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*REAR BUMPER SIDE RETAINER	Necessary	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
5	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
6	1		*REAR END PANEL	Bent	0.00 F	*- F
7	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
8	1		*REAR LH TAILLAMP	Scratched	0.00 F	*- F
9	1		*REAR RH TAILLAMP	Scratched	0.00 F	*- F
10	1		*BOOTLID	Bent	0.00 F	*- F
11	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
12	1		*BOOTLID LOCK	Bent	0.00 F	*- F
13	1		*BOOTLID RUBBER	Necessary	0.00 F	*- F
14	1		*SPARE TYRE BOARD	Deformed	0.00 F	*- F
15	1		*REAR LH FENDER	Buckled	0.00 F	*- F
16	1		*REAR RH FENDER	Buckled	0.00 F	*- F
17	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
18	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00 0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >