

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG21003984/AVF3E2

Date: 16/08/2021

REFERENCE

Insured/Claimant:	LIM SIEW HWA	Policy No:	2100443165		
Date of Loss:	02/02/2021	Nature of Claim:	OD	Claim No:	3687978072SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX5508M		
Make & Model:	AUDI A3, 1.4 TFSI (A)	Engine No:	CZC501632
Reg. Date:	17/12/2015 (Man. Year: 2015)	Chassis No:	WAUZZZ8V7GA067472
Colour:	Black	Odometer:	31072 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$65,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,621.00	6,941.68	7,679.32	52.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,942.00	6,462.00	3,480.00	35.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,563.00	13,403.68	11,159.32	45.43
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	23,563.00	12,403.68	11,159.32	47.36
+ GST 7.00/7.00% (S\$)	1,649.41	868.26	781.15	47.36
Nett Amount (S\$)	25,212.41	13,271.94	11,940.47	47.36

INSPECTION

Date of Assignment:	29/03/2021		
Date Inspected:	24/02/2021	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	8.0 days		

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,016.00 FS	*1,612.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	1		*FRONT BUMPER COVER LOWER CENTRE	Not Necessary	156.00 FS	*- FS
4	4		*FRONT BUMPER LOWER PULL STRAP	Not Necessary	206.00 FS	*- FS
5	1		*FRONT BUMPER GUIDE SECTION LH	Not Necessary	63.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE	Cracked	109.00 FS	*87.20 FS
7	1		*RADIATOR GRILLE	Not Necessary	691.00 FS	*- FS
8	1		*RADIATOR GRILLE COVER	Not Necessary	98.00 FS	*- FS
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	795.00 FS	*- FS
10	1		*FRONT BUMPER IMPACT ABSORBER	Not Necessary	83.00 FS	*- FS
11	1		*FRONT SUPPORT PANEL TOP COVER	Not Necessary	56.00 FS	*- FS
12	1		*FRONT FENDER LH	Dented	851.00 FS	*680.40 FS
13	1		*FRONT FENDER ATTACHMENT PARTS LH	Not Necessary	72.00 FS	*- FS
14	1		*FRONT FENDER TOP BRACKET LH - REAR	Bent	28.00 FS	*21.84 FS
15	1		*FRONT FENDER TOP BRACKET LH - FRONT	Bent	48.00 FS	*37.68 FS
16	1		*FRONT FENDER BRACE LH	Bent	96.00 FS	*76.48 FS
17	1		*FRONT FENDER LOWER BRACKET LH	Bent	62.00 FS	*48.88 FS
18	1		*FRONT WHEEL HOUSING LINER LH	Not Necessary	169.00 FS	*- FS
19	1		*FRONT WHEEL HOUSING LINER ATTACHMENTS PARTS LH	Not Necessary	89.00 FS	*- FS
20	1		*BONNET	Dented	2,745.00 FS	*2,196.00 FS
21	1		*BONNET ATTACHMENT PARTS	Not Necessary	165.00 FS	*- FS
22	1		*BONNET EDGE PROTECTION SEAL - FRONT	Necessary	28.00 FS	*22.00 FS
23	1		*BONNET STRIKER	Not Necessary	110.00 FS	*- FS
24	1		*BONNET LOCK W/MICRO SWITCH	Not Necessary	214.00 FS	*- FS
25	1		*HEADLIGHT LH	Cracked	2,641.00 FS	*2,112.80 FS
26	1		*HEADLIGHT WASHER LIFT CYLINDER LH	Not Necessary	193.00 FS	*- FS
27	1		*WING MIRROR MOUNTING LH	Not Necessary	1,024.00 FS	*- FS
28	1		*FRONT ALUMINIUM RIM LH	Not Necessary	1,166.00 FS	*- FS
29	1		*SUNDRIES	Necessary	400.00 FS	*45.60 FS
30	1		*FRONT NO. PLATE	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 14,621.00 6,941.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	360.00	360.00
2	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL / RENEW LHS WING MIRROR ASSY	New	280.00	280.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO REPAIR LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,150.00	2,000.00
4	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS FRONT DOOR, LHS WING MIRROR COVER, DOOR HANDLES, LHS REAR DOOR AND LHS REAR FENDER	New	5,400.00	3,350.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			9,942.00	6,462.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >