

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21003984/AVF3E2**Date:** 17/08/2021**REFERENCE**

Insured/Claimant: LIM SIEW HWA Policy No: 2100443165  
Date of Loss: 02/02/2021 Nature of Claim: OD Claim No: 3687978072SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SKX5508M**  
Make & Model: AUDI A3, 1.4 TFSI (A) Engine No: CZC501632  
Reg. Date: 17/12/2015 (Man. Year: 2015) Chassis No: WAUZZZ8V7GA067472  
Colour: Black Odometer: 31072 km  
Engine Capacity: 1395 cc  
Market Value/New Car Price: S\$65,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	14,621.00	6,941.68	7,679.32	52.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,942.00	6,462.00	3,480.00	35.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>24,563.00</b>	<b>13,403.68</b>	<b>11,159.32</b>	<b>45.43</b>
<b>- Excess (S\$)</b>	1,000.00	1,000.00	0.00	0.00
<b>(S\$)</b>	23,563.00	12,403.68	11,159.32	47.36
<b>+ GST 7.00/7.00% (S\$)</b>	1,649.41	868.26	781.15	47.36
<b>Nett Amount (S\$)</b>	<b>25,212.41</b>	<b>13,271.94</b>	<b>11,940.47</b>	<b>47.36</b>

**INSPECTION**

Date of Assignment: 29/03/2021  
Date Inspected: 24/02/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 8.0 days

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,016.00 FS	*1,612.80 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	187.00 FS	*- FS
3	1		*FRONT BUMPER COVER LOWER CENTRE	Not Necessary	156.00 FS	*- FS
4	4		*FRONT BUMPER LOWER PULL STRAP	Not Necessary	206.00 FS	*- FS
5	1		*FRONT BUMPER GUIDE SECTION LH	Not Necessary	63.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE GRILLE	Cracked	109.00 FS	*87.20 FS
7	1		*RADIATOR GRILLE	Not Necessary	691.00 FS	*- FS
8	1		*RADIATOR GRILLE COVER	Not Necessary	98.00 FS	*- FS
9	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	795.00 FS	*- FS
10	1		*FRONT BUMPER IMPACT ABSORBER	Not Necessary	83.00 FS	*- FS
11	1		*FRONT SUPPORT PANEL TOP COVER	Not Necessary	56.00 FS	*- FS
12	1		*FRONT FENDER LH	Dented	851.00 FS	*680.40 FS
13	1		*FRONT FENDER ATTACHMENT PARTS LH	Not Necessary	72.00 FS	*- FS
14	1		*FRONT FENDER TOP BRACKET LH - REAR	Bent	28.00 FS	*21.84 FS
15	1		*FRONT FENDER TOP BRACKET LH - FRONT	Bent	48.00 FS	*37.68 FS
16	1		*FRONT FENDER BRACE LH	Bent	96.00 FS	*76.48 FS
17	1		*FRONT FENDER LOWER BRACKET LH	Bent	62.00 FS	*48.88 FS
18	1		*FRONT WHEEL HOUSING LINER LH	Not Necessary	169.00 FS	*- FS
19	1		*FRONT WHEEL HOUSING LINER ATTACHMENTS PARTS LH	Not Necessary	89.00 FS	*- FS
20	1		*BONNET	Dented	2,745.00 FS	*2,196.00 FS
21	1		*BONNET ATTACHMENT PARTS	Not Necessary	165.00 FS	*- FS
22	1		*BONNET EDGE PROTECTION SEAL - FRONT	Necessary	28.00 FS	*22.00 FS
23	1		*BONNET STRIKER	Not Necessary	110.00 FS	*- FS
24	1		*BONNET LOCK W/MICRO SWITCH	Not Necessary	214.00 FS	*- FS
25	1		*HEADLIGHT LH	Cracked	2,641.00 FS	*2,112.80 FS
26	1		*HEADLIGHT WASHER LIFT CYLINDER LH	Not Necessary	193.00 FS	*- FS
27	1		*WING MIRROR MOUNTING LH	Not Necessary	1,024.00 FS	*- FS
28	1		*FRONT ALUMINIUM RIM LH	Not Necessary	1,166.00 FS	*- FS
29	1		*SUNDRIES	Necessary	400.00 FS	*45.60 FS
30	1		*FRONT NO. PLATE	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 14,621.00 6,941.68**

LKK Auto Consultants Pte Ltd/SKX5508M/17/08/2021 08:09

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	360.00	360.00
2	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL / RENEW LHS WING MIRROR ASSY	New	280.00	280.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO REPAIR LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,150.00	2,000.00
4	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS FRONT DOOR, LHS WING MIRROR COVER, DOOR HANDLES, LHS REAR DOOR AND LHS REAR FENDER	New	5,400.00	3,350.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE	New	280.00	0.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$\$)</b>			<b>9,942.00</b>	<b>6,462.00</b>

LKK Auto Consultants Pte Ltd/SKX5508M/17/08/2021 08:09

< END OF ESTIMATES >