

Messages

Claims



	Summary		
General Details		Workshop Det	tails
nvolving	2016 TPVD TOYOTA DYNA 150 (GBE1239	Total Repate	0
Date of Loss	13 March 2021	Amount	
ime of Loss	10:50	Nett Loss Amoun	nt -\$8,641.00
oss Description	SLX3668K (INSD) -> GBE1239Y (TP) -> SKZ6092C	Assigned Worksh	nop LKK AUTO CONSULTANTS PTE LTD (TP)
Comment		Days of work completion *	20

Messages

Claims



General & Workshop	Details	Vehicle & Drive	er Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	
				Summary				
Vehicle & Driver De	tails							
/ehicle Registration#	GBE12	39Y		Pul	rchase Date	DD/MM/YYYY		Í
Registration State	SING	APORE		Reş	gistration Date *	09/09/2015		Í
1ileage	1725	96		Age	e of Vehicle	5		
CATEGORY	POLICY INF	ORMATION	ASSESSMENT INFORMATIO		ver Details			
Manufacturing Year	2010		2015		CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION	
					Driver Name	SUBRAMANIAN KANNAN		

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Make	MINI	ТОУОТА	Date of Birth	21 May 1984	DD/MM/YYYY
Model	COOPER CABRIOLET	TOYOTA DY	Age	36	
Туре		~	Occupation	Unknown	
Type of Paint			Education Qualification	Other	•
Chassis No	WMWZN32030TZ12382	JTFAT35Y1	Driving Experience	0	
Engine No	A972I803	1KD255483	Driver License #		
Engine Capacity		2982	License Type		•
Sum Insured	0		License Issue Date		DD/MM/YYYY

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value	0	0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		DD/MM/YYYY
Address	Not Entered By User, Singapore	
Address type	Personal Correspondence	•
Gender	Unknown	•
Marital status	Unknown	•
Identification #	GXXXX942L	

Messages

Claims



General & Workshop De	tails Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	
			Summary			
Detailed Assessment		Со	ndition of Vehicle	e at time of surve	ey .	
Inspection Date *	30/03/2021	Ge	neral condition	Fair		•
Total Loss	Yes <b>No</b>	Ste	ering (Serviceable)	Yes	No	
Towing Charges	0		otbrake rviceable)	Yes	No	
Voluntary Excess	0		ndbrake rviceable)	Yes	No	
Compulsory Excess	0	Enį	gine Modification	Yes	No	
Young/Inexperienced/ Unnamed Driver Excess	0	Pre	e-accident condition	Fair		•

0

#### Tyre Condition

Age of Tyres	
Front Tyre Size	195 R15C
Front left side	BRIDGESTONE6mm
Front right side	BRIDGESTONE6mm
Spare wheel	
Rear Tyre Size	195 R15C
Rear left side	BRIDGESTONE6mm
Rear right side	BRIDGESTONE6mm



Messages

Claims



General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneou	s Summary	
Tax Eligibility & Additiona	l Deduction for Parts						
Depr./Bttr%	0		Salvage%		0		
Discount%	25		Settlement	%	100		
			Paint Labour/	Material Ratio			
Paint Labour Ratio	20		Cash Loss		Yes	No	P y
Paint Material Ratio	80						r t S
							u p
							p l i
							e d
							b y

Α

Χ

Α

Save

Messages

Claims



Add		Approve	Deny	Submit All								
EDIT	SR NO	QUAN MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJU AMO
	0	1	REAR TAIL GATE	Dented	0	1217.45	No	0	25	0	0	913.
	0	2	REAR TAIL GATE HINES	Bent	0	145	No	0	25	0	0	217.
	0	1	REAR NO PLATE PANEL	Dented	0	281	No	0	25	0	0	210
	0	1	REAR LH TAIL LAMP ASSY	Cracked	0	289.9	No	0	25	0	0	217.
	0	1	REAR LH TAIL LAMP PANEL	Bent	0	185	No	0	25	0	0	138
	0	1	REAR LH STOPPER BRACKET	Bent	0	78.1	No	0	25	0	0	58.5
	0	1	REAR LH STOPPER	Damaged	0	75.5	No	0	25	0	0	56.6

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR LH STOPPER RUBBER "B"	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR TAILGATE "DYNA" STICKER	Necessary	0	58.2	No	0	25	0	0	43.65
	0	1		REAR END PANEL	Repair	0	0	No	0	0	0	0	0
	0	1		REAR EXHAUST	Bent	0	756	No	0	25	0	0	567
	0	1		REAR SPARE TYRE HOLDER	Bent	0	371.75	No	0	25	0	0	278.81
	0	1		FRONT PANEL	Dented	0	950	No	0	25	0	0	712.5
	0	1		FRONT "DYNA" EMBLEM	Necessary	0	72	No	0	25	0	0	54
	0	1		FRONT LOGO	Necessary	0	71.8	No	0	25	0	0	53.85
	0	1		FRONT GRILLE	Damaged	0	581.9	No	0	25	0	0	436.43
	0	1		FRONT LH HEAD LAMP ASSY	Cracked	0	932.4	No	0	25	0	0	699.3

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		FRONT PANEL GARNISH	Damaged	0	308.9	No	0	25	0	0	231.68
	0	1		FRONT BUMPER	Dented	0	441.6	No	0	25	0	0	331.2
	0	2		R&L FRONT BUMPER BRACKET	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT WINDSCREEN RUBBER	Necessary	0	303.7	No	0	25	0	0	227.78
	0	1		FRONT HEAD LAMP ASSY RH	Cracked	0	932.4	No	0	25	0	0	699.3
	0	1		FRONT AIRCON BLOWER HOUSING	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT AIRCON COIL & HOUSING	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR LH TAIL GATE LOCK (SIDE)	Bent	0	198.35	No	0	25	0	0	148.76
	0	1		FRONT WIPER PANEL COVER	Repair	0	0	No	0	0	0	0	0

	EDIT	SR NO	QUAN MATI	ERIAL PART NAME	CONDITIC	DN	LIST PRICE (WORKSHO		LIST PRIC		SUPPL	EMENTARY	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT
		0	1	FRONT PANEL RH GARNISH	Cracked	I	0		95		No		0	25	0	0
		0	1	REAR TYRE BRACKET MEMBER	Bent		0		380		No		0	25	0	0
		0	1	FRONT CROSS MEMBER	Bent		0		443.32		No		0	25	0	0
Labou	r															
	Add		Approve	Deny	Subm	it All										
	EDIT	SR NO	REPAIR/REPLA	CE PART NAME		ESTIMAT LABOUR AMOUNT		ADJUSTED LABOUR AMOUNT		ESTIMATE PAINT AMOUNT		ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	СОММЕ	NT	REMOVE
		0		TO REMOVE & REFI W/SCREEN	T FRONT	0		120		0		0	Reviewin	g		
		0		TO REMOVE & REP FRONT AIRCON SY: AND TOP UP GAS		0		120		0		0	Reviewin	g		
		0		TO REMOVE & REFI		0		300		0		0	Reviewin	g		
		0		WIRING FEE		0		30		0		0	Reviewin	g		
		0		REAR TAIL GATE IN COVER REMOVE &		0		60		0		0	Reviewin	g		
		0		SPRAY PAINTING D AREA FRONT & REA		0		1200		0		0	Reviewin	g		

ADJUSTED AMOUNT

71.25

285

332.49

E	DIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
		0		TO REPAIR FRONT & REAR ACC DAMAGE PORTION	0	1100	0	0	Reviewing		
		0		REAR EXHAUST REMOVE & REFIT & REPAIR	0	60	0	0	Reviewing		
		0		ANTI RUST	0	40	0	0	Reviewing		

Messages

Claims



### Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Add		Approve		D	eny	Submit Al	l		
EDIT	SR NO	NAME	ACT	TION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	СОММ	IENT	REMOVE
	0	DAYS OF REPAIR : 7 DAYS	Rev	viewing	0	0			
	0	FRONT NO PLATE	Rev	viewing	0	40	CRUI	MPLED	
	0	REAR NO PLATE	Rev	viewing	0	40	CRUI	MPLED	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR "8 PAX" STICKER	Reviewing	0	15	NECESSARY	
	0	REAR "70KM" STICKER	Reviewing	0	15	NECESSARY	
	0	FRONT LH DOOR ADD STICKER	Reviewing	0	25	NECESSARY	
	0	REAR TAILGATE "TOYOTA" STICKER	Reviewing	0	79	NECESSARY	
	0	1 SET FRONT GRILLE CLIP	Reviewing	0	35	NECESSARY	

ED	IT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	· )	0	REAR STEP BOARD	Reviewing	0	380	BENT	
	·	0	1 SET REAR SENSOR	Reviewing	0	220	SHORTED	
0	·	0	AIR BLOWER AIR HOSE	Reviewing	0	185	DEFORMED	
	•	0	FRONT PANEL JOINT SEALANT	Reviewing	0	50	NECESSARY	



Messages

Claims



### Assessment Details

General & Workshop	Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary						
Estimated Claim Amount	\$0.00		Adj	usted Claim Amoun	t \$11,099.73	
CATEGORY		ESTIMATE	ADJUSTED			
Spare Parts						
Labour						
Spare Parts						
Miscellaneous						

Submit for Review



Messages


Claims



#### Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary



Messages

Claims



## Assessment Details

General & Workshop	Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary						
Estimated Claim Amount	\$0.00		Adj	usted Claim Amoun	t \$8,900.00	
CATEGORY		ESTIMATE	ADJUSTED			
Miscellaneous						

Submit for Review