

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21003988/ARA3Q2
Date: 15/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900071480
Claimant Vehicle No :	SJB2167K	Insured Vehicle No :	SKS2649K
Date of Loss:	27/03/2021	Nature of Claim:	TP
		Claim No:	2540925263SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJB2167K		
Make & Model:	HONDA CIVIC, 2.0 L (A)	Engine No:	K20Z23500577
Reg. Date:	04/01/2008 (Man. Year: 2007)	Chassis No:	JHMF26408S200578
Colour:	White	Odometer:	228020 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	668.00	0.00	668.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	400.00	200.00	200.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,068.00	200.00	868.00	81.27
+ GST 7.00/7.00% (S\$)	74.76	14.00	60.76	81.27

Nett Amount (S\$)	1,142.76	214.00	928.76	81.27
+ Loss of Use (2.0 x S\$120.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		461.45		

INSPECTION

Date of Assignment: 03/05/2021

Date Inspected: 03/05/2021

Estimated Period of Repair: 1.0 days

Inspected At:

MG Solution Pte Ltd (HQ)
 23 Kaki Bukit Avenue 4 #02-03B, VICOM Inspection Centre
 Singapore 415933

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	638.00 F	*- F
2	1		*REAR BUMPER CLIPS	Not Necessary	30.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	
					668.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEAING	New	200.00	0.00
2	SPRAY PAINTING	New	200.00	200.00
Gross Labour Cost (S\$)			400.00	200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >