

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|--|---|-----------------|-------|--------------------------|--|
| | AIG ASIA PACIFIC | INSURANCE PTE LTD | F | Ref: | CS3/AIG20011344/Qtf3e2-1 | |
| | 78 SHENTON WAY AIG BUILDING SINGAPORE 0791 | | С | Date: | 09/04/2021 | |
| | ATTN: JEFFREY N | IG | C | Code: | AIG | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SKG 2322R | Veh. Inspected | | SLN 7434U | |
| | Policy No. | 1900141037 | Coverage (\$) | | 0.00 | |
| | Claim No. | 7196211019SG | Excess (\$) | | 0.00 | |
| | Assign From | JEFFREY NG | Assign Date | | 29/03/2021 | |
| 2. | 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | HONDA VEZEL HYBRID | c.c | | 1496 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2017 | |
| | Chassis No. | RU31237000 | Colour | | GOLD | |
| | Odometer | - | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | FAIR | | | | |
| 3. | 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 215/60 R16 | TOYO | | 6 mm | |
| | L/H Front Tyre | 215/60 R16 | TOYO | | 6 mm | |
| | R/H Rear Tyre | 215/60 R16 | TOYO | | 6 mm | |
| | L/H Rear Tyre | 215/60 R16 | TOYO | | 6 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 16/10/2020 | Inspection Date | | 27/10/2020 | |
| | Survey held at | ELITE AUTOMOTIVE | | | | |
| | | 280 WOODLANDS INDUSTRIAL PARK E5 #01-17 HARVEST@WOODLANDS SINGAPORE 757322 | | | | |
| 5a. | Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |
| | ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days | | | | | |
| | | | | | <u> </u> | |