

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21004000/T1TF3E2**Date:** 21/09/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00179042000		
Claimant Vehicle No :	SMM1923H	Insured Vehicle No :	SMT7048H		
Date of Loss:	22/03/2021	Nature of Claim:	TP	Claim No:	SNM21D201661/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM1923H	Engine No:	L13B1456395
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Chassis No:	GK31347396
Reg. Date:	20/06/2019 (Man. Year: 2019)	Odometer:	48432 km
Colour:	Blue		
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	35,449.92	8,729.36	26,720.56	75.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,850.00	2,130.00	4,720.00	68.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	42,299.92	10,859.36	31,440.56	74.33
Approved Total (Overridden) (\$\$)		8,650.00		
(\$\$)	42,299.92	8,650.00	33,649.92	79.55
+ GST 7.00/7.00% (\$\$)	2,960.99	605.50	2,355.49	79.55
Nett Amount (\$\$)	45,260.91	9,255.50	36,005.41	79.55

INSPECTION

Date of Assignment:	29/03/2021		
Date Inspected:	26/03/2021	Inspected At:	56 Loyang Way, #04-04
Estimated Period of Repair:	7.0 days		Repairer: AP Automotive Services Pte Ltd (HQ)

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

THE REPAIRER IS INFORMED ON THE REVISED AMOUNT BUT NOT AGREED WITH OUR RECOMMENDATION.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Sep 2021)
Parts:	143	HONDA FIT 1.3 GF CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMM1923H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET LOCK	Not Necessary	97.50 FL	*- FL
2	2		*SET BONNET HINGE	Not Necessary	116.00 FL	*- FL
3	1		*HEADLAMP LH	Cracked	1,023.40 FL	*762.50 FL
4	1		*HEADLAMP BRACKET LH	Cracked	52.10 FL	*52.10 FL
5	1		*FRONT GRILLE ASSY	Cracked	455.00 FL	*395.00 FL
6	1		*FRONT GRILLE TOP CHROME	Cracked	281.00 FL	*250.00 FL
7	1		*FRONT GRILLE LOWER CHROME	Cracked	230.80 FL	*190.00 FL
8	1		*FRONT BUMPER RETAINER LH	Deformed	27.50 FL	*27.50 FL
9	1		*FRONT BUMPER REINFORCEMENT BAR	Not Necessary	299.90 FL	*- FL
10	1		*FRONT BUMPER BEAM (NPA)	Not Necessary	0.00 FL	*- FL
11	1		*FRONT BUMPER UNDERCOVER	Deformed	158.00 FL	*158.00 FL
12	1		*FRONT FENDER LH	Bent	462.70 FL	*462.70 FL
13	1		*FRONT FENDER QUARTER WINDOW MOULDING LH	Not Necessary	149.00 FL	*- FL
14	1		*FRONT FENDER COWLING LH	Torn	108.80 FL	*108.80 FL
15	1		*FRONT SUPPORT PANEL	Repair	512.00 FL	*- FL
16	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	35.00 FL	*- FL
17	1		*FRONT ABSORBER LH	Bent	254.10 FL	*254.10 FL
18	1		*FRONT LOWER ARM LH	Bent	198.70 FL	*160.20 FL
19	1		*FRONT KNUCKLE ARM LH	Bent	289.60 FL	*230.40 FL
20	1		*FRONT KNUCKLE BEARING LH	Bent	118.00 FL	*118.00 FL
21	1		*FRONT BEARING HUB LH	Not Necessary	145.10 FL	*- FL
22	1		*FRONT DRIVE SHAFT LH	Not Necessary	961.50 FL	*- FL
23	1		*FRONT TIE ROD LH	Bent	132.40 FL	*132.40 FL
24	1		*FRONT TIE ROD END LH	Bent	90.50 FL	*90.50 FL
25	1		*FRONT DOOR LH (NPA)	Repair	0.00 FL	*- FL
26	1		*FRONT DOOR SIDE MIRROR ASSY LH	Distorted	519.50 FL	*519.50 FL
27	1		*FRONT DOOR CHECKER LH	Not Necessary	52.10 FL	*- FL
28	1		*FRONT DOOR WEATHERSTRIP LH	Not Necessary	229.70 FL	*- FL
29	1		*ROCKER PANEL LH (NPA)	Not Necessary	0.00 FL	*- FL
30	1		*BONNET TOP GARNISH	Not Necessary	800.00 FS	*- FS
31	1		*BONNET TOP GARNISH STICKER	Not Necessary	400.00 FS	*- FS
32	1		*FRONT GRILLE LOGO - HONDA	Not Necessary	250.00 FS	*- FS
33	1		*FRONT GRILLE LOWER CHROME STICKER	Necessary	200.00 FS	*60.00 FS
34	1		*FRONT BUMPER	Torn	4,000.00 FS	*1,000.00 FS
35	1		*FRONT BUMPER GRILLE	Not Necessary	600.00 FS	*- FS
36	1		*FRONT BUMPER GARNISH LH	Deformed	250.00 FS	*100.00 FS
37	1		*FRONT BUMPER FOG LAMP LH	Cracked	1,200.00 FS	*150.00 FS
38	1		*FRONT BUMPER FOG LAMP STICKER LH	Not Necessary	150.00 FS	*- FS
39	1		*FRONT BUMPER FOG LAMP GARNISH LH	Cracked	450.00 FS	*200.00 FS
40	1		*FRONT BUMPER LOWER	Cracked	3,500.00 FS	*750.00 FS
41	1		*FRONT BUMPER LOWER RUBBER SEAL	Necessary	250.00 FS	*50.00 FS
42	1		*FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
43	1		*FRONT NUMBER PLATE	Not Necessary	180.00 FS	*- FS
44	1		*FRONT FENDER COWLING CLIPS	Cracked	100.00 FS	*10.00 FS

Report was unsubmitted during this print-out.

9/21/21, 9:41 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*FRONT FENDER QUARTER WINDOW SEALANT LH	Not Necessary	120.00 FS	*- FS
46	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
47	1		*FRONT DOOR SIDE MIRROR COVER LH	Cracked	1,500.00 FS	*250.00 FS
48	1		*ROCKER PANEL SIDE SKIRT LH	Cracked	3,500.00 FS	*750.00 FS
49	1		*ROCKER PANEL SIDE SKIRT CLIPS LH	Necessary	100.00 FS	*30.00 FS
50	1		*FRONT DOOR WINDOW STICKER LH	Cut	300.00 FS	*100.00 FS
51	1		*FRONT DOOR VISOR LH	Not Necessary	500.00 FS	*- FS
52	1		*FRONT TYRE LH (\$150.00) (80%)	Cut	800.00 FS	*120.00 FS
53	1		*FRONT RIM LH	Cracked	4,500.00 FS	*700.00 FS
54	1		*BONNET CARBON FIBRE	Cracked	6,000.00 FS	*1,300.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					36,849.90	9,511.70
- List Item Discount on L Items 20.00/20.00% (S\$)					1,399.98	782.34
Total Parts (S\$)					35,449.92	8,729.36
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	2,000.00	700.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,400.00	1,000.00
3	TO RNR FRONT FENDER QUARTER WINDOW	New	250.00	0.00
4	TO CHECK WIRING AND HEADLAMP FOCUS }	New	150.00	30.00
5	TO CHECK WIRING AND FOG LAMP FUNCTION }	New	150.00	0.00
6	TO RNR INNER TRIM AND UPHOLSTERY	New	400.00	0.00
7	TO CHECK WATER LEAK	New	150.00	0.00
8	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
9	TO CHECK WHEEL ALIGNMENT AND ADJUST	New	250.00	80.00
10	TO RNR UNDERCARRIAGE	New	250.00	150.00
11	TO CHECK WHEEL BALANCING	New	250.00	30.00
12	TO RNR FRONT DOOR MECHANISM	New	400.00	60.00
13	TO RNR FRONT DOOR SIDE MIRROR	New	300.00	50.00
14	TO PERFORM RUST PROOFING	New	300.00	30.00
Gross Labour Cost (\$\$)			6,850.00	2,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >