

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21004015/UTF3E2

Date: 15/04/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001484622		
Claimant Vehicle No :	SKX2041L	Insured Vehicle No :	SMS2568L		
Date of Loss:	28/03/2021	Nature of Claim:	TP	Claim No:	255326

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX2041L	Engine No:	1ZRY236311
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053REH104542566
Reg. Date:	30/11/2015 (Man. Year: 2015)	Odometer:	128674 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,934.20	6,447.26	6,486.94	50.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,990.00	5,060.00	1,930.00	27.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,924.20	11,507.26	8,416.94	42.24
Approved Total (Overridden) (S\$)		9,200.00		
Nett Amount (S\$)	19,924.20	9,200.00	10,724.20	53.82

INSPECTION

Date of Assignment:	31/03/2021		
Date Inspected:	30/03/2021	Inspected At:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	14.0 days		

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Apr 2021)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX2041L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented / Buckled	754.30 FL	*754.30 FL
2	1		*BOOT LID LOGO EMBLEM	Necessary	52.20 FL	*52.20 FL
3	1		*BOOT LID COROLLA EMBLEM	Necessary	47.73 FL	*47.73 FL
4	1		*BOOT LID ALTIS EMBLEM	Necessary	47.73 FL	*47.73 FL
5	1		*BOOT LID CHROME MOULDING	Cracked	332.90 FL	*243.70 FL
6	2		*O/S & N/S LICENCE LAMP ASSY	Not Necessary	131.26 FL	*- FL
7	1		*BOOT LID LOCK KEY LESS SENSOR	Not Necessary	119.34 FL	*- FL
8	2		*BOOT LID O/S & N/S REFLECTOR	Cracked	569.20 FL	*569.20 FL
9	1		*BOOT LID LOCK	Bent / Twisted	382.10 FL	*382.10 FL
10	1		*BOOT LID LOCK STRICKER	Twisted	35.80 FL	*35.80 FL
11	1		*BOOT LID O/S & N/S HINGE	N/S Twisted	139.22 FL	*69.61 FL
12	1		*BOOT LID INNER GARNISH	Not Necessary	308.29 FL	*- FL
13	10		*BOOT LID INNER GARNISH CLIPS	Not Necessary	69.60 FL	*- FL
14	1		*BOOT LID REVERSE CAMERA	Serviceable	580.00 FL	*- FL
15	1		*BOOT LID WEATHERSTRIP	Twisted	169.39 FL	*169.39 FL
16	2		*O/S & N/S TAIL LAMP ASSY (WITH GASKET)	Cracked	823.46 FL	*823.46 FL
17	1		*O/S & N/S TAIL LAMP CLIPS STOPPER	N/S Cracked	13.92 FL	*6.96 FL
18	1		*O/S & N/S TAIL LAMP PANEL	N/S Badly Dented	213.60 FL	*106.80 FL
19	1		*REAR BUMPER	Distorted	492.20 FL	*492.20 FL
20	10		*REAR BUMPER CLIPS	Necessary	58.70 FL	*58.70 FL
21	1		*REAR BUMPER REINFORCEMENT	Distorted	361.60 FL	*361.60 FL
22	2		*REAR BUMPER DAMPER	No such part	111.38 FL	*- FL
23	2		*REAR BUMPER O/S & N/S TOP RETAINER	Bent	179.00 FL	*179.00 FL
24	2		*REAR BUMPER O/S & N/S SIDE RETAINER	Bent	208.80 FL	*184.00 FL
25	2		*REAR BUMPER O/S & N/S SIDE BRACKET CLIPS	Necessary	14.40 FL	*14.40 FL
26	2		*REAR BUMPER O/S & N/S REVERSE SENSOR	Shorted	367.96 FL	*319.50 FL
27	2		*REAR BUMPER O/S & N/S SENSOR STOPPER	Not Necessary	25.00 FL	*- FL
28	1		*REAR BUMPER O/S & N/S REFLECTOR	N/S Cracked	133.40 FL	*66.70 FL
29	1		*REAR END PANEL	Badly Dented	581.20 FL	*581.20 FL
30	1		*REAR END PANEL TOP GARNISH	Twisted	229.40 FL	*184.20 FL
31	5		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	34.80 FL	*- FL
32	1		*REAR END PANEL LOCK STRICKER GARNISH	Cracked	29.50 FL	*29.50 FL
33	1		*REAR FLOOR BOARD PANEL	Buckled / Cracked	839.80 FL	*818.10 FL
34	1		*REAR FLOOR BOARD COVER	Torn	298.35 FL	*267.00 FL
35	1		*REAR FLOOR BOARD PANEL INSULATOR	Necessary	65.00 FL	*65.00 FL
36	1		*REAR N/S FENDER	Distorted	855.82 FL	*855.82 FL
37	14		*REAR FENDER INNER GARNISH CLIPS	Not Necessary	97.44 FL	*- FL
38	1		*REAR N/S FENDER INNER GARNISH	Deformed / Warped	288.40 FL	*154.00 FL
39	1		*REAR N/S FENDER AIRSCOOP GRILLE	Cracked	95.47 FL	*95.47 FL
40	1		*REAR BUMPER REINFORCEMENT BRACKET (N/S)	Bent	89.50 FL	*89.50 FL
41	1		*REAR N/S FENDER WHEEL GUARD	Distorted	75.58 FL	*75.58 FL
42	5		*REAR N/S FENDER WHEEL GUARD CLIPS	Necessary	34.80 FL	*34.80 FL
43	1		*REAR END PANEL KEY LESS SENSOR	Not Necessary	144.20 FL	*- FL
44	1		*REAR N/S CHASSIS FRAME MEMBER	Repair	1,326.00 FL	*- FL
45	1		*REAR WINDSCREEN GLASS OUTER MOULDING	Necessary	144.85 FL	*81.10 FL
46	1		*REAR WINDSCREEN GLASS INNER DAMPER	Necessary	75.00 FN	*30.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	60.00 FN	*40.00 F
48	1		*FUEL TANK LID PANEL	Repair	89.50 FL	*- FL
49	2		*FUEL TANK LID RIVETS	Not Necessary	71.60 FL	*- FL
50	1		*FUEL TANK LID CABLE HOLDER (WITH CAP)	Not Necessary	14.93 FL	*- FL
51	1		*FUEL TANK GROVE COVER GARNISH	Not Necessary	99.45 FL	*- FL
52	1		*FUEL TANK PIPE	Not Necessary	358.02 FL	*- FL
53	1		*REAR N/S DOOR	Repair	954.72 FL	*- FL
54	1		*SET REAR N/S DOOR FRAME STICKER	Not Necessary	45.74 FL	*- FL
55	1		*REAR N/S DOOR INNER LOCK	Not Necessary	358.02 FL	*- FL
56	1		*REAR N/S DOOR INNER LOCK STRICKER	Not Necessary	49.78 FL	*- FL
57	12		*REAR N/S DOOR INNER TRIM BOARD CLIPS	Not Necessary	83.52 FL	*- FL
58	1		*REAR N/S SHOCK ABSORBER SHAFT	Not Necessary	139.23 FL	*- FL
59	1		*REAR N/S LOWER ARM	Not Necessary	1,591.12 FL	*- FL
60	1		*REAR N/S WHEEL TYRE	Not Necessary	320.00 FL	*- FL
61	1		*FUEL TANK	Not Necessary	775.71 FL	*- FL
62	1		*REAR NUMBER PLATE	Bent	40.00 FS	*40.00 FS
63	1		*SET BODY SEALANT	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	17,198.93	8,526.35
- List Item Discount on L Items 25.00/25.00% (S\$)	4,230.98	2,079.09
- Nett Item Discount on N Items 25.00/0.00% (S\$)	33.75	0.00
Total Parts (S\$)	12,934.20	6,447.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DIAGNOSE & RE-SET ABS SENSOR & FAULT CODE	New	150.00	50.00
2	TO CHECK & ADJUST WHEEL ALIGNMENT & BALANCING	New	150.00	60.00
3	TOWING CHARGE (KING DOLLY) ATTACH BILL	New	120.00	120.00
4	TO REMOVE & REFIX REAR WINDSCREEN GLASS & NECESSARY PARTS	New	150.00	120.00
5	TO REMOVE & REFIX FUEL TANK, HOSE, PIPE & NECESSARY PARTS	New	180.00	80.00
6	TO REMOVE & REFIX REAR CUSHION SEAT, CARPET, FLOOR MAT, GARNISH, FLOOR BOARD COVER, TOOL SET, SPARE TYRE & NECESSARY PARTS	New	150.00	120.00
7	TO REMOVE & REFIX REAR N/S DOOR INNER TRIM BOARD COVER, GLASS, REGULATOR, MOTOR, MOULDING, WEATHERSTRIP, HINGE, INNER LOCK & NECESSARY PARTS INTO NEW DOOR	New	120.00	0.00
8	TO REMOVE & REFIX REAR N/S SHOCK ABSORBER SHAFT, LOWER ARM, WHEEL HUB, ABS SYSTEM, BEARING & NECESSARY PARTS	New	200.00	200.00
9	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	180.00	140.00
10	TO REMOVE & REFIX WIRING SYSTEM, INCLUDING WIRING CHECK UP FOR AFFECTED WIRING SYSTEM	New	60.00	30.00
11	TO JACK, STRAIGHTEN & KNOCKING OUT REAR EXHAUST & TAIL PIPE	New	150.00	60.00
12	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT REAR O/S FENDER, REAR FLOOR BOARD PANEL & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS }	New	2,500.00	2,480.00
13	TO JACK, STRAIGHTEN & KNOCKING OUT REAR N/S CHASSIS FRAME }	New	380.00	0.00
14	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	2,500.00	1,600.00
Gross Labour Cost (\$\$)			6,990.00	5,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >