



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 8900H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	DEFORMED	1,897.30	1,510.00
1	FRONT BUMPER SPONGE (CONSISTENT)	CRACKED	379.10	185.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	983.40	-
1	FRONT BUMPER NOZZLE RH (CONSISTENT)	NOT NECESSARY	242.50	-
1	FRONT BUMPER NOZZLE COVER RH (CONSISTENT)	NOT NECESSARY	174.00	-
1	FRONT BUMPER NOZZLE BRACKET RH (CONSISTENT)	NOT NECESSARY	158.00	-
1	FRONT BUMPER TOWING CAP RH (CONSISTENT)	NOT NECESSARY	126.00	-
3	FRONT BUMPER SENSOR RH (CONSISTENT)	DAMAGED (1 PCS ONLY)	1,455.00	250.00
1	FRONT BUMPER GRILLE (CONSISTENT)	NOT NECESSARY	183.00	-
1	FRONT BUMPER FOG LAMP RH (CONSISTENT)	NOT NECESSARY	684.00	-
1	FRONT BUMPER FOG LAMP GARNISH RH (CONSISTENT)	DEFORMED	289.30	135.00
1	FRONT BUMPER BRACKET RH (CONSISTENT)	NOT NECESSARY	140.00	-
10	FRONT BUMPER CLIP (CONSISTENT)	NECESSARY	50.00	50.00
1	FRONT FOG LAMP COVER (CONSISTENT)	REPEATED	288.00	-
2	HEADLAMP ASSY LH (CONSISTENT)	CUT	2,348.00	2,348.00
1	HEADLAMP PANEL LH (CONSISTENT)	NOT NECESSARY	189.00	-
1	FRONT SUPPORT PANEL (CONSISTENT)	NOT NECESSARY	372.00	-
2	REVERSE SENSOR (CONSISTENT)	REPEATED	560.00	-
1	FRONT LOWER LAP (CONSISTENT)	CUT	864.00	864.00
	LESS 10% DISCOUNT		-	-534.20
			11,382.60	4,807.80
<u>LABOUR</u>				
	TO R&R ACCIDENT DAMAGE PARTS ,TO CUT/WELD,KNOCK AND REALIGN ACCIDENT AFFECTED AREA.		1,200.00	400.00
	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA .		1,200.00	200.00
	TO RUST PROOF ACCIDENT AFFECTED AREA .	NOT NECESSARY	120.00	-
	TO R&R REVERSE SENSOR ,RESET AND TEST FUNCTION.		200.00	50.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO CHECK WIRING LAYOUT, PARKING SENSOR AND RESET HEADLAMP SYSTEM.		800.00	30.00
			3,520.00	680.00
GRAND TOTAL			14,902.60	5,487.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,300.00

Report Ref No. CC4/ASM21004042/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.