

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	NTUC INCOME INSURANCE CO-OPERATIVE LTD			CS/INC21004048/Utf3n2	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE	Date:	13/04/2021	
	ATTN: CHARLOTT	E CHEW	Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMQ 4904Y	Veh. Inspected	SCK 2282X	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1126052-002	Excess (\$)	0.00	
	Assign From	ANNIE KOH	Assign Date	30/03/2021	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA STREAM (A)	c.c	1799	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	RN61073874	Colour	BLACK	
	Odometer	165636 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/45 ZR17	MICHELIN	6 mm	
	L/H Front Tyre	225/45 ZR17	MICHELIN	6 mm	
	R/H Rear Tyre	225/45 ZR17	MICHELIN	6 mm	
	L/H Rear Tyre	225/45 ZR17	MICHELIN	6 mm	
4.	1. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
_					
5.	General Information				
	Accident Date	29/03/2021	Inspect Date / Time	30/03/2021 (11:39 AM)	
	Survey held at				
_	Repairer ZOOM AUTOWERKS PTE LTD				
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	STIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
	•				