

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/INC 2100.4048/4tf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SCK 2282X

at Workshop m/s

Zoom

of

Insured:

SMA 4904Y

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

\$18k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

we ant. 07-08-2023 LTA \$8240

6/4/21

L/S \$3100 confirmed with Elin
(Red: 10,145.00 : 76%)

Veh No:

SCK 2282X

Yr Regn:

8/8/08

Type:

M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

Herbo steam

c.c

1799

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

165 636

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

RN 61073874

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

Inorder / Jammed / Leaked / Burnt or

Brake:

Inorder / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/452217

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

29/3/21

D.O.I.

30/3/21

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

TP

Lump Sum / I.B.I. (\$

3100

** Submit to insurance*



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: SCK2282X

Model: Honda Stream

Damaged Area: (Rear Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

2/5 @ 3100

*Not Authorized
LPR
30/3/21
When the After Repair
4 days.*

Parts / Material :

1	Rear Bumper body kit	waged/cne		\$	725.30	✓
2	Rear Bumper Side Retainer @ 49.40	11		\$	98.80	X
3	Rear Bumper Tow Garnish	NZ		\$	34.70	X
4	Rear Bumper Clips	neu	39.00	\$	60.00	✓
5	Rear End Panel Top Garnish	11		\$	195.60	X
6	Rear End Panel	R		\$	545.90	X
7	Rear End Panel top Garnish Clips	11		\$	60.00	X
8	Rear Tailgate	DO / sent	908.20	\$	1,171.30	✓
9	Rear Tailgate Inner Trimboard	de/cne	261.20	\$	281.60	✓
10	Rear Tailgate Inner Trimboard Clips	neu	39.00	\$	60.00	✓
11	Rear Tailgate Inner Lock	8u		\$	245.90	X
12	Rear Tailgate Inner Handle	11		\$	68.40	X
13	Rear Tailgate Centre Garnish	11		\$	361.20	X
14	Rear Tailgate Emblem (Stream)	neu	42.50	\$	72.40	✓
15	Rear Tailgate Logo	11		\$	98.40	X
16	Rear Tailgate Damper @ 195.20	11		\$	390.40	X
17	Rear Tailgate Weather Strip	1w1	188.20	\$	214.50	✓
18	Rear Taillamps @ 725.40	0/5 cne	368.50	\$	1,450.80	12C
19	Rear Taillamps clips	11		\$	32.00	X
20	Rear Fender Inner Trimboard @ 770.40	11		\$	1,540.80	X
21	Rear Fender Inner Trimboard Clips	11		\$	60.00	X
1 set	22 Reverse Sensor Original	shredded		\$	380.00	220 S.N
23	Reverse Sensor Holder	11		\$	160.00	X
24	Rear Floor Panel Top Tray	11		\$	245.70	X
25	Rear Floor Panel	11		\$	1,451.60	X
26	Rear Spare Tyre Holder	11		\$	425.80	X
27	Rear Exhaust Chrome Muffler	11		\$	120.00	X
28	Rear Exhaust End Pipe	11		\$	785.00	X
29	Rear Exhaust Mounting @ 54.20	11		\$	108.40	X

Parts \$ 11,444.50
Less 20% \$ 2,288.90
Total Parts \$ 9,155.60

Special Net Item :

1	Rear Tailgate Glass Inner Seal	neu	\$	75.00	30
2	Rear Tailgate Glass Sealant	neu	\$	80.00	40
3	Rear Number Plate	11	\$	55.00	X

Total S/N Parts : \$ 210.00

Total Labour :

To Remove, Repair & Renew affected Rear Accident Areas	\$	1,400.00	580
To Putty, Spray Paint on affected Rear Accident Areas	\$	1,400.00	650
To Check & Re-Connect all electrical wiring	\$	50.00	20
To Remove & Install Rear Tailgate Glass	\$	150.00	120
To Remove & Refit Rear Tailgate Component to Assist Repairs	\$	100.00	60
To Remove & Install Rear Booth id Compartment Trims to Assist Repairs	\$	100.00	60
To Remove & Re-position Rear Exhaust Pipe	\$	150.00	X
To Conduct Rear Water Seepage Test	\$	100.00	X
To Remove & Re-position Reverse Sensor	\$	80.00	50
To Re-Programme & Reset Diagnostic	\$	250.00	X
To Rust Proof Affected Areas	\$	100.00	30
Total Labour :	\$	3,880.00	

TOTAL PARTS :	\$9,155.60
TOTAL SPECIAL NET ITEMS :	\$210.00
TOTAL LABOUR :	\$3,880.00
TOTAL REPAIR COST:	\$13,245.60

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2571-90
202
P-2057-52
S/N-270-00
1-1570-00
3897.52
202
3118.