

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT CS3/SMO21004056/Uvf3e2 SOMPO INSURANCE SINGAPORE PL Ref: 50 RAFFLES PLACE #03-03 Date: 12/04/2021 SINGAPORE LAND TOWERSINGAPORE 048623 Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. GBJ 6818S **GBE 3920A** Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. CMTD2100932/MYE Excess (\$) 0.00 **GRACE TEO Assign Date** 30/03/2021 Assign From **Vehicle Particulars & Condition** 2. TOYOTA HIACE (M) Make & Model 2982 C.C 2019 HIDDEN Engine No. Year of Reg. JTFHT02P000249250 SILVER Chassis No. Colour Odometer 35234 KM Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195 R15 BRIDGESTONE 7 mm L/H Front Tyre 195 R15 BRIDGESTONE 7 mm 195 R15 BRIDGESTONE R/H Rear Tyre 7 mm BRIDGESTONE 7 mm L/H Rear Tyre 195 R15 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. 5. **General Information** 24/03/2021 07/04/2021 ( 12:42 PM ) Inspect Date / Time Accident Date **UE MOTOR** Survey held at BLK 3006 UBI ROAD 1 #01-334 SINGAPORE 408700 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000

Report Ref No. CS3/SMO21004056/Uvf3e2

**Estimate Days of Repair** 

Inspected By

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

5b.

CHUA KANG SENG Licensed Appraiser K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

4 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser