

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004059/KRA3Q2
Date: 19/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100509968
Claimant Vehicle No :	SMP2428Z	Insured Vehicle No :	SLP4588T
Date of Loss:	29/03/2021	Nature of Claim:	TP
		Claim No:	0862810189SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP2428Z		
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Engine No:	2ZR0E58607
Reg. Date:	18/09/2019 (Man. Year: 2019)	Chassis No:	JTDZS3EU40J048044
Colour:	Metallic White	Odometer:	201438 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/50 R15	Rear Tyre Size:	205/50 R15
Front Left Side:	Firenza 9 mm	Rear Left Side:	West Lake 8 mm
Front Right Side:	Firenza 9 mm	Rear Right Side:	West Lake 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,567.37	2,501.10	1,066.27	29.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,060.00	780.00	280.00	26.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,627.37	3,281.10	1,346.27	29.09
+ GST 7.00/7.00% (S\$)	323.92	229.68	94.24	29.09

Nett Amount (S\$)	4,951.29	3,510.78	1,440.51	29.09
+ Car Rental (5.0 x S\$104.00/day) (S\$)		520.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,032.78		

INSPECTION

Date of Assignment: 30/03/2021

Date Inspected: 31/03/2021

Estimated Period of Repair: 4.0 days

Inspected At: City Auto Pte Ltd (HQ)
160 Sin Ming Drive #05-01,, Sin Ming AutoCity,
Singapore 575722

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	556.40 FL	*556.40 FL
2	2		*FRONT BUMPER RETAINER	Distorted (1 PCS ONLY)	136.40 FL	*68.20 FL
3	1		*FRONT BUMPER AIR DUCT -RH	Dented	129.10 FL	*129.10 FL
4	1		*FRONT BUMPER SPONGE	Serviceable	79.60 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	656.90 FL	*- FL
6	1		*RH HEADLAMP	Mtg Cracked	2,526.40 FL	*2,526.40 FL
7	1		*RH LED LAMP	Serviceable	617.00 FL	*- FL
8	1		*EMBLEM -HYBRID	Necessary	54.70 FL	*54.70 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,756.50	3,334.80
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,189.13	833.70
Total Parts (\$\$)	3,567.37	2,501.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING AND LIGHTING	New	60.00	20.00
2	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ACCIDENT PARTS	New	500.00	360.00
3	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	500.00	400.00
Gross Labour Cost (\$\$)			1,060.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >