

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG21004060/EQF3E2

Date: 30/04/2021

REFERENCE

Insured/Claimant: HAGLEY NIGEL TAK-LING Policy No: 2100506485
Date of Loss: 29/03/2021 Nature of Claim: OD Claim No: 7354967347SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM8806D**
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGGH667636
Reg. Date: 17/04/2017 (Man. Year: 2016) Chassis No: KNAFX411MH5696968
Colour: Grey Odometer: 85314 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$59,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Roadstone 4 mm Rear Left Side: Roadstone 4 mm
Front Right Side: Roadstone 4 mm Rear Right Side: Roadstone 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,650.00	5,796.00	2,854.00	32.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,540.00	4,710.00	830.00	14.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,190.00	10,506.00	3,684.00	25.96
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	13,890.00	10,206.00	3,684.00	26.52
+ GST 7.00/7.00% (S\$)	972.30	714.42	257.88	26.52
Nett Amount (S\$)	14,862.30	10,920.42	3,941.88	26.52

INSPECTION

Date of Assignment: 30/03/2021
Date Inspected: 30/03/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 11.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
3	1		*RESERVOIR & PUMP ASSY-WASHER	Broken	125.00 FL	*125.00 FL
4	1		*LAMP ASSY-HEAD, RH	Broken	1,707.00 FL	*1,707.00 FL
5	1		*HINGE ASSY-HOOD, RH	Not Necessary	34.00 FL	*- FL
6	1		*HINGE ASSY-HOOD, LH	Not Necessary	34.00 FL	*- FL
7	1		*PANEL ASSY-HOOD	Dented	1,384.00 FL	*1,384.00 FL
8	1		*PAD-HOOD INSULATING	Not Necessary	141.00 FL	*- FL
9	1		*ROD ASSY-HOOD STAY	Not Necessary	35.00 FL	*- FL
10	1		*LATCH ASSY-HOOD	Not Necessary	65.00 FL	*- FL
11	1		*INSULATOR-FENDER RH	Not Necessary	28.00 FL	*- FL
12	1		*PANEL-FENDER, RH	Dented	435.00 FL	*435.00 FL
13	1		*BRACKET-FR BUMPER SIDE MTG, LH	Not Necessary	13.00 FL	*- FL
14	1		*BRACKET-FR BUMPER SIDE MTG, RH	Broken	13.00 FL	*13.00 FL
15	1		*RAIL ASSY-FR BUMPER	Not Necessary	496.00 FL	*- FL
16	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
17	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	84.00 FL	*- FL
18	1		*MOULDING-FRONT BUMPER A/INTAKE	Not Necessary	91.00 FL	*- FL
19	1		*STRIP ASSY-FR BUMPER UPR	Not Necessary	29.00 FL	*- FL
20	1		*GARNISH-RADIATOR GRILLE, UPR	Not Necessary	54.00 FL	*- FL
21	1		*GRILLE ASSY-RADIATOR	Not Necessary	328.00 FL	*- FL
22	2		*RETAINER-BUMPER SIDE MTG	Not Necessary	2.00 FL	*- FL
23	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
24	1		*LIP ASSY-FRONT BUMPER	Not Necessary	55.00 FL	*- FL
25	1		*DUCT ASSY-AIR CURTAIN, RH	Broken	6.00 FL	*6.00 FL
26	1		*AIR DUCT-FR BUMPER, RH	Missing	33.00 FL	*33.00 FL
27	1		*LAMP ASSY-FRONT FOG, RH	Not Necessary	241.00 FL	*- FL
28	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
29	1		*ARM COMPLETE-FR LWR, RH	Bent	380.00 FL	*380.00 FL
30	1		*STAY RH	Not Necessary	23.00 FL	*- FL
31	1		*CROSSMEMBER COMPL	Bent	1,330.00 FL	*1,330.00 FL
32	1		*STRUT ASSY-FR, RH	Bent	280.00 FL	*280.00 FL
33	1		*BEARING-STRUT	Not Necessary	54.00 FL	*- FL
34	1		*PAD-FRONT SPRING, UPR	Not Necessary	42.00 FL	*- FL
35	1		*INSULATOR ASSY-STRUT	Not Necessary	93.00 FL	*- FL
36	1		*LINK-STABILIZER	Bent	72.00 FL	*72.00 FL
37	1		*GEAR ASSY-STEERING	Not Necessary	832.00 FL	*- FL
38	1		*HUB ASSY-FR WHEEL	Not Necessary	150.00 FL	*- FL
39	1		*BEARING-FRONT WHEEL HUB	Not Necessary	131.00 FL	*- FL
40	1		*RING-SNAP	Not Necessary	11.00 FL	*- FL
41	1		*KNUCKLE-FRONT AXLE, RH	Not Necessary	350.00 FL	*- FL
42	1		*GUARD ASSY-FRONT WHEEL, RH (Supplementary)	Broken	95.00 FL	*95.00 FL
43	10		*CLIP (Supplementary)	Necessary	20.00 FL	*20.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,800.00	7,240.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,150.00	1,444.00
Total Parts (\$\$)	8,650.00	5,796.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PART ON FRONT SUPPORT PANEL, FRONT BONNET, RH FRONT FENDER, REPAIR RH FRONT DOOR, REPAIR LH FRONT FENDER	New	2,000.00	1,600.00
2	REMOVE & INSTALL RADIATOR AND A/CON CONDENSER	New	100.00	100.00
3	TOP UP A/CON GAS AND CHECK A/CON SYSTEM	New	80.00	80.00
4	PAINT WORK SPRAY FRONT BONNET, FRONT BUMPER, RH FRONT FENDER, RH FRONT DOOR, LH FRONT FENDER AND AFFECTED PORTION	New	2,100.00	1,750.00
5	APPLY BODY SEALANT	New	80.00	40.00
6	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	PERFORM RUST PREVENTION	New	80.00	40.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	REPLACE FRT U/CARRIAGE DAMAGES	New	400.00	400.00
10	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
11	SUPPLY RH FRONT SPORT RIM SSW266	New	400.00	400.00
12	LABOUR RENEW RH FRONT SPORT RIM INCLUDING BALANCING	New	30.00	30.00
Gross Labour Cost (\$\$)			5,540.00	4,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >