

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/GRB21002215/NVF3E2-1

**Date:** 29/04/2021

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447  
**Claimant Vehicle No :** SCW8880S **Insured Vehicle No :** SLS9851J  
Date of Loss: 04/02/2021 Nature of Claim: TP Claim No: MFL2021D0000572

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCW8880S**  
Make & Model: HONDA STREAM, 1.8 L (A) Engine No: R18A12803620  
Reg. Date: 02/06/2008 (Man. Year: 2008) Chassis No: JHMRN68408S203633  
Colour: Blue Odometer: 161606 km  
Engine Capacity: 1799 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/65 R15 Rear Tyre Size: 205/65 R15  
Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 4 mm  
Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 4 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,802.64	4,302.16	2,500.48	36.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,000.00	2,740.00	2,260.00	45.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,802.64</b>	<b>7,042.16</b>	<b>4,760.48</b>	<b>40.33</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,650.00</b>		
<b>Nett Amount (S\$)</b>	<b>11,802.64</b>	<b>5,650.00</b>	<b>6,152.64</b>	<b>52.13</b>

### INSPECTION

Date of Assignment: 30/03/2021  
Date Inspected: 17/02/2021 Inspected At: 3 Motorwerkz Concepts Pte Ltd (HQ)  
25 Kaki Bukit Road 4, Synergy @ KB #01-40  
Singapore 417800  
Estimated Period of Repair: 8.0 days

**Adjuster:** Muhammad Nazril Bin Abdullah

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Apr 2021)
<b>Parts:</b>	M1-MPV	HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SCW8880S)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT GRILLE MOULDING	Serviceable	264.50 FL	*- FL
2	1		*FRT GRILLE BASE	Cracked	230.40 FL	*230.40 FL
3	2		*HEADLAMP R/L	Serviceable	1,395.00 FL	*- FL
4	1		*FRT BUMPER	Deformed	655.60 FL	*655.60 FL
5	6		*FRT BUMPER CLIP	Necessary	21.00 FL	*21.00 FL
6	2		*FRT BUMPER RETAINER R/L	Serviceable	55.00 FL	*- FL
7	1		*FRT BUMPER REINFORCEMENT	Dented	248.80 FL	*248.80 FL
8	1		*TAILGATE	Dented	903.20 FL	*903.20 FL
9	1		*RR WINDSCREEN MOULDING (TOP)	Necessary	23.80 FL	*23.80 FL
10	1		*RR WINDSCREEN MOULDING (BOTTOM)	Necessary	24.30 FL	*24.30 FL
11	1		*TAILGATE WIPER MOTOR	Serviceable	282.80 FL	*- FL
12	1		*TAILGATE NO. PLATE GARNISH	Deformed	300.60 FL	*300.60 FL
13	2		*TAILGATE NO. PLATE LAMP R/L	Serviceable	88.40 FL	*- FL
14	1		*TAILGATE EMBLEM (H)	Necessary	29.90 FL	*29.90 FL
15	1		*TAILGATE EMBLEM (STREAM)	Necessary	31.60 FL	*31.60 FL
16	1		*TAILGATE INNER TRIM GARNISH	Cracked	271.50 FL	*271.50 FL
17	8		*TAILGATE INNER TRIM GARNISH CLIP	Necessary	25.60 FL	*25.60 FL
18	1		*TAILGATE WEATHERSTRIP	Torn	121.60 FL	*121.60 FL
19	1		*TAILGATE LOCK	Dented	277.50 FL	*277.50 FL
20	1		*TAILLAMP LH	Broken	382.50 FL	*382.50 FL
21	1		*RR BUMPER	Deformed	688.90 FL	*688.90 FL
22	1		*RR BUMPER TOW COVER	Deformed	43.70 FL	*43.70 FL
23	6		*RR BUMPER CLIP	Necessary	21.00 FL	*21.00 FL
24	2		*RR BUMPER RETAINER R/L	Deformed	58.80 FL	*58.80 FL
25	1		*RR END PANEL	Dented	406.70 FL	*406.70 FL
26	1		*RR END PANEL GARNISH ASSY	Dented	222.90 FL	*222.90 FL
27	4		*RR END PANEL GARNISH CLIP	Necessary	12.80 FL	*12.80 FL
28	2		*RR COMPARTMENT COVER R/L	Serviceable	358.40 FL	*- FL
29	1		*RR FLOOR PANEL	Repair	619.00 FL	*- FL
30	1		*FRT SUPPORT PANEL (NPA)	Repair	0.00 FL	*- FL
31	2		*RR FENDER R/L (NPA)	Repair	0.00 FL	*- FL
32	2		*RR CHASSIS MEMBER R/L (NPA)	Repair	0.00 FL	*- FL
33	1		*RR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
34	1		*RR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*20.00 FS
35	1		*RR END PANEL SEALANT	Necessary	50.00 FS	*40.00 FS
36	1		*SET REVERSE SENSOR	Dented	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,415.80</b>	<b>5,302.70</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	1,613.16	1,000.54
<b>Total Parts (\$\$)</b>	<b>6,802.64</b>	<b>4,302.16</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK FRONT ELECTRICAL SYSTEM AND CALIBRATE / FOCUS HEADLAMP	New	30.00	20.00
2	TO STRAIGHTEN, REPAIR, REALIGN ON FRONT AFFECTED AREA AND REPLACE DAMAGED PARTS	New	600.00	200.00
3	TO SPRAY PAINTING, BLENDING ON FRONT AFFECTED AND ADJACENT AREA	New	600.00	300.00
4	TO REMOVE AND REINSTALL REAR ELECTRICAL WIRING SYSTEM FOR NECESSARY REPAIRS. TO CHECK REAR ELECTRICAL WIRING SYSTEM	New	60.00	40.00
5	TO TRANSFER TAILGATE COMPONENT PARTS TO NEW TAILGATE	New	100.00	80.00
6	TO TRANSFER REAR WINDSCREEN TO NEW TAILGATE	New	120.00	120.00
7	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS, GARNISHES, ETC. FOR NECESSARY REPAIRS	New	150.00	100.00
8	TO REMOVE, REPLACE AND REINSTALL REAR REVERSE SENSORS & CONTROL UNIT	New	50.00	30.00
9	TO STRAIGHTEN, REPAIR, REALIGN ON REAR AFFECTED AREA AND REPLACE DAMAGED PARTS	New	1,600.00	800.00
10	TO SPRAY PAINTING, BLENDING ON REAR AFFECTED AND ADJACENT AREA	New	1,600.00	1,000.00
11	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS	New	90.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,000.00</b>	<b>2,740.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >