

PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 888259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SCW8880S

Report No.: PAS/TP/0110221

APPRAISEMENT SCHEDULE

	S/No.	Qty	Parts Descriptions	Condition			Re Est	pairer's timate (S\$)		Our ment (S\$)
	1	l pc	Frt grille moulding	Refit			\$	264.50	\$	- XSVL
	2	•	Frt grille base	Dented/Cracked			\$	230.40	\$	230.40./CRX
	3	•	Headlamp R/L	Refit	\$	697.50	\$	1,395.00	\$	- XSVL
	4	•	Frt bumper	Dented/Deformed	•		\$	655.60	\$	655.60 DEF
	5	•	Frt bumper clip	Necessary	\$	3.50	\$	21.00	\$	21.00 /NEC
(6		Frt bumper retainer R/L	Necessary	\$	27.50	\$	55.00	\$	55.00
	7	-	Frt bumper reinforcement	Dented	7	100	\$	248.80	\$	248.80 / DD
	8	1 pc	Tailgate	Dented			\$	903.20	\$	903.20 / DD
	9	l pc	Rr windscreen moulding (top)	Necessary			\$	23.80	\$	23.80 - NEC
	10	1 pc	Rr windscreen moulding (bottom)	Necessary			\$	24.30	\$	24.30 / NEL
	11	l pc	Tailgate wiper motor	Refit			\$	282.80	\$	- XSVL
	12	1 pc	Tailgate no.plate garnish	Loop Cracked			\$	300.60	\$	300.60/DEF
	13	•	Tailgate no.plate lamp R/L	Refit	\$	44.20	\$	88.40	\$	- XSUL
	14	l pc	Tailgate emblem (H)	Necessary	~		\$	29.90	\$	29.90/NEC
	15	l pc	Tailgate emblem (Stream)	Necessary			\$	31.60	\$	31.60 - NEC
	16	l pc	Tailgate inner trim garnish	Loop Cracked			\$	271.50	\$	271.50 CRX
	17		Tailgate inner trim garnish clip	Necessary	\$	3.20	\$	25.60	\$	25.60 /NEC
	18	1 pc	Tailgate weatherstrip	Tom/Necessary			\$	121.60	\$	121.60 /TN
	19	l pc	Tailgate lock	Dented/Damaged			\$	277.50	\$	277.50
	20	1 pc	Taillamp LH	Broken			\$	382.50	\$	382.50 / BR
	21	l pc	Rr bumper	Dented			\$	688.90	\$	688.90 / DEF
	22	•	Rr bumper tow cover	Dented/Cracked			\$	43.70	\$	43.70 / DEF
	23		Rr bumper clip	Necessary	\$	3.50	\$	21.00	\$	21.00/NEC
	24	•	Rr bumper retainer R/L	Cracked/Necessary	\$	29.40	\$	58.80	\$	58.80 DEC
	25	•	Rr end panel	Dented/Distorted			\$	406.70	\$	406.70 / DD
	26	•	Rr end panel garnish assy	Dented/Deformed			\$	222.90	\$	222.90
	27	-	Rr end panel garnish clip	Necessary	\$	3.20	\$	12.80	\$	12.80/NEC
	28	-	Rr compartment cover R/L	Serviceable	\$	179.20	\$	358.40	\$	- XSVL
	29		Rr floor panel	Dented/Distorted			\$	619.00	\$	619.00 ?
log	30	-	Frt support panel	Dented/Repair				(Re	fer labour	no. 2 & 3) K
	31		Rr fender R/L	Dented/Repair				-		7,9 & 10) 4
	32	•	Rr chassis member R/L	Dented/Repair				(Refer	labour no.	7,9 & 10) (
							\$	8,065.80	\$	-/
						Discount: 20%	\$	1,613.16	20% \$	1,135.34
				List Parts Sub-Total:		ub-Total:	\$	6,452.64	\$	4,541.36 4,002.16
	1	l pc	Rr windscreen sealant	Necessary		S/N	\$	50.00	\$	40.00 NEC
	2	-	Rr windscreen inner seal	Necessary		S/N	\$	50.00	\$	20.00 ∕ √€ €
	3	-	Rr end panel sealant	Necessary		S/N	\$	50.00	\$	40.00 /N Fac
	4		Reverse sensor	Dented		S/N	\$	200.00	\$	200.00
				Special Nett Sub-Total:			-\$		\$	300.00
		Special Nett Suo-1 otal :						350.00	\$	300.00

Parts Total:

6,802.64

\$ 4,841.36 \$ 4,302.16



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers
Correspondence Mail Address: My Mail Box 886259 Singapore 919191.
Mobile: 9295 2204 Fax: 6722 8508 Email: pasves@hotmail.com

Business Reg. 201404434D

Vehicle No : SCW8880S	Falk Supplement to the Control of th	Report No. : PAS/TP/0110221				
S/No. Labour Descriptions	1 A 1 A 1 A 1 A 1 A 1 A 1 A 1 A 1 A 1 A	Repairer's Estimate (SS	THE RESERVE OF THE PARTY OF THE	Our ment (S\$)		
1. To shook forms destrict out on the U.S. 166 1 11						
1 To check front electrical system and calibrate/focus headlamp.		\$ 30.00) \$	20.00		
2 To straighten, repair, realign on front affected area and replace damag	ed parts.	\$ 600.00	\$	300.00 20		
3 To spray painting, blending on front affected and adjacent area.		\$ 600.00) \$	400.00 /		
4 To remove and reinstall rear electrical wiring system for necessary rep				1		
To check rear electrical wiring system.		\$ 60.00) \$	50.00		
5 To transfer tailgate component parts to new tailgate.	:	\$ 100.00	\$	80.00 -		
6 To transfer rear windscreen to new tailgate.	;	\$ 120.00	\$	120.00		
7 To remove and reinstall rear interior trims, garnishes, etc. for necessar	y repairs.	\$ 150.00	\$	120.00		
8 To remove, replace and reinstall rear reverse sensors & control unit.	9	\$ 50.00	\$	50.00 3		
9 To straighten, repair, realign on rear affected area and replace damage	d parts.	1,600.00	\$	1,320.00		
10 To spray painting, blending on rear affected and adjacent area.	9	\$ 1,600.00	\$	1,200.00		
11 To spray anti-rust coating on new and affected panels.		\$ 90.00	\$	60.00		
La	bour Total:	\$ 5,000.00	<u></u>			
			4	3,440		
Total (Parts	& Labour) :	\$ 11,802.64	\$	8,561.36		
			4	7,742.16		

For Lump Sum Repairs

Under normal circumstances, the repairs should be completed within a reasonable period

of Working Days. (Exclude waiting days of PRI, Sunday, Pubic Holiday and awaiting of shipment for spare parts)

76 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall has the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.